

110c Annual Report

(DRMS Office Use Only)	Permit Number:	M-1988-087
	Permittee Name:	Southway Construction Company, Inc.
	Operation Name:	Swede Corners Pit
	County:	Saguache
	Anniversary Date:	January 13, 2017
	Current Bond Amt:	\$11,270.00
	Annual Fee Due:	\$323.00
	Permit Acreage:	9.90
	DRMS Specialist	SJM

According to C.R.S. 34-32.5-116 or 34-32-116, each year, on the anniversary date of the permit, an operator shall submit the Annual Fee, an Annual Report and Map showing the extent of current disturbances to affected land, required monitoring information, reclamation accomplished to date and during the preceding year, any new disturbance that is anticipated to occur during the upcoming year, any reclamation that will be performed during the upcoming year, the dates for the beginning of active operations, and the date active operations ceased for the year.

Information contained in this report will be reviewed by the Division upon receipt and prior to the next compliance inspection of the site. If, while completing this report, you learn that your site is not in compliance with the rules and the act, it is advisable that the issues be rectified promptly to avoid possible enforcement action.

1. Is the site identification sign posted in accordance with Rule 3.1.12(1)? YES ☒ NO ☐
2. Is the affected area boundary clearly marked in accordance with Rule 3.1.12(2)? YES ☒ NO ☐
3. Is the mine site in final reclamation (all material extraction and stockpile removal is complete)?
If "YES," please note time limits related to completion of reclamation, Rule 3.1.3. YES ☒ NO ☐
4. What was the date of last excavation, processing or hauling activity at the mine? 2005
5. Does the mine operate more than 180 days per year?
If "NO", please review Rule 1.13 to assure that your mine is in compliance. YES ☐ NO ☒
6. Has this mine been granted: YES ☐ NO ☒
 a) approval of TEMPORARY CESSATION Status?
 b) approval for INTERMITTENT OPERATION? YES ☐ NO ☒
7. Number of acres currently affected (mining + incomplete and or unreleased reclamation): 9.90
8. Number of acres that were newly affected during the current report year: NA
9. Number of acres that were reclaimed during the current report year: 0
10. Estimated new acreage to be affected in the next report year: NA
11. Estimated acres to be reclaimed in the next report year: 0

Division records indicate the following permittee/landowner contact information (blank fields indicate that we do not have information on record). If this information is blank or not current, please type or print **current** contact information:

Permittee Contact:	Ralph Martinez	
Permittee Company:	Southway Construction Company, Inc.	
Address:	117 White Pine Dr Alamosa, CO 81101	
Phone Number:	(719) 589-5103	
Fax Number:	(719) 589-5522	
Email Address:	SAFETY@Southwayco.com	
Permitting Contact:	Izora Southway	Ralph Martinez
Company:	Southway Construction Company, Inc.	
Address:	117 White Pine Dr Alamosa, CO 81101	
Phone Number:	(719) 589-5103	
Fax Number:	719-589-5103	
Email Address:	Safety@SouthwayCo.com	
Inspection Contact:	Izora Southway	Ralph Martinez
Company:	Southway Construction Company, Inc.	
Address:	117 White Pine Dr Alamosa, CO 81101	
Phone Number:	(719) 589-5103	
Fax Number:	(719) 589-5522	
Email Address:		Safety@SouthwayCo.com

I, the undersigned, hereby state that the information provided in this report is true and accurate, and that site operations are being conducted in accordance with the Division approved mining and reclamation plans.


 Signature of Permittee, Corporate Officer, Owner, or Documented Designee

12-26-12
 Date