



COLORADO

Division of Reclamation,
Mining and Safety

Department of Natural Resources

1313 Sherman Street, Room 215
Denver, CO 80203

January 29, 2018

Miranda Kawcak
Peabody Energy, LLC
29515 Routt County Road #27
Oak Creek, CO 84607

RE: **Hayden Gulch Terminal, LLC, Hayden Gulch Loadout, Permit C-1992-081
Third Quarter 2017 Discharge Monitoring Report (COG- 850008)**

Dear Ms. Kawcak:

The Colorado Division of Reclamation, Mining, and Safety (CDRMS) has reviewed and found the above referenced report to be in compliance with Rule 4.05.13(2). The Third Quarter 2017 Discharge Monitoring Report for the above referenced CDPS Permit was received by the Division on 24 January 2018 via email; the reports cover the time period from 01 July 2017 through 30 September 2017.

During the third quarter of 2017 no outfalls discharged.

If you have any questions feel free to contact me. (303) 866-3567 ext 8134

Sincerely,

Jason Musick
Environmental Protection Specialist
Jason.musick@state.co.us

