


Estimated St Vrain Breaches and flow during 2013 flood

- 1 Plant Site – 5 acres
Waiting on Boulder County review before we can prepare site to begin mining again.
- 2 Sediment deposited by St. Vrain Creek from Breach 1 - 4.5 acres*
- 3 Sediment deposited by St. Vrain Creek from Breach 2 - 10.5 acres*
- 4 Sediment deposited by St. Vrain Creek from Breach 2. Boulder County Parks and Open Space working with FEMA to reestablish water storage reservoir and remove sediment - 10 acres

*MM intends to re-mine to re-establish prior reclamation, Boulder County would like for it to remain as-is. Discussions will continue thru 2018.

	
Lyons Pit	
2018 DRMS Annual Report	
Not to scale	02-14-18