

Notes:

7. Mining was done by December 1, 2016. The dark green area (5.32 acres) is undisturbed area along the river. Side sloping and final grading is completed on the reservoir slopes.

9. The areas above the reservoir water elevation around the reservoir area were seeded in the fall of 2015. The grass is growing as expected.

11. Final grading of the reservoir floor was completed in 2017. Much of the mine area is lake bottom and needs little or no reclamation. Final 3:1 slopes into the reservoir area are complete.

14. There are no topsoil piles on the site they have been used for reclamation.

16. A copy of the SEO's slurry wall certification letter is on file with the division. The water exposed in the reservoir is owned by AFS.

20. The monitoring results are attached from September 2008 thru February 16, 2018. This report contains ground water depth information collected monthly by AFS for monitoring wells 1, 2, 3, 4, 7 & 8 starting in first quarter 2013 as requested by Division. Monitoring wells are north and east of the mined area. The ground water levels have been stable and are back to the levels when we took the permit over. Therefore we believe that the activities we have done, have minimized the impact to the hydrological balance on the mine site.