# **Minerals Reclamation Permit Annual Report**



# **Disclaimer**

Under the terms of your NOI or Reclamation Permit and Colorado Statutes, you must submit Annual Fees and Annual Reports (including a map). You must pay the Annual Fee and submit an Annual Report each year until reclamation responsibility release is granted. The Annual Fee is not a renewal fee. The Fee and Report are for LAST YEAR'S mining and reclamation season, and MUST be paid even if your operation was inactive.

If you have requested reclamation responsibility release from the Division of Reclamation, Mining and Safety ("Division") but your permit is not released by the anniversary date listed below, the Annual Fee MUST be paid. If the permit is released before the anniversary date, then by Statute, it is not necessary to pay an Annual Fee or submit an Annual Report for that year.

Division records indicate the following is due:

#### Select Permit Number \*

Only Permit Numbers with currently due Annual Fees will be listed. If the Permit Number is not listed, then the Annual Fees are not due, the Permit Number has already been submitted, or the Permit Number Annual Fee payment has been processed.

M1977365

### Select Anniversary Date \*

04-01-2018

#### PLEASE REMEMBER TO CLICK "SUBMIT" AFTER YOU HAVE COMPLETED YOUR REPORT AND PAYMENT.

Please check the box indicating you have read and understand the terms of the Annual Report and Annual Fee  $^{\mbox{*}}$ 

▼ I understand and agree to the terms

## **General Information**

#### **Permittee Name**

Park County

## **Operation Name**

Sulphur Mtn Grav Pit

Permit Number Fee Due Permit Acreage

M1977365 323.00 4.00

County Anniversary Date Current Bond Amount

Park 04-01-2018 0.00

# **Permittee Contact Information**

## **Permitting Contact Name**

Nicki Griffin

Park County  Address 1 PO Box 147  Address 2  City State Zip Code Fairplay CO 804400000  Phone # Fax # 7198364271 7198364275  Permitting Contact Email Address angulfiling@parkco.us  Is the Permitting Contact information listed above correct? If it is not correct your organization's Administrator will receive an email notification. * 6 Yes C No  Annual Report Questions  Information contained in this report is required and will be reviewed by the Division upon receipt and prior to the next compliance inspection of the size. If, while completing this report, you learn that performance in the next is enabled that the issues be rectified prompty to avord possible enforcement audisted that the issues be rectified prompty to avord possible enforcement active in the rules and the next, is advantable that the issues be rectified prompty to avord possible enforcement active in the rules and the next, is advantable that the issues be rectified prompty to avord possible enforcement active in the rules and the next, is advantable that the issues be rectified prompty to avord possible enforcement active information.  I. Is the site identification sign posted in accordance with Rule 3.1.12(1), * 6 Yes C No  2. Is the affected area boundary clearly marked in accordance with Rule 3.1.12(2), * 6 Yes C No  3. Is the milne site in final reclamation (all material extraction and stockpille removal is complete)? * IT'YES. Please note time limits related to completion of reclamation, Rule 3.1.3. C Yes C No  4. Has excavation, processing or hauling activity commenced at the site? * 6 Yes C No  5. Does the mine operate more than 180 days per year? * IT'NOT, please review Rule 1.13 to assure that your mine is in compliance. C Yes C No  6. Has this mine been granted approval for INTERMITTENT OPERATION? * C Yes C No  7. Has this mine been granted approval for INTERMITTENT OPERATION? * C Yes C No  8. Has this mine been granted approval for INTERMITTENT operations of the decimal place, such as "0.0" for the following questions, please note t	Company			
City State Zip Code Fairplay CO 804400000  Phone # Fax # 7198364271 7198364275  Permitting Contact Email Address ngriffin@park.co.us  Is the Permitting Contact information listed above correct? If it is not correct your organization's Administrator will receive an email notification. *  Yes C No  Annual Report Questions  Information contained in this report is required and will be reviewed by the Division upon receipt and prior to the next compliance inspection of the size. If, while completing this report, you kear that your size is not in compliance with the rules and the act, it is advisable that the issues be rectified promptly to avoid possible enforcement action.  I. Is the site identification sign posted in accordance with Rule 3.1.12(1). *  Yes C No  2. Is the affected area boundary clearly marked in accordance with Rule 3.1.12(2). *  Yes C No  3. Is the mine site in final reclamation (all material extraction and stockpile removal is complete)? *  If "YES," please note time limits related to completion of reclamation, Rule 3.1.3.  C Yes C No  4. Has excavation, processing or hauling activity commenced at the site? *  Yes C No  What was the date of last excavation, processing or hauling activity at the mine? *  3/20/2018  5. Does the mine operate more than 180 days per year? *  If "No", please review Rule 1.13 to assure that your mine is in compliance.  C Yes C No  6. Has this mine been granted approval for INTERMITTENT OPERATION? *  C Yes C No  7. Has this mine been granted approval for INTERMITTENT OPERATION? *	Park County			
City State Zip Code Fairplay CO 804400000  Phone # Fax # 7198364271 7198364275  Permitting Contact Email Address- regriffin@park.co.us  Is the Permitting Contact Information listed above correct? If it is not correct your organization's Administrator will receive an email notification. *  C Yes C No  Annual Report Questions  Information contained in this report is required and will be reviewed by the Division upon receipt and prior to the next complained in stable that the issues be rectified promptly to avoid possible enforcement action.  1. Is the site identification sign posted in accordance with Rule 3.1.12(1), *  C Yes C No  2. Is the affected area boundary clearly marked in accordance with Rule 3.1.12(2). *  C Yes C No  3. Is the mine site in final reclamation (all material extraction and stockpile removal is complete)? *  If "YES," please note time limits related to completion of reclamation, Rule 3.1.3.  C Yes C No  4. Has excavation, processing or hauling activity commenced at the site? *  C Yes C No  What was the date of last excavation, processing or hauling activity at the mine? *  3/20/2018  5. Does the mine operate more than 180 days per year? *  If "NO", please review Rule 1.13 to assure that your mine is in compliance.  C Yes C No  6. Has this mine been granted approval of TEMPORARY CESSATION Status? *  C Yes C No  7. Has this mine been granted approval for INTERMITTENT OPERATION? *	Address 1			
City State Zip Code Fairplay CO 804400000  Phone # Fax # 7198364271 7198364275  Permitting Contact Email Address ngriffin@parkco.us  Is the Permitting Contact information listed above correct? If it is not correct your organization's Administrator will receive an email notification. *  © Yes C No  Annual Report Questions  Information contained in this report is required and will be reviewed by the Division upon receipt and prior to the next compliance inspection of the size. If, while completing this report, you learn that your size is not in compliance with the rules and the act, it is advisable that the issues be rectified promptly to avoid possible enforcement action.  1. Is the site identification sign posted in accordance with Rule 3.1.12(1). *  © Yes C No  2. Is the affected area boundary clearly marked in accordance with Rule 3.1.12(2). *  © Yes C No  3. Is the mine site in final reclamation (all material extraction and stockpile removal is complete)? *  If "Yes," please note time limits related to completion of reclamation, Rule 3.1.3.  C Yes C No  4. Has excavation, processing or hauling activity commenced at the site? *  © Yes C No  What was the date of last excavation, processing or hauling activity at the mine? *  3/20/2018  5. Does the mine operate more than 180 days per year? *  If "TeOT, please review Rule 1.13 to assure that your mine is in compliance.  C Yes C No  6. Has this mine been granted approval for INTERMITTENT OPERATION? *  © Yes C No  7. Has this mine been granted approval for INTERMITTENT OPERATION? *	PO Box 147			
Phone # Fax # 7198364271 7198364275  Permitting Contact Email Address Ingriffin@parkco.us  Is the Permitting Contact Information listed above correct? If it is not correct your organization's Administrator will receive an email notification. *  © Yes © No  Annual Report Questions  Information contained in this report is required and will be reviewed by the Division upon receipt and prior to the next compliance inspection of the site. If, while completing this report, you learn that your site is not in compliance with the rules and the act, it is advisable that the issues be rectified promptly to avoid possible enforcement action.  1. Is the site identification sign posted in accordance with Rule 3.1.12(1). *  © Yes © No  2. Is the affected area boundary clearly marked in accordance with Rule 3.1.12(2). *  © Yes © No  3. Is the mine site in final reclamation (all material extraction and stockpile removal is complete)? *  If "YES," please note time limits related to completion of reclamation, Rule 3.1.3.  C Yes © No  4. Has excavation, processing or hauling activity commenced at the site? *  © Yes © No  What was the date of last excavation, processing or hauling activity at the mine? *  3/20/2018  5. Does the mine operate more than 180 days per year? *  If "No", please review Rule 1.13 to assure that your mine is in compliance.  C Yes © No  6. Has this mine been granted approval of TEMPORARY CESSATION Status? *  © Yes © No  7. Has this mine been granted approval for INTERMITTENT OPERATION? *  C Yes © No	Address 2			
Phone # Fax # 7198364271 7198364275  Permitting Contact Email Address Ingriffin@parkco.us  Is the Permitting Contact Information listed above correct? If it is not correct your organization's Administrator will receive an email notification. *  © Yes © No  Annual Report Questions  Information contained in this report is required and will be reviewed by the Division upon receipt and prior to the next compliance inspection of the site. If, while completing this report, you learn that your site is not in compliance with the rules and the act, it is advisable that the issues be rectified promptly to avoid possible enforcement action.  1. Is the site identification sign posted in accordance with Rule 3.1.12(1). *  © Yes © No  2. Is the affected area boundary clearly marked in accordance with Rule 3.1.12(2). *  © Yes © No  3. Is the mine site in final reclamation (all material extraction and stockpile removal is complete)? *  If "YES," please note time limits related to completion of reclamation, Rule 3.1.3.  C Yes © No  4. Has excavation, processing or hauling activity commenced at the site? *  © Yes © No  What was the date of last excavation, processing or hauling activity at the mine? *  3/20/2018  5. Does the mine operate more than 180 days per year? *  If "No", please review Rule 1.13 to assure that your mine is in compliance.  C Yes © No  6. Has this mine been granted approval of TEMPORARY CESSATION Status? *  © Yes © No  7. Has this mine been granted approval for INTERMITTENT OPERATION? *  C Yes © No				
Phone # Fax # 7198364271 7198364275  Permitting Contact Email Address Ingriffin@parkco.us  Is the Permitting Contact Information listed above correct? If it is not correct your organization's Administrator will receive an email notification. *  © Yes © No  Annual Report Questions  Information contained in this report is required and will be reviewed by the Division upon receipt and prior to the next compliance inspection of the site. If, while completing this report, you learn that your site is not in compliance with the rules and the act, it is advisable that the issues be rectified promptly to avoid possible enforcement action.  1. Is the site identification sign posted in accordance with Rule 3.1.12(1). *  © Yes © No  2. Is the affected area boundary clearly marked in accordance with Rule 3.1.12(2). *  © Yes © No  3. Is the mine site in final reclamation (all material extraction and stockpile removal is complete)? *  If "YES," please note time limits related to completion of reclamation, Rule 3.1.3.  C Yes © No  4. Has excavation, processing or hauling activity commenced at the site? *  © Yes © No  What was the date of last excavation, processing or hauling activity at the mine? *  3/20/2018  5. Does the mine operate more than 180 days per year? *  If "No", please review Rule 1.13 to assure that your mine is in compliance.  C Yes © No  6. Has this mine been granted approval of TEMPORARY CESSATION Status? *  © Yes © No  7. Has this mine been granted approval for INTERMITTENT OPERATION? *  C Yes © No				
Phone # Fax # 7198364271 7198364275  Permitting Contact Email Address ngriffin@parkco.us  Is the Permitting Contact information listed above correct? If it is not correct your organization's Administrator will receive an email notification. * © Yes C No  Annual Report Questions  Information contained in this report is required and will be reviewed by the Division upon receipt and prior to the next compliance inspection of the size. If, while completing this report, you learn that your size is not in compliance with the rules and the act, it is advisable that the issues be rectified promptly to avoid possible enforcement action.  1. Is the site identification sign posted in accordance with Rule 3.1.12(1), * © Yes C No  2. Is the affected area boundary clearly marked in accordance with Rule 3.1.12(2), * © Yes C No  3. Is the mine site in final reclamation (all material extraction and stockpile removal is complete)? * If Yes C No  4. Has excavation, processing or hauling activity commenced at the site? * © Yes C No  What was the date of last excavation, processing or hauling activity at the mine? * 3/20/2018  5. Does the mine operate more than 180 days per year? * If NoO*, please review Rule 1.13 to assure that your mine is in compliance. C Yes C No  6. Has this mine been granted approval of TEMPORARY CESSATION Status? * © Yes C No  7. Has this mine been granted approval for INTERMITTENT OPERATION? * C Yes C No	City	State	Zip Code	
Permitting Contact Email Address ngriffin@parkco.us  Is the Permitting Contact information listed above correct? If it is not correct your organization's Administrator will receive an email notification. *  (**) Yes** O No  Annual Report Questions  Information contained in this report is required and will be reviewed by the Division upon receipt and prior to the next compliance inspection of the site. If, while completing this report, you learn that your site is not in compliance with the rules and the act, it is advisable that the issues be rectified promptly to avoid possible enforcement action.  1. Is the site identification sign posted in accordance with Rule 3.1.12(1). *  (**) Yes** O No  2. Is the affected area boundary clearly marked in accordance with Rule 3.1.12(2). *  (**) Yes** O No  3. Is the mine site in final reclamation (all material extraction and stockpile removal is complete)? *  If "YES," please note time limits related to completion of reclamation, Rule 3.1.3.  (**) Yes** O No  What was the date of last excavation, processing or hauling activity at the mine? *  3/20/2018  5. Does the mine operate more than 180 days per year? *  If "NO", please review Rule 1.13 to assure that your mine is in compliance.  (**) Yes** O No  7. Has this mine been granted approval of TEMPORARY CESSATION Status? *  (**) Yes** O No  7. Has this mine been granted approval for INTERMITTENT OPERATION? *  (**) Yes** O No	Fairplay	СО	804400000	
Permitting Contact Email Address ngriffin@parkco.us  Is the Permitting Contact information listed above correct? If it is not correct your organization's Administrator will receive an email notification. *  (**) Yes** O No  Annual Report Questions  Information contained in this report is required and will be reviewed by the Division upon receipt and prior to the next compliance inspection of the site. If, while completing this report, you learn that your site is not in compliance with the rules and the act, it is advisable that the issues be rectified promptly to avoid possible enforcement action.  1. Is the site identification sign posted in accordance with Rule 3.1.12(1). *  (**) Yes** O No  2. Is the affected area boundary clearly marked in accordance with Rule 3.1.12(2). *  (**) Yes** O No  3. Is the mine site in final reclamation (all material extraction and stockpile removal is complete)? *  If "YES," please note time limits related to completion of reclamation, Rule 3.1.3.  (**) Yes** O No  What was the date of last excavation, processing or hauling activity at the mine? *  3/20/2018  5. Does the mine operate more than 180 days per year? *  If "NO", please review Rule 1.13 to assure that your mine is in compliance.  (**) Yes** O No  7. Has this mine been granted approval of TEMPORARY CESSATION Status? *  (**) Yes** O No  7. Has this mine been granted approval for INTERMITTENT OPERATION? *  (**) Yes** O No				
Permitting Contact Email Address ngriffin@parkco.us  Is the Permitting Contact information listed above correct? If it is not correct your organization's Administrator will receive an email notification. * © Yes © No  Annual Report Questions  Information contained in this report is required and will be reviewed by the Division upon receipt and prior to the next compliance inspection of the site. If, while completing this report, you learn that your site is not in compliance with the rules and the act, it is advisable that the issues be rectified promptly to avoid possible enforcement action.  I. Is the site identification sign posted in accordance with Rule 3.1.12(1). * © Yes © No  2. Is the affected area boundary clearly marked in accordance with Rule 3.1.12(2). * © Yes © No  3. Is the mine site in final reclamation (all material extraction and stockpile removal is complete)? * If "YES," please note time limits related to completion of reclamation, Rule 3.1.3. C Yes © No  4. Has excavation, processing or hauling activity commenced at the site? * © Yes © No  What was the date of last excavation, processing or hauling activity at the mine? * 3/20/2018  5. Does the mine operate more than 180 days per year? * If "No", please review Rule 1.13 to assure that your mine is in compliance. C Yes © No  6. Has this mine been granted approval of TEMPORARY CESSATION Status? * © Yes © No  7. Has this mine been granted approval for INTERMITTENT OPERATION? * C Yes © No	Phone #	Fax #		
Is the Permitting Contact information listed above correct? If it is not correct your organization's Administrator will receive an email notification. * © Yes © No  Annual Report Questions  Information contained in this report is required and will be reviewed by the Division upon receipt and prior to the next compliance inspection of the site. If, while completing this report, you learn that your site is not in compliance with the rules and the act, it is advisable that the issues be rectified promptly to avoid possible enforcement action.  1. Is the site identification sign posted in accordance with Rule 3.1.12(1).* © Yes © No  2. Is the affected area boundary clearly marked in accordance with Rule 3.1.12(2).* © Yes © No  3. Is the mine site in final reclamation (all material extraction and stockpile removal is complete)?*  If "YES," please note time limits related to completion of reclamation, Rule 3.1.3. C Yes © No  4. Has excavation, processing or hauling activity commenced at the site? * © Yes © No  What was the date of last excavation, processing or hauling activity at the mine? * 3/20/2018  5. Does the mine operate more than 180 days per year? *  If "NO", please review Rule 1.13 to assure that your mine is in compliance. C Yes © No  6. Has this mine been granted approval of TEMPORARY CESSATION Status? * © Yes © No	7198364271	7198364275		
Is the Permitting Contact information listed above correct? If it is not correct your organization's Administrator will receive an email notification. * © Yes © No  Annual Report Questions  Information contained in this report is required and will be reviewed by the Division upon receipt and prior to the next compliance inspection of the site. If, while completing this report, you learn that your site is not in compliance with the rules and the act, it is advisable that the issues be rectified promptly to avoid possible enforcement action.  1. Is the site identification sign posted in accordance with Rule 3.1.12(1).* © Yes © No  2. Is the affected area boundary clearly marked in accordance with Rule 3.1.12(2).* © Yes © No  3. Is the mine site in final reclamation (all material extraction and stockpile removal is complete)?*  If "YES," please note time limits related to completion of reclamation, Rule 3.1.3. C Yes © No  4. Has excavation, processing or hauling activity commenced at the site? * © Yes © No  What was the date of last excavation, processing or hauling activity at the mine? * 3/20/2018  5. Does the mine operate more than 180 days per year? *  If "NO", please review Rule 1.13 to assure that your mine is in compliance. C Yes © No  6. Has this mine been granted approval of TEMPORARY CESSATION Status? * © Yes © No				
Is the Permitting Contact information listed above correct? If it is not correct your organization's Administrator will receive an email notification. * © Yes © No  Annual Report Questions  Information contained in this report is required and will be reviewed by the Division upon receipt and prior to the next compliance inspection of the site. If, while completing this report, you learn that your site is not in compliance with the rules and the act, it is advisable that the issues be rectified promptly to avoid possible enforcement action.  1. Is the site identification sign posted in accordance with Rule 3.1.12(1). * © Yes © No  2. Is the affected area boundary clearly marked in accordance with Rule 3.1.12(2). * © Yes © No  3. Is the mine site in final reclamation (all material extraction and stockpile removal is complete)? * If "YES," please note time limits related to completion of reclamation, Rule 3.1.3. C Yes © No  4. Has excavation, processing or hauling activity commenced at the site? * © Yes © No  What was the date of last excavation, processing or hauling activity at the mine? * 3/20/20/18  5. Does the mine operate more than 180 days per year? * If "No", please review Rule 1.13 to assure that your mine is in compliance. C Yes © No  6. Has this mine been granted approval of TEMPORARY CESSATION Status? * © Yes © No  7. Has this mine been granted approval for INTERMITTENT OPERATION? *		Email Address		
Administrator will receive an email notification.* © Yes © No  Annual Report Questions  Information contained in this report is required and will be reviewed by the Division upon receipt and prior to the next compliance inspection of the site. If, while completing this report, you learn that your site is not in compliance with the rules and the act, it is advisable that the issues be rectified promptly to avoid possible enforcement action.  1. Is the site identification sign posted in accordance with Rule 3.1.12(1). * © Yes © No  2. Is the affected area boundary clearly marked in accordance with Rule 3.1.12(2). * © Yes © No  3. Is the mine site in final reclamation (all material extraction and stockpile removal is complete)? * If "YES," please note time limits related to completion of reclamation, Rule 3.1.3. © Yes © No  4. Has excavation, processing or hauling activity commenced at the site? * © Yes © No  What was the date of last excavation, processing or hauling activity at the mine? * 3/20/2018  5. Does the mine operate more than 180 days per year? * If "No", please review Rule 1.13 to assure that your mine is in compliance. © Yes © No  6. Has this mine been granted approval of TEMPORARY CESSATION Status? * © Yes © No  7. Has this mine been granted approval for INTERMITTENT OPERATION? * © Yes © No	0 0,			
Annual Report Questions  Information contained in this report is required and will be reviewed by the Division upon receipt and prior to the next compliance inspection of the site. If, while completing this report, you learn that your site is not in compliance with the rules and the act, it is advisable that the issues be rectified promptly to avoid possible enforcement action.  1. Is the site identification sign posted in accordance with Rule 3.1.12(1). *  (**) Yes **C No**  2. Is the affected area boundary clearly marked in accordance with Rule 3.1.12(2). *  (**) Yes **C No**  3. Is the mine site in final reclamation (all material extraction and stockpile removal is complete)? *  If "YES," please note time limits related to completion of reclamation, Rule 3.1.3.  (**) Yes **C No**  4. Has excavation, processing or hauling activity commenced at the site? *  (**) Yes **C No**  What was the date of last excavation, processing or hauling activity at the mine? *  3/20/2018  5. Does the mine operate more than 180 days per year? *  If "NO", please review Rule 1.13 to assure that your mine is in compliance.  (**) Yes **C No**  6. Has this mine been granted approval of TEMPORARY CESSATION Status? *  (**) Yes **C No**  7. Has this mine been granted approval for INTERMITTENT OPERATION? *  (**) Yes **C No**	_			
Information contained in this report is required and will be reviewed by the Division upon receipt and prior to the next compliance inspection of the site. If, while completing this report, you learn that your site is not in compliance with the rules and the act, it is advisable that the issues be rectified promptly to avoid possible enforcement action.  1. Is the site identification sign posted in accordance with Rule 3.1.12(1). *  © Yes © No  2. Is the affected area boundary clearly marked in accordance with Rule 3.1.12(2). *  © Yes © No  3. Is the mine site in final reclamation (all material extraction and stockpile removal is complete)? *  If "YES," please note time limits related to completion of reclamation, Rule 3.1.3.  © Yes © No  4. Has excavation, processing or hauling activity commenced at the site? *  © Yes © No  What was the date of last excavation, processing or hauling activity at the mine? *  3/20/2018  5. Does the mine operate more than 180 days per year? *  If "No", please review Rule 1.13 to assure that your mine is in compliance.  © Yes © No  6. Has this mine been granted approval of TEMPORARY CESSATION Status? *  © Yes © No  7. Has this mine been granted approval for INTERMITTENT OPERATION? *  © Yes © No				
Information contained in this report is required and will be reviewed by the Division upon receipt and prior to the next compliance inspection of the site. If, while completing this report, you learn that your site is not in compliance with the rules and the act, it is advisable that the issues be rectified promptly to avoid possible enforcement action.  1. Is the site identification sign posted in accordance with Rule 3.1.12(1). *  © Yes © No  2. Is the affected area boundary clearly marked in accordance with Rule 3.1.12(2). *  © Yes © No  3. Is the mine site in final reclamation (all material extraction and stockpile removal is complete)? *  If "YES," please note time limits related to completion of reclamation, Rule 3.1.3.  © Yes © No  4. Has excavation, processing or hauling activity commenced at the site? *  © Yes © No  What was the date of last excavation, processing or hauling activity at the mine? *  3/20/2018  5. Does the mine operate more than 180 days per year? *  If "No", please review Rule 1.13 to assure that your mine is in compliance.  © Yes © No  6. Has this mine been granted approval of TEMPORARY CESSATION Status? *  © Yes © No  7. Has this mine been granted approval for INTERMITTENT OPERATION? *  © Yes © No				
compliance inspection of the site. If, while completing this report, you learn that your site is not in compliance with the rules and the act, it is advisable that the issues be rectified promptly to avoid possible enforcement action.  1. Is the site identification sign posted in accordance with Rule 3.1.12(1). *  © Yes © No  2. Is the affected area boundary clearly marked in accordance with Rule 3.1.12(2). *  © Yes © No  3. Is the mine site in final reclamation (all material extraction and stockpile removal is complete)? *  If "YES," please note time limits related to completion of reclamation, Rule 3.1.3.  © Yes © No  4. Has excavation, processing or hauling activity commenced at the site? *  © Yes © No  What was the date of last excavation, processing or hauling activity at the mine? *  3/20/2018  5. Does the mine operate more than 180 days per year? *  If "No", please review Rule 1.13 to assure that your mine is in compliance.  © Yes © No  6. Has this mine been granted approval of TEMPORARY CESSATION Status? *  © Yes © No  7. Has this mine been granted approval for INTERMITTENT OPERATION? *  © Yes © No	Annual Repo	ort Questions		
© Yes ○ No  2. Is the affected area boundary clearly marked in accordance with Rule 3.1.12(2).* © Yes ○ No  3. Is the mine site in final reclamation (all material extraction and stockpile removal is complete)?*  If "YES," please note time limits related to completion of reclamation, Rule 3.1.3. ○ Yes ⓒ No  4. Has excavation, processing or hauling activity commenced at the site?* ⓒ Yes ⓒ No  What was the date of last excavation, processing or hauling activity at the mine?* 3/20/2018  5. Does the mine operate more than 180 days per year?*  If "NO", please review Rule 1.13 to assure that your mine is in compliance. ○ Yes ⓒ No  6. Has this mine been granted approval of TEMPORARY CESSATION Status?* ⓒ Yes ⓒ No  7. Has this mine been granted approval for INTERMITTENT OPERATION?* ⓒ Yes ⓒ No	compliance inspection	of the site. If, while com	appleting this report, you learn that your site is not in compliance with the rules and	
© Yes ○ No  2. Is the affected area boundary clearly marked in accordance with Rule 3.1.12(2).* © Yes ○ No  3. Is the mine site in final reclamation (all material extraction and stockpile removal is complete)?*  If "YES," please note time limits related to completion of reclamation, Rule 3.1.3. ○ Yes ⓒ No  4. Has excavation, processing or hauling activity commenced at the site?* ⓒ Yes ⓒ No  What was the date of last excavation, processing or hauling activity at the mine?* 3/20/2018  5. Does the mine operate more than 180 days per year?*  If "NO", please review Rule 1.13 to assure that your mine is in compliance. ○ Yes ⓒ No  6. Has this mine been granted approval of TEMPORARY CESSATION Status?* ⓒ Yes ⓒ No  7. Has this mine been granted approval for INTERMITTENT OPERATION?* ○ Yes ⓒ No	1. Is the site ident	ification sign posted	in accordance with Rule 3.1.12(1). *	
© Yes © No  3. Is the mine site in final reclamation (all material extraction and stockpile removal is complete)? *  If "YES," please note time limits related to completion of reclamation, Rule 3.1.3.  ○ Yes ⓒ No  4. Has excavation, processing or hauling activity commenced at the site? *  ⓒ Yes ⓒ No  What was the date of last excavation, processing or hauling activity at the mine? *  3/20/2018  5. Does the mine operate more than 180 days per year? *  If "NO", please review Rule 1.13 to assure that your mine is in compliance.  ○ Yes ⓒ No  6. Has this mine been granted approval of TEMPORARY CESSATION Status? *  ⓒ Yes ⓒ No  7. Has this mine been granted approval for INTERMITTENT OPERATION? *  ○ Yes ⓒ No		maation sign postea	4000.441.100 11.11.14.0	
© Yes © No  3. Is the mine site in final reclamation (all material extraction and stockpile removal is complete)? *  If "YES," please note time limits related to completion of reclamation, Rule 3.1.3.  ○ Yes ⓒ No  4. Has excavation, processing or hauling activity commenced at the site? *  ⓒ Yes ⓒ No  What was the date of last excavation, processing or hauling activity at the mine? *  3/20/2018  5. Does the mine operate more than 180 days per year? *  If "NO", please review Rule 1.13 to assure that your mine is in compliance.  ○ Yes ⓒ No  6. Has this mine been granted approval of TEMPORARY CESSATION Status? *  ⓒ Yes ⓒ No  7. Has this mine been granted approval for INTERMITTENT OPERATION? *  ○ Yes ⓒ No	2 Is the affected a	area houndary clearl	ly marked in accordance with Pule 3.1.12(2) *	
3. Is the mine site in final reclamation (all material extraction and stockpile removal is complete)? *  If "YES," please note time limits related to completion of reclamation, Rule 3.1.3.  O Yes O No  4. Has excavation, processing or hauling activity commenced at the site? *  O Yes O No  What was the date of last excavation, processing or hauling activity at the mine? *  3/20/2018  5. Does the mine operate more than 180 days per year? *  If "NO", please review Rule 1.13 to assure that your mine is in compliance.  O Yes O No  6. Has this mine been granted approval of TEMPORARY CESSATION Status? *  O Yes O No  7. Has this mine been granted approval for INTERMITTENT OPERATION? *  O Yes O No		irea boundary cicari	y marked in accordance with raic 5.1.12(2).	
If "YES," please note time limits related to completion of reclamation, Rule 3.1.3.  O Yes O No  4. Has excavation, processing or hauling activity commenced at the site? *  O Yes O No  What was the date of last excavation, processing or hauling activity at the mine? *  3/20/2018  5. Does the mine operate more than 180 days per year? *  If "NO", please review Rule 1.13 to assure that your mine is in compliance.  O Yes O No  6. Has this mine been granted approval of TEMPORARY CESSATION Status? *  O Yes O No  7. Has this mine been granted approval for INTERMITTENT OPERATION? *  O Yes O No		<i>6</i>	(-II	
C Yes				
© Yes ○ No  What was the date of last excavation, processing or hauling activity at the mine? * 3/20/2018  5. Does the mine operate more than 180 days per year? *  If "NO", please review Rule 1.13 to assure that your mine is in compliance.  ○ Yes ○ No  6. Has this mine been granted approval of TEMPORARY CESSATION Status? *  ⓒ Yes ○ No  7. Has this mine been granted approval for INTERMITTENT OPERATION? *  ○ Yes ○ No		ne minis related to compl	leading of reclamation, rule 3.1.3.	
© Yes ○ No  What was the date of last excavation, processing or hauling activity at the mine? * 3/20/2018  5. Does the mine operate more than 180 days per year? *  If "NO", please review Rule 1.13 to assure that your mine is in compliance.  ○ Yes ○ No  6. Has this mine been granted approval of TEMPORARY CESSATION Status? *  ⓒ Yes ○ No  7. Has this mine been granted approval for INTERMITTENT OPERATION? *  ○ Yes ○ No	4 Has excavation	processing or hauli	ing activity commonced at the cite? *	
What was the date of last excavation, processing or hauling activity at the mine? * 3/20/2018  5. Does the mine operate more than 180 days per year? *  If "NO", please review Rule 1.13 to assure that your mine is in compliance.  ○ Yes ○ No  6. Has this mine been granted approval of TEMPORARY CESSATION Status? *  ○ Yes ○ No  7. Has this mine been granted approval for INTERMITTENT OPERATION? *  ○ Yes ○ No		processing or naun	ing activity commenced at the site:	
5. Does the mine operate more than 180 days per year? *  If "NO", please review Rule 1.13 to assure that your mine is in compliance.  C Yes  No  6. Has this mine been granted approval of TEMPORARY CESSATION Status? *  © Yes  No  7. Has this mine been granted approval for INTERMITTENT OPERATION? *  C Yes  No				
5. Does the mine operate more than 180 days per year? *  If "NO", please review Rule 1.13 to assure that your mine is in compliance.  C Yes  No  6. Has this mine been granted approval of TEMPORARY CESSATION Status? *  Yes  No  7. Has this mine been granted approval for INTERMITTENT OPERATION? *  C Yes  No		of last excavation,	processing or hauling activity at the mine? *	
If "NO", please review Rule 1.13 to assure that your mine is in compliance.  O Yes O No  6. Has this mine been granted approval of TEMPORARY CESSATION Status? *  O Yes O No  7. Has this mine been granted approval for INTERMITTENT OPERATION? *  O Yes O No				
C Yes				
6. Has this mine been granted approval of TEMPORARY CESSATION Status? *  ⊙ Yes ○ No  7. Has this mine been granted approval for INTERMITTENT OPERATION? *  ○ Yes ⊙ No				
<ul> <li>⊙ Yes ○ No</li> <li>7. Has this mine been granted approval for INTERMITTENT OPERATION? *</li> <li>○ Yes ⊙ No</li> </ul>				
7. Has this mine been granted approval for INTERMITTENT OPERATION? *  C Yes ⊙ No		en granted approva	al of TEMPORARY CESSATION Status? *	
C Yes    No		een granted annroy:	al for INTERMITTENT OPERATION? *	
		granicea approve		
	For the following a	uestions, please note	that numeric values must include one decimal place, such as "0.0" for	

8. Number of acres currently affected (mining + incomplete and or unreleased reclamation). * (?) 3.2
9. Number of acres that were newly affected during the current report year * (?) 0.5
<ul><li>10. Number of acres that were reclaimed during the current report year. * (?)</li><li>0.0</li></ul>
11. Estimated new acreage to be affected in the next report year. * (?) 0.8
12. Estimated acres to be reclaimed in the next report year. * (?) 1.0
13. Total acres in various stages of reclamation, since permitted mining activities began:
Total acres backfilled * (?) 0.0
Total acres graded * (?) 0.0
Total acres seeded with approved mix * (?) 0.0
Seed Application Method * NA
Total acres fertilized with aproved fertilizer * (?) 0.0
Fertilizer Application Method * NA
Total acres with topsoil replaced * (?) 0.0
Topsoil replacement depth (in.) * (?) 0.0
Total acres mulched with approved mulch * (?) 0.0
Mulch application rate (tons/ac) * (?) 0.0
Mulch Application Method * NA
14. Is weed control being conducted in accordance with an approved Weed Control Plan? ★  If "YES", indicate the weed species, control area, control type, application rate and treatment date on the report map.  O Yes O No O N/A
15. Is adequate topsoil reserved for reclamation, based on your approved permit? *

zero acres, or 10.2 instead of 10.23.

If "NO", please explain
16. Is the reserved topsoil vegetated/stabilized in accordance with Rule 3.1.9(1)? *  If "NO", please explain  Yes O No O N/A
17. If mining has exposed groundwater, is the site in compliance with the approved mining plan and Office of the State Engineer (Well Permit, S.W.S.P., and/or Permanent Augmentation Plan)? *  O Yes O No O N/A
18. Are all hazardous materials stored within approved spill containment structures? ★ ○ Yes ○ No ○ N/A
19. Is your financial warranty value sufficient to cover the cost to complete reclamation? ★  ○ Yes ○ No ○ N/A
20. Is your basis for legal right to enter still valid? *  • Yes • No
21. Does your permit require you to submit monitoring information annually? *  O Yes O No O N/A
22. As required by Colorado Mined Land Reclamation Act and/or Colorado Land Reclamation Act for the Extraction of Construction Materials (C.R.S.34-32-116 or 34-32.5-116), attach a map to this report that accurately depicts the permit boundary, current affected area boundary and location of the acreages specified in items 8-12 and 15. *
Only PDF formatted files can be uploaded.  SULPHUR MTN ANNUAL MAP.pdf  68.16KB
23. If you have supplemental information you would like to provide, please upload it here.  Only PDF formatted files can be uploaded.
24. Rule 5.7 requires submittal of final abandonment reports within 60 days for any drill hole(s) with artesian flows and no later than 12 months for all other completed drill holes. If drill holes are a component of your exploration/prospecting activities, have they been properly abandoned?  © Yes © No © NA
Annual Fee Payment
Payment Confirmation Number * (?) 86876944
Signature
<b>Submittal Date</b> 03-30-2018
<ul> <li>I, the undersigned, hereby state that the information provided in this report is true and accurate, and that site operations are being conducted in accordance with the Division approved mining and reclamation plans. *</li> <li>✓ I Agree</li> </ul>