Annual Report Map:

Snyder Quarry
May 9, 2018

.75 acre

Unaffected area

Rock fall, .33 acres

Old sediment pond, .48 acres

2.7 acres

43.7 acres affected

2.4 acres

Processing area

2.5 acres

Reclaimed, not released.

Quarry access road 5.0 acres

Notes: Product stockpiles are located at various locations throughout the pit floor, based on product type.
Light blue lines are the affected area boundaries. Double red line is the access road affected area.

Please see the 2016 Annual Report map for the location of the Affected Area Boundary versus the Permit Boundary.

Total affected acres:
43.7 Pit area
.33 Rockfall
.48 Old sed pond
5.0 Access road
49.51 subtotal
- .7 Unaffected area
48.81 Total affected acres

Google Earth
2016 Google

N

360

3000 ft