

Cazier - DNR, Tim <tim.cazier@state.co.us>

Weekly Liner Update

1 message

Justin Bills < Justin.Bills@newmont.com>

Thu, Jun 7, 2018 at 4:25 PM

To: "Cazier - DNR, Tim" <tim.cazier@state.co.us>

Cc: Meg Burt <Margaret.Burt@newmont.com>, Gary Horton <Gary.Horton@newmont.com>, Elliott Russell - DNR <elliott.russell@state.co.us>, "Eschberger - DNR, Amy" <amy.eschberger@state.co.us>

Tim,

The geomembrane liner integrity investigation has continued to make steady progress with Newfields overseeing Ames Construction as they continue to remove material from the investigation area. The Cat 321C, D6T and D9T continued to remove material from between the 9650' and 9750' benches. Material removal was focused in the Northeast side of the work area.

A Cat 336F excavator equipped with a smooth roller compactor was used to compact the loose material on the SLF between the 9735' and 9695' elevations.

In preparation for liner repairs, 12 rolls of geomembrane material arrived on site June 1st.

Please let me know if you have any questions,

Thank you,



Justin Bills

Senior Environmental Specialist

Cripple Creek and Victor Gold Mining Co.

T 719.689.4046

M 719.306.3388

www.newmont.com

Newmont Mining Corporation

Cripple Creek and Victor Gold Mining Co.

100 North 3rd Street

Victor, CO 80860

Please consider the environment before printing this e-mail.

2 attachments



06.01_GeoExposure.jpg 140K



604_SLF_compaction.jpg 265K



