

Taft Expansion 2018 Annual Report

Mining

All mining and reclamation is complete except for the area where the conveyor feeds to the south and east. This 0.85 acres will not be reclaimed until mining on M-1977-439 is completed and the conveyor can be removed.

Water Monitoring

Now that mining is complete, dewatering pumps have been removed and water has been allowed to fill back in, submittal of annual monitoring data will now cease.