



September 6, 2018

Rob Zuber
Division of Reclamation, Mining & Safety
Department of Natural Resources
1313 Sherman Street, Room 215
Denver, Colorado 80203

Re: Quarterly Pond Inspection
Keenesburg Mine, Permit C-1981-028

Dear Rob Zuber:

Attached is a copy of the Quarterly Pond Inspection report for the third Quarter of 2018. Coors Energy Company has prepared and is submitting this copy in compliance with revised Division Regulation 4.05.9(17). The original of this report has been placed in the inspection reference volume at the site.

Should there be questions about the report, or a need for additional information, please contact me at (303 944-8166).

Sincerely,
Danny Kipp

Danny Kipp
Chief Reclamation Specialist

Enclosure

ANNUAL & QUARTERLY POND INSPECTION

COORS ENERGY COMPANY

KEENESBURG MINE SITE

Date of Inspection 9-6-18

Pond Identification:	Sediment Pond #2	Dugout	
Type of Pond	Sediment	Permanent	
Approx. water level - (% of capacity)	<u>4'</u>	<u>3'</u>	
Sediment level - (% of capacity)	<u>0</u>	<u>0</u>	
Outflow			
Erosional Features:	<u>yes</u> <u>no</u>	<u>yes</u> <u>no</u>	
- Rills / Gullies	<u>NO</u>	<u>NO</u>	
- Inadequate Vegetation			
- Outlet Channel Erosion	<u>NO</u>	<u>NO</u>	
- Burrows	<u>NO</u>	<u>NO</u>	
- Other			
Structural Issues:			
- Settlement	<u>NO</u>	<u>NO</u>	
- Cracks/Slides	<u>NO</u>	<u>NO</u>	
- Seepage	<u>NO</u>	<u>NO</u>	
- Spillways (cond.)	<u>Good</u>	<u>Good</u>	
-Other			
Capacities:	15.6 acre ft. 5,097,925 gals.	19.7 acre ft. 6,437,760 gals.	
Comments:	These impoundments are maintained in accordance with the approved plans and applicable regulations for each.		

Signature (P.E. or Authorized Inspector): Dany J. Hys