Minerals Reclamation Permit Annual Report



Disclaimer

Under the terms of your NOI or Reclamation Permit and Colorado Statutes, you must submit Annual Fees and Annual Reports (including a map). You must pay the Annual Fee and submit an Annual Report each year until reclamation responsibility release is granted. The Annual Fee is not a renewal fee. The Fee and Report are for LAST YEAR'S mining and reclamation season, and MUST be paid even if your operation was inactive.

If you have requested reclamation responsibility release from the Division of Reclamation, Mining and Safety ("Division") but your permit is not released by the anniversary date listed below, the Annual Fee MUST be paid. If the permit is released before the anniversary date, then by Statute, it is not necessary to pay an Annual Fee or submit an Annual Report for that year.

Division records indicate the following is due:

Select Permit Number *

Only Permit Numbers with currently due Annual Fees will be listed. If the Permit Number is not listed, then the Annual Fees are not due, the Permit Number has already been submitted, or the Permit Number Annual Fee payment has been processed.

M2005060

Select Anniversary Date *

09-30-2018

PLEASE REMEMBER TO CLICK "SUBMIT" AFTER YOU HAVE COMPLETED YOUR REPORT AND PAYMENT.

Please check the box indicating you have read and understand the terms of the Annual Report and Annual Fee $^{\mbox{*}}$

▼ I understand and agree to the terms

General Information

Permittee Name

Weld County Public Works

Operation Name

Ashbaugh Gravel Pit

Permit Number Fee Due Permit Acreage

M2005060 791.00 139.60

County Anniversary Date Current Bond Amount

Weld 09-30-2018 0.00

Permittee Contact Information

Permitting Contact Name

Clay Kimmi

Address 2 P.O. Box 758 City State Zip Code Greeley CO 805320000 Phone # Fax # 9703046496 9703046497 Permitting Contact Email Address Is the Permitting Contact information listed above correct? If it is not correct your organization's Administrator will receive an email notification. * 6 Yes C No Annual Report Questions Information contained in this report is required and will be reviewed by the Division upon receipt and prior to the next compliance inspection of the site. If, while completing this report, you learn that your site is not in compliance with the rules and the act, it is advisable that the issues be rectified promptly to avoid possible enforcement action. 1. Is the site identification sign posted in accordance with Rule 3.1.12(1). * 6 Yes C No 2. Is the affected area boundary clearly marked in accordance with Rule 3.1.12(2). * 6 Yes C No 3. Is the mine site in final reclamation (all material extraction and stockpile removal is complete)? * If Yes, *please note time limits related to completion of reclamation, Rule 3.1.3. G Yes C No 4. Has excavation, processing or hauling activity commenced at the site? * 6 Yes C No What was the date of last excavation, processing or hauling activity at the mine? * 12/31/2015 5. Does the mine operate more than 180 days per year? * IT NOT, please review Rule 1.13 to assure that your mine is in compliance. C Yes C No 6. Has this mine been granted approval for INTERMITTENT OPERATION? *	Company		
Address 2 P.O. Box 758 City State Zip Code Greeley CO 805320000 Phone # Fax # 9703046496 9703046497 Permitting Contact Email Address Is the Permitting Contact information listed above correct? If it is not correct your organization's Administrator will receive an email notification. * 6 Yes C No Annual Report Questions Information contained in this report is required and will be reviewed by the Division upon receipt and prior to the next compliance inspection of the site. If, while completing this report, you learn that your site is not in compliance with the rules and the act, it is advisable that the issues be rectified promptly to avoid possible enforcement action. 1. Is the site identification sign posted in accordance with Rule 3.1.12(1). * 6 Yes C No 2. Is the affected area boundary clearly marked in accordance with Rule 3.1.12(2). * 6 Yes C No 3. Is the mine site in final reclamation (all material extraction and stockpile removal is complete)? * If Yes, *please note time limits related to completion of reclamation, Rule 3.1.3. G Yes C No 4. Has excavation, processing or hauling activity commenced at the site? * 6 Yes C No What was the date of last excavation, processing or hauling activity at the mine? * 12/31/2015 5. Does the mine operate more than 180 days per year? * IT NOT, please review Rule 1.13 to assure that your mine is in compliance. C Yes C No 6. Has this mine been granted approval for INTERMITTENT OPERATION? *	Weld County Public V	Vorks	
Address 2 P.O. Box 758 City State Zip Code Greeley CO 806320000 Phone # Fax # 9703046496 9703046497 Permitting Contact Email Address Lis the Permitting Contact Information listed above correct? If it is not correct your organization's Administrator will receive an email notification. * 6 Yes C No Annual Report Questions Information contained in this report is required and will be reviewed by the Division upon receipt and prior to the next compliance inspection of the site. If, while completing this report, you learn that your site is not in compliance with the rules and the act, it is advisable that the issues be rectified promptly to avoid possible enforcement action. 1. Is the site identification sign posted in accordance with Rule 3.1.12(1). * 6 Yes C No 2. Is the affected area boundary clearly marked in accordance with Rule 3.1.12(2). * 6 Yes C No 3. Is the mine site in final reclamation (all material extraction and stockpile removal is complete)? * Lif YES, *please note time limits related to completion of reclamation, Rule 3.1.3. 6 Yes C No 4. Has excavation, processing or hauling activity commenced at the site? * 6 Yes C No What was the date of last excavation, processing or hauling activity at the mine? * 12/31/2015 5. Does the mine operate more than 180 days per year? * 15 No.*, please review Rule 1.13 to assure that your mine is in compliance. C Yes C No 6. Has this mine been granted approval of TEMPORARY CESSATION Status? * C Yes C No 7. Has this mine been granted approval for INTERMITTENT OPERATION? *	Address 1		
P.O. Box 758 City State Zip Code Greeley CO 806320000 Phone # Fax # 9703046496 9703046497 Permitting Contact Email Address Is the Permitting Contact information listed above correct? If it is not correct your organization's Administrator will receive an email notification. * © Yes C No Annual Report Questions Information contained in this report is required and will be reviewed by the Division upon receipt and prior to the next compliance inspection of the site. If, while completing this report, you learn that your site is not in compliance with the rules and the act, it is advisable that the issues be rectified promptly to avoid possible enforcement action. 1. Is the site identification sign posted in accordance with Rule 3.1.12(1). * © Yes C No 2. Is the affected area boundary clearly marked in accordance with Rule 3.1.12(2). * © Yes C No 3. Is the mine site in final reclamation (all material extraction and stockpile removal is complete)? * If "YES," please note time limits related to complete of reclamation, Rule 3.1.3. © Yes C No 4. Has excavation, processing or hauling activity commenced at the site? * © Yes C No What was the date of last excavation, processing or hauling activity at the mine? * 11/21/31/2015 5. Does the mine operate more than 180 days per year? * If "No", please review Rule 1.13 to assure that your mine is in compliance. C Yes C No 6. Has this mine been granted approval of TEMPORARY CESSATION Status? * C Yes C No 7. Has this mine been granted approval for INTERMITTENT OPERATION? *	1111 H St.		
City State Zip Code Greeley CO 806320000 Phone # Fax # 9703046496 9703046497 Permitting Contact Email Address Is the Permitting Contact information listed above correct? If it is not correct your organization's Administrator will receive an email notification. * 6 Yes C No Annual Report Questions Information contained in this report is required and will be reviewed by the Division upon receipt and prior to the next compliance inspection of the site. If, while completing this report, you learn that your site is not in compliance with the rules and the act, it is advisable that the issues be rectified promptly to avoid possible enforcement action. 1. Is the site identification sign posted in accordance with Rule 3.1.12(1). * 6 Yes C No 2. Is the affected area boundary clearly marked in accordance with Rule 3.1.12(2). * 6 Yes C No 3. Is the mine site in final reclamation (all material extraction and stockpile removal is complete)? * If "YES," please note time limits related to completion of reclamation, Rule 3.1.3. 6 Yes C No 4. Has excavation, processing or hauling activity commenced at the site? * 6 Yes C No What was the date of last excavation, processing or hauling activity at the mine? * 12/31/2015 5. Does the mine operate more than 180 days per year? * 11 "YO", please review Rule 1.13 to assure that your mine is in compliance. C Yes C No 6. Has this mine been granted approval of TEMPORARY CESSATION Status? * C Yes C No 7. Has this mine been granted approval for INTERMITTENT OPERATION? *	Address 2		
Phone # Fax # 9703046496 9703046497 Permitting Contact Email Address Is the Permitting Contact information listed above correct? If it is not correct your organization's Administrator will receive an email notification. * © Yes C No Annual Report Questions Information contained in this report is required and will be reviewed by the Division upon receipt and prior to the next compliance inspection of the site. If, while completing this report, you learn that your site is not in compliance with the rules and the act, it is advisable that the issues be rectified promptly to avoid possible enforcement action. 1. Is the site identification sign posted in accordance with Rule 3.1.12(1). * © Yes C No 2. Is the affected area boundary clearly marked in accordance with Rule 3.1.12(2). * © Yes C No 3. Is the mine site in final reclamation (all material extraction and stockpile removal is complete)? * If "YES," please note time limits related to completion of reclamation, Rule 3.1.3. © Yes C No 4. Has excavation, processing or hauling activity commenced at the site? * © Yes C No What was the date of last excavation, processing or hauling activity at the mine? * 12/31/2015 5. Does the mine operate more than 180 days per year? * If "No", please review Rule 1.13 to assure that your mine is in compliance. C Yes C No 6. Has this mine been granted approval of TEMPORARY CESSATION Status? * C Yes C No 7. Has this mine been granted approval for INTERMITTENT OPERATION? *	P.O. Box 758		
Phone # Fax # 9703046496 9703046497 Permitting Contact Email Address Is the Permitting Contact information listed above correct? If it is not correct your organization's Administrator will receive an email notification. * © Yes C No Annual Report Questions Information contained in this report is required and will be reviewed by the Division upon receipt and prior to the next compliance inspection of the site. If, while completing this report, you learn that your site is not in compliance with the rules and the act, it is advisable that the issues be rectified promptly to avoid possible enforcement action. 1. Is the site identification sign posted in accordance with Rule 3.1.12(1). * © Yes C No 2. Is the affected area boundary clearly marked in accordance with Rule 3.1.12(2). * © Yes C No 3. Is the mine site in final reclamation (all material extraction and stockpile removal is complete)? * If "YES," please note time limits related to completion of reclamation, Rule 3.1.3. © Yes C No 4. Has excavation, processing or hauling activity commenced at the site? * © Yes C No What was the date of last excavation, processing or hauling activity at the mine? * 12/31/2015 5. Does the mine operate more than 180 days per year? * If "No", please review Rule 1.13 to assure that your mine is in compliance. C Yes C No 6. Has this mine been granted approval of TEMPORARY CESSATION Status? * C Yes C No 7. Has this mine been granted approval for INTERMITTENT OPERATION? *			
Phone # Fax # 9703046496 9703046497 Permitting Contact Email Address Is the Permitting Contact information listed above correct? If it is not correct your organization's Administrator will receive an email notification. * 6 Yes C No Annual Report Questions Information contained in this report is required and will be reviewed by the Division upon receipt and prior to the next compliance inspection of the site. If, while completing this report, you learn that your site is not in compliance with the rules and the act, it is advisable that the issues be rectified promptly to avoid possible enforcement action. 1. Is the site identification sign posted in accordance with Rule 3.1.12(1). * 6 Yes C No 2. Is the affected area boundary clearly marked in accordance with Rule 3.1.12(2). * 6 Yes C No 3. Is the mine site in final reclamation (all material extraction and stockpile removal is complete)? * If "YES," please note time limits related to completion of reclamation, Rule 3.1.3. 6 Yes C No 4. Has excavation, processing or hauling activity commenced at the site? * 6 Yes C No What was the date of last excavation, processing or hauling activity at the mine? * 12/31/2015 5. Does the mine operate more than 180 days per year? * If "No", please review Rule 1.13 to assure that your mine is in compliance. C Yes C No 6. Has this mine been granted approval of TEMPORARY CESSATION Status? * C Yes C No 7. Has this mine been granted approval for INTERMITTENT OPERATION? *	City	State	Zip Code
Permitting Contact Email Address Is the Permitting Contact information listed above correct? If it is not correct your organization's Administrator will receive an email notification. * © Yes © No Annual Report Questions Information contained in this report is required and will be reviewed by the Division upon receipt and prior to the next compliance inspection of the site. If, while completing this report, you learn that your site is not in compliance with the rules and the act, it is advisable that the issues be rectified promptly to avoid possible enforcement action. 1. Is the site identification sign posted in accordance with Rule 3.1.12(1). * © Yes © No 2. Is the affected area boundary clearly marked in accordance with Rule 3.1.12(2). * © Yes © No 3. Is the mine site in final reclamation (all material extraction and stockpile removal is complete)? * If "YES," please note time limits related to completion of reclamation, Rule 3.1.3. © Yes © No 4. Has excavation, processing or hauling activity commenced at the site? * © Yes © No What was the date of last excavation, processing or hauling activity at the mine? * 12/31/2015 5. Does the mine operate more than 180 days per year? * If "No", please review Rule 1.13 to assure that your mine is in compliance. C Yes © No 6. Has this mine been granted approval of TEMPORARY CESSATION Status? * C Yes © No 7. Has this mine been granted approval for INTERMITTENT OPERATION? *	Greeley	СО	806320000
Permitting Contact Email Address Is the Permitting Contact information listed above correct? If it is not correct your organization's Administrator will receive an email notification. * © Yes © No Annual Report Questions Information contained in this report is required and will be reviewed by the Division upon receipt and prior to the next compliance inspection of the site. If, while completing this report, you learn that your site is not in compliance with the rules and the act, it is advisable that the issues be rectified promptly to avoid possible enforcement action. 1. Is the site identification sign posted in accordance with Rule 3.1.12(1). * © Yes © No 2. Is the affected area boundary clearly marked in accordance with Rule 3.1.12(2). * © Yes © No 3. Is the mine site in final reclamation (all material extraction and stockpile removal is complete)? * If "YES," please note time limits related to completion of reclamation, Rule 3.1.3. © Yes © No 4. Has excavation, processing or hauling activity commenced at the site? * © Yes © No What was the date of last excavation, processing or hauling activity at the mine? * 12/31/2015 5. Does the mine operate more than 180 days per year? * If "No", please review Rule 1.13 to assure that your mine is in compliance. C Yes © No 6. Has this mine been granted approval of TEMPORARY CESSATION Status? * C Yes © No 7. Has this mine been granted approval for INTERMITTENT OPERATION? *			
Permitting Contact Email Address Is the Permitting Contact information listed above correct? If it is not correct your organization's Administrator will receive an email notification. * © Yes © No Annual Report Questions Information contained in this report is required and will be reviewed by the Division upon receipt and prior to the next compliance inspection of the site. If, while completing this report, you learn that your site is not in compliance with the rules and the act, it is advisable that the issues be rectified promptly to avoid possible enforcement action. 1. Is the site identification sign posted in accordance with Rule 3.1.12(1). * © Yes © No 2. Is the affected area boundary clearly marked in accordance with Rule 3.1.12(2). * © Yes © No 3. Is the mine site in final reclamation (all material extraction and stockpile removal is complete)? * If "YES," please note time limits related to completion of reclamation, Rule 3.1.3. © Yes © No 4. Has excavation, processing or hauling activity commenced at the site? * © Yes © No What was the date of last excavation, processing or hauling activity at the mine? * 12/31/2015 5. Does the mine operate more than 180 days per year? * If "No", please review Rule 1.13 to assure that your mine is in compliance. C Yes © No 6. Has this mine been granted approval of TEMPORARY CESSATION Status? * C Yes © No 7. Has this mine been granted approval for INTERMITTENT OPERATION? *	Phone #	Fax #	
Is the Permitting Contact information listed above correct? If it is not correct your organization's Administrator will receive an email notification. * 6 Yes C No Annual Report Questions Information contained in this report is required and will be reviewed by the Division upon receipt and prior to the next compliance inspection of the site. If, while completing this report, you learn that your site is not in compliance with the rules and the act, it is advisable that the issues be rectified promptly to avoid possible enforcement action. 1. Is the site identification sign posted in accordance with Rule 3.1.12(1). * 6 Yes C No 2. Is the affected area boundary clearly marked in accordance with Rule 3.1.12(2). * 6 Yes C No 3. Is the mine site in final reclamation (all material extraction and stockpile removal is complete)? * 1f "YES," please note time limits related to completion of reclamation, Rule 3.1.3. 6 Yes C No 4. Has excavation, processing or hauling activity commenced at the site? * 6 Yes C No What was the date of last excavation, processing or hauling activity at the mine? * 12/31/2015 5. Does the mine operate more than 180 days per year? * 1f "No", please review Rule 1.13 to assure that your mine is in compliance. C Yes C No 6. Has this mine been granted approval of TEMPORARY CESSATION Status? * C Yes C No 7. Has this mine been granted approval for INTERMITTENT OPERATION? *	9703046496	970304	16497
Is the Permitting Contact information listed above correct? If it is not correct your organization's Administrator will receive an email notification. * 6 Yes C No Annual Report Questions Information contained in this report is required and will be reviewed by the Division upon receipt and prior to the next compliance inspection of the site. If, while completing this report, you learn that your site is not in compliance with the rules and the act, it is advisable that the issues be rectified promptly to avoid possible enforcement action. 1. Is the site identification sign posted in accordance with Rule 3.1.12(1). * 6 Yes C No 2. Is the affected area boundary clearly marked in accordance with Rule 3.1.12(2). * 6 Yes C No 3. Is the mine site in final reclamation (all material extraction and stockpile removal is complete)? * 1f "YES," please note time limits related to completion of reclamation, Rule 3.1.3. 6 Yes C No 4. Has excavation, processing or hauling activity commenced at the site? * 6 Yes C No What was the date of last excavation, processing or hauling activity at the mine? * 12/31/2015 5. Does the mine operate more than 180 days per year? * 1f "No", please review Rule 1.13 to assure that your mine is in compliance. C Yes C No 6. Has this mine been granted approval of TEMPORARY CESSATION Status? * C Yes C No 7. Has this mine been granted approval for INTERMITTENT OPERATION? *			
Administrator will receive an email notification. * 6 Yes O No Annual Report Questions Information contained in this report is required and will be reviewed by the Division upon receipt and prior to the next compliance inspection of the site. If, while completing this report, you learn that your site is not in compliance with the rules and the act, it is advisable that the issues be rectified promptly to avoid possible enforcement action. 1. Is the site identification sign posted in accordance with Rule 3.1.12(1). * 6 Yes O No 2. Is the affected area boundary clearly marked in accordance with Rule 3.1.12(2). * 6 Yes O No 3. Is the mine site in final reclamation (all material extraction and stockpile removal is complete)? * 1f "YES," please note time limits related to completion of reclamation, Rule 3.1.3. 6 Yes O No 4. Has excavation, processing or hauling activity commenced at the site? * 6 Yes O No What was the date of last excavation, processing or hauling activity at the mine? * 12/31/2015 5. Does the mine operate more than 180 days per year? * 1f "No", please review Rule 1.13 to assure that your mine is in compliance. C Yes O No 6. Has this mine been granted approval of TEMPORARY CESSATION Status? * C Yes O No 7. Has this mine been granted approval for INTERMITTENT OPERATION? *	Permitting Contact	: Email Address	
Administrator will receive an email notification. * 6 Yes O No Annual Report Questions Information contained in this report is required and will be reviewed by the Division upon receipt and prior to the next compliance inspection of the site. If, while completing this report, you learn that your site is not in compliance with the rules and the act, it is advisable that the issues be rectified promptly to avoid possible enforcement action. 1. Is the site identification sign posted in accordance with Rule 3.1.12(1). * 6 Yes O No 2. Is the affected area boundary clearly marked in accordance with Rule 3.1.12(2). * 6 Yes O No 3. Is the mine site in final reclamation (all material extraction and stockpile removal is complete)? * 1f "YES," please note time limits related to completion of reclamation, Rule 3.1.3. 6 Yes O No 4. Has excavation, processing or hauling activity commenced at the site? * 6 Yes O No What was the date of last excavation, processing or hauling activity at the mine? * 12/31/2015 5. Does the mine operate more than 180 days per year? * 1f "No", please review Rule 1.13 to assure that your mine is in compliance. C Yes O No 6. Has this mine been granted approval of TEMPORARY CESSATION Status? * C Yes O No 7. Has this mine been granted approval for INTERMITTENT OPERATION? *			
Annual Report Questions Information contained in this report is required and will be reviewed by the Division upon receipt and prior to the next compliance inspection of the site. If, while completing this report, you learn that your site is not in compliance with the rules and the act, it is advisable that the issues be rectified promptly to avoid possible enforcement action. 1. Is the site identification sign posted in accordance with Rule 3.1.12(1). * © Yes © No 2. Is the affected area boundary clearly marked in accordance with Rule 3.1.12(2). * © Yes © No 3. Is the mine site in final reclamation (all material extraction and stockpile removal is complete)? * If "YES," please note time limits related to completion of reclamation, Rule 3.1.3. © Yes © No 4. Has excavation, processing or hauling activity commenced at the site? * © Yes © No What was the date of last excavation, processing or hauling activity at the mine? * 12/31/2015 5. Does the mine operate more than 180 days per year? * If "NO", please review Rule 1.13 to assure that your mine is in compliance. © Yes © No 6. Has this mine been granted approval of TEMPORARY CESSATION Status? * © Yes © No 7. Has this mine been granted approval for INTERMITTENT OPERATION? *			
Annual Report Questions Information contained in this report is required and will be reviewed by the Division upon receipt and prior to the next compliance inspection of the site. If, while completing this report, you learn that your site is not in compliance with the rules and the act, it is advisable that the issues be rectified promptly to avoid possible enforcement action. 1. Is the site identification sign posted in accordance with Rule 3.1.12(1). * © Yes C No 2. Is the affected area boundary clearly marked in accordance with Rule 3.1.12(2). * © Yes C No 3. Is the mine site in final reclamation (all material extraction and stockpile removal is complete)? * If "YES," please note time limits related to completion of reclamation, Rule 3.1.3. © Yes C No 4. Has excavation, processing or hauling activity commenced at the site? * © Yes C No What was the date of last excavation, processing or hauling activity at the mine? * 12/31/2015 5. Does the mine operate more than 180 days per year? * If "No", please review Rule 1.13 to assure that your mine is in compliance. C Yes © No 6. Has this mine been granted approval of TEMPORARY CESSATION Status? * C Yes © No 7. Has this mine been granted approval for INTERMITTENT OPERATION? *		eceive an email noti	ilication.
Information contained in this report is required and will be reviewed by the Division upon receipt and prior to the next compliance inspection of the site. If, while completing this report, you learn that your site is not in compliance with the rules and the act, it is advisable that the issues be rectified promptly to avoid possible enforcement action. 1. Is the site identification sign posted in accordance with Rule 3.1.12(1). * © Yes C No 2. Is the affected area boundary clearly marked in accordance with Rule 3.1.12(2). * © Yes C No 3. Is the mine site in final reclamation (all material extraction and stockpile removal is complete)? * If "YES," please note time limits related to completion of reclamation, Rule 3.1.3. © Yes C No 4. Has excavation, processing or hauling activity commenced at the site? * © Yes C No What was the date of last excavation, processing or hauling activity at the mine? * 12/31/2015 5. Does the mine operate more than 180 days per year? * If "NO", please review Rule 1.13 to assure that your mine is in compliance. C Yes © No 6. Has this mine been granted approval of TEMPORARY CESSATION Status? * C Yes © No 7. Has this mine been granted approval for INTERMITTENT OPERATION? *			
compliance inspection of the site. If, while completing this report, you learn that your site is not in compliance with the rules and the act, it is advisable that the issues be rectified promptly to avoid possible enforcement action. 1. Is the site identification sign posted in accordance with Rule 3.1.12(1).* C Yes C No 2. Is the affected area boundary clearly marked in accordance with Rule 3.1.12(2).* C Yes C No 3. Is the mine site in final reclamation (all material extraction and stockpile removal is complete)?* If "YES," please note time limits related to completion of reclamation, Rule 3.1.3. C Yes C No 4. Has excavation, processing or hauling activity commenced at the site?* C Yes C No What was the date of last excavation, processing or hauling activity at the mine?* 12/31/2015 5. Does the mine operate more than 180 days per year?* If "No", please review Rule 1.13 to assure that your mine is in compliance. C Yes C No 6. Has this mine been granted approval of TEMPORARY CESSATION Status?* C Yes C No 7. Has this mine been granted approval for INTERMITTENT OPERATION?*	Annual Repo	ort Questions	
C Yes C No 2. Is the affected area boundary clearly marked in accordance with Rule 3.1.12(2). * C Yes C No 3. Is the mine site in final reclamation (all material extraction and stockpile removal is complete)? * If "YES," please note time limits related to completion of reclamation, Rule 3.1.3. C Yes C No 4. Has excavation, processing or hauling activity commenced at the site? * C Yes C No What was the date of last excavation, processing or hauling activity at the mine? * 12/31/2015 5. Does the mine operate more than 180 days per year? * If "NO", please review Rule 1.13 to assure that your mine is in compliance. C Yes C No 6. Has this mine been granted approval of TEMPORARY CESSATION Status? * C Yes C No 7. Has this mine been granted approval for INTERMITTENT OPERATION? *	compliance inspection	of the site. If, while comp	pleting this report, you learn that your site is not in compliance with the rules and
C Yes C No 2. Is the affected area boundary clearly marked in accordance with Rule 3.1.12(2). * C Yes C No 3. Is the mine site in final reclamation (all material extraction and stockpile removal is complete)? * If "YES," please note time limits related to completion of reclamation, Rule 3.1.3. C Yes C No 4. Has excavation, processing or hauling activity commenced at the site? * C Yes C No What was the date of last excavation, processing or hauling activity at the mine? * 12/31/2015 5. Does the mine operate more than 180 days per year? * If "NO", please review Rule 1.13 to assure that your mine is in compliance. C Yes C No 6. Has this mine been granted approval of TEMPORARY CESSATION Status? * C Yes C No 7. Has this mine been granted approval for INTERMITTENT OPERATION? *	1. Is the site identi	ification sign posted i	in accordance with Rule 3.1.12(1). *
© Yes © No 3. Is the mine site in final reclamation (all material extraction and stockpile removal is complete)? * If "YES," please note time limits related to completion of reclamation, Rule 3.1.3. © Yes © No 4. Has excavation, processing or hauling activity commenced at the site? * © Yes © No What was the date of last excavation, processing or hauling activity at the mine? * 12/31/2015 5. Does the mine operate more than 180 days per year? * If "NO", please review Rule 1.13 to assure that your mine is in compliance. © Yes © No 6. Has this mine been granted approval of TEMPORARY CESSATION Status? * © Yes © No 7. Has this mine been granted approval for INTERMITTENT OPERATION? *	• Yes • No		(,
© Yes C No 3. Is the mine site in final reclamation (all material extraction and stockpile removal is complete)? * If "YES," please note time limits related to completion of reclamation, Rule 3.1.3. © Yes C No 4. Has excavation, processing or hauling activity commenced at the site? * © Yes C No What was the date of last excavation, processing or hauling activity at the mine? * 12/31/2015 5. Does the mine operate more than 180 days per year? * If "NO", please review Rule 1.13 to assure that your mine is in compliance. C Yes C No 6. Has this mine been granted approval of TEMPORARY CESSATION Status? * C Yes C No 7. Has this mine been granted approval for INTERMITTENT OPERATION? *	2. Is the affected a	rea boundary clearly	v marked in accordance with Rule 3.1.12(2). *
3. Is the mine site in final reclamation (all material extraction and stockpile removal is complete)? * If "YES," please note time limits related to completion of reclamation, Rule 3.1.3. Yes O No 4. Has excavation, processing or hauling activity commenced at the site? * Yes O No What was the date of last excavation, processing or hauling activity at the mine? * 12/31/2015 5. Does the mine operate more than 180 days per year? * If "NO", please review Rule 1.13 to assure that your mine is in compliance. Yes O No 6. Has this mine been granted approval of TEMPORARY CESSATION Status? * Yes O No 7. Has this mine been granted approval for INTERMITTENT OPERATION? *		ica boardary cicarry	, marked in decordance with rate 512122(2)1
If "YES," please note time limits related to completion of reclamation, Rule 3.1.3. Yes O No 4. Has excavation, processing or hauling activity commenced at the site? * Yes O No What was the date of last excavation, processing or hauling activity at the mine? * 12/31/2015 5. Does the mine operate more than 180 days per year? * If "NO", please review Rule 1.13 to assure that your mine is in compliance. Yes O No 6. Has this mine been granted approval of TEMPORARY CESSATION Status? * O Yes O No 7. Has this mine been granted approval for INTERMITTENT OPERATION? *		in final reclamation ((all material extraction and stacknile removal is complete)2 *
 Yes ○ No 4. Has excavation, processing or hauling activity commenced at the site? * Yes ○ No What was the date of last excavation, processing or hauling activity at the mine? * 12/31/2015 5. Does the mine operate more than 180 days per year? * If "NO", please review Rule 1.13 to assure that your mine is in compliance. ○ Yes ○ No 6. Has this mine been granted approval of TEMPORARY CESSATION Status? * ○ Yes ○ No 7. Has this mine been granted approval for INTERMITTENT OPERATION? * 		_	
 • Yes ○ No What was the date of last excavation, processing or hauling activity at the mine? * 12/31/2015 5. Does the mine operate more than 180 days per year? * If "NO", please review Rule 1.13 to assure that your mine is in compliance. ○ Yes ○ No 6. Has this mine been granted approval of TEMPORARY CESSATION Status? * ○ Yes ○ No 7. Has this mine been granted approval for INTERMITTENT OPERATION? * 	• Yes • No	ne mines related to comple	and of reclamation, Nate 3.1.3.
 • Yes ○ No What was the date of last excavation, processing or hauling activity at the mine? * 12/31/2015 5. Does the mine operate more than 180 days per year? * If "NO", please review Rule 1.13 to assure that your mine is in compliance. ○ Yes ○ No 6. Has this mine been granted approval of TEMPORARY CESSATION Status? * ○ Yes ○ No 7. Has this mine been granted approval for INTERMITTENT OPERATION? * 	4 Has averyation	nua angaina au bauliu	an activity common at the site 2 *
What was the date of last excavation, processing or hauling activity at the mine? * 12/31/2015 5. Does the mine operate more than 180 days per year? * If "NO", please review Rule 1.13 to assure that your mine is in compliance. O Yes O No 6. Has this mine been granted approval of TEMPORARY CESSATION Status? * O Yes O No 7. Has this mine been granted approval for INTERMITTENT OPERATION? *	_	processing or naulin	ig activity commenced at the site? "
12/31/2015 5. Does the mine operate more than 180 days per year? * If "NO", please review Rule 1.13 to assure that your mine is in compliance. ○ Yes No 6. Has this mine been granted approval of TEMPORARY CESSATION Status? * ○ Yes No 7. Has this mine been granted approval for INTERMITTENT OPERATION? *			
5. Does the mine operate more than 180 days per year? * If "NO", please review Rule 1.13 to assure that your mine is in compliance. O Yes O No 6. Has this mine been granted approval of TEMPORARY CESSATION Status? * O Yes O No 7. Has this mine been granted approval for INTERMITTENT OPERATION? *		of last excavation, p	processing or hauling activity at the mine? *
If "NO", please review Rule 1.13 to assure that your mine is in compliance. O Yes O No 6. Has this mine been granted approval of TEMPORARY CESSATION Status? * O Yes O No 7. Has this mine been granted approval for INTERMITTENT OPERATION? *			
 C Yes			
O Yes • No 7. Has this mine been granted approval for INTERMITTENT OPERATION? *	If "NO", please review FO Yes • No	Rule 1.13 to assure that yo	our mine is in compliance.
O Yes • No 7. Has this mine been granted approval for INTERMITTENT OPERATION? *	6 Has this mine he	een granted annroval	Lof TEMPORARY CESSATION Status? *
	O Yes O No	.c., grantea approvai	
	7 Has this mine be	een granted annroyal	I for INTERMITTENT OPERATION? *
	O Yes O No	3. a.i.cea approvai	
For the following questions, please note that numeric values must include one decimal place, such as "0.0" for		lactions places wet- t	that numeric values must include one desired where such as 10.01 fee

8. Number of acres currently affected (mining + incomplete and or unreleased reclamation). * (?) 22.4
9. Number of acres that were newly affected during the current report year * (?) 0.0
10. Number of acres that were reclaimed during the current report year. * (?)0.0
11. Estimated new acreage to be affected in the next report year. * (?) 0.0
12. Estimated acres to be reclaimed in the next report year. * (?)0.0
13. Total acres in various stages of reclamation, since permitted mining activities began:
Total acres backfilled * (?) 9.9
Total acres graded * (?) 22.4
Total acres seeded with approved mix * (?) 22.4
Seed Application Method * Drill seeding
Total acres fertilized with aproved fertilizer * (?) 0.0
Fertilizer Application Method * NA
Total acres with topsoil replaced * (?) 22.4
Topsoil replacement depth (in.) * (?) 4.0
Total acres mulched with approved mulch * (?) 22.4
Mulch application rate (tons/ac) * (?) 1.5
Mulch Application Method * Crimping, with tractor
14. Is weed control being conducted in accordance with an approved Weed Control Plan? ★ If "YES", indicate the weed species, control area, control type, application rate and treatment date on the report map. C Yes C No C N/A
15. Is adequate topsoil reserved for reclamation, based on your approved permit? *

zero acres, or 10.2 instead of 10.23.

C Yes C No O N/A
16. Is the reserved topsoil vegetated/stabilized in accordance with Rule 3.1.9(1)? ★ If "NO", please explain O Yes O No O N/A
17. If mining has exposed groundwater, is the site in compliance with the approved mining plan and Office of the State Engineer (Well Permit, S.W.S.P., and/or Permanent Augmentation Plan)? * ○ Yes ○ No ○ N/A
18. Are all hazardous materials stored within approved spill containment structures? * ○ Yes ○ No ○ N/A
19. Is your financial warranty value sufficient to cover the cost to complete reclamation? ★ ○ Yes ○ No ⊙ N/A
20. Is your basis for legal right to enter still valid? ★ ⊙ Yes O No
21. Does your permit require you to submit monitoring information annually? ★ ○ Yes ○ No ⊙ N/A
22. As required by Colorado Mined Land Reclamation Act and/or Colorado Land Reclamation Act for the Extraction of Construction Materials (C.R.S.34-32-116 or 34-32.5-116), attach a map to this report that accurately depicts the permit boundary, current affected area boundary and location of the acreages specified in items 8-12 and 15. *
Only PDF formatted files can be uploaded.
2018 Ashbaugh Annual Report Map.pdf 2MB
23. If you have supplemental information you would like to provide, please upload it here.
Only PDF formatted files can be uploaded.
24. Rule 5.7 requires submittal of final abandonment reports within 60 days for any drill hole(s) with artesian flows and no later than 12 months for all other completed drill holes. If drill holes are a component of your exploration/prospecting activities, have they been properly abandoned? ○ Yes ○ No ○ NA
Annual Fee Payment
Payment Confirmation Number * (?) 94935084
Signature
Submittal Date 09-12-2018
I, the undersigned, hereby state that the information provided in this report is true and accurate, and that site operations are being conducted in accordance with the Division approved mining and reclamation plans. * I Agree If you do not see the "Submit" button after completing your report, try to un-check and then re-check the "I Agree" box.

If "NO", please explain