

Date: 9-1-18

Int. C. Chess

Field Inspection Report Form

SG/VLF 2/LDS

Squaw Gulch

VLF 2 LVLC -

Totalizer/Gpm 164 8601

Pump 1 7.9

Pump 2 8.2

VLF 2

Squaw Gulch Pump Back - Totalizer/Gpm 115 7737

Pump 1 13.4

Pump 2 13.9

VLF 2 Leak Detection System

		Total Gallons	Sampled	Time	pH	Temp. C	Cond	D.O.	O & G
Water Observed		Comments	Y N	:					
#1	Y (N)		Y (N)	6:30					
#2	Y (N)		Y (N)	6:35					
#3	Y (N)	<u>1/2"</u>	Y (N)	6:40					

Comments: Can #3 does not have enough water to pump or sample.

Date: 9-2-18

Int. C. Chess

Field Inspection Report Form

SG/VLF 2/LDS

Squaw Gulch

VLF 2 LVLC -

Totalizer/Gpm 1652682

Pump 1 10.4

Pump 2 11.0

VLF 2

Squaw Gulch Pump Back - Totalizer/Gpm 1157737

Pump 1 13.4

Pump 2 13.9

VLF 2 Leak Detection System

		Total Gallons	Sampled	Time	pH	Temp. C	Cond	D.O.	O & G
Water Observed		Comments	Y N	:					
#1	Y ☒ N		Y N	<u>7:00</u>					
#2	Y ☒ N		Y N	<u>7:05</u>					
#3	Y ☒ N	<u>1/2" water</u>	Y N	<u>7:10</u>					

Comments:

Int. 2K

Squaw Gulch

Totalizer/Gpm 1657504
Pump 1 6.2
Pump 2 6.3

Squaw Gulch Pump Back - Totalizer/Gpm 1157737/0 gpm
Pump 1 13.4
Pump 2 13.7

			Total Gallons	Sampled	Time	pH	Temp. C	Cond	D.O.	O & G
Water Observed	Comments			Y N	:					
#1	Y			Y N	:					
#2	Y			Y N	:					
#3	Y			Y N	:					

Comments:

Date: 09-07-18

Int. R

Field Inspection Report Form

SG/VLF 2/LDS

Squaw Gulch

VLF 2 LVLC -

Totalizer/Gpm 1660978
Pump 1 7.6
Pump 2 8.0

VLF 2

Squaw Gulch Pump Back - Totalizer/Gpm 1152237 10gpm
Pump 1 13.4
Pump 2 13.7

VLF 2 Leak Detection System

		Total Gallons	Sampled		Time	pH	Temp. C	Cond	D.O.	O & G
Water Observed		Comments	Y	N	:					
#1	Y (N)		Y	(N)	6 : 30					
#2	Y (N)		Y	(N)	6 : 35					
#3	Y (N)		Y	(N)	6 : 45					

Comments:

**Field Inspection Report Form
SG/VLF 2/LDS**

Date: 9/5/18

Int. Cody J.

Squaw Gulch

VLF 2 LVLC -

Totalizer/Gpm 1665054

Pump 1 9.6

Pump 2 9.7

VLF 2

Squaw Gulch Pump Back -

Totalizer/Gpm 1157737/0

Pump 1 13.7

Pump 2 13.4

VLF 2 Leak Detection System

	Water Observed	Comments	Total Gallons	Sampled	Time	pH	Temp. C	Cond	D.O.	O & G
				Y N	:					
#1	Y <u>N</u>			Y N	<u>6:55</u>					
#2	Y <u>N</u>			Y N	<u>6:58</u>					
#3	Y <u>N</u>			Y N	<u>7:05</u>					

Comments:

Date: 9/6/18
Int. FA

Field Inspection Report Form
SG/VLF 2/LDS

Squaw Gulch

VLF 2 LVLC -

Totalizer/Gpm 1669123
Pump 1 9.9
Pump 2 10.2

VLF 2

Squaw Gulch Pump Back - Totalizer/Gpm 1157737/0
Pump 1 13.5
Pump 2 13.6

VLF 2 Leak Detection System

Water Observed		Comments	Total Gallons	Sampled	Time	pH	Temp. C	Cond	D.O.	O & G
				Y N	:					
#1	Y	<u>(N)</u>		Y <u>(N)</u>	<u>9:00</u>					
#2	Y	<u>(N)</u>		Y <u>(N)</u>	<u>9:05</u>					
#3	Y	<u>(N)</u>		Y <u>(N)</u>	<u>9:15</u>					

Comments:

Date: 9/7/18

Int. DE

Field Inspection Report Form
SG/VLF 2/LDS

Squaw Gulch

VLF 2 LVLC -
6:37 AM

Totalizer/Gpm 1673192/0 Gpm
Pump 1 11.3
Pump 2 11.6

VLF 2

Squaw Gulch Pump Back -

7:18 AM

Totalizer/Gpm 1157737/0 Gpm
Pump 1 13.4
Pump 2 13.7

VLF 2 Leak Detection System

		Total Gallons	Sampled	Time	pH	Temp. C	Cond	D.O.	O & G
Water Observed									
Comments									
#1	Y ☒ N ☐	N/A	Y ☒ N ☐	<u>6:30 AM</u>	N/A	N/A	N/A	N/A	N/A
#2	Y ☒ N ☐	N/A	Y ☒ N ☐	<u>6:35 AM</u>	N/A	N/A	N/A	N/A	N/A
#3	☒ Y ☐ N	N/A	Y ☒ N ☐	<u>6:40 AM</u>	N/A	N/A	N/A	N/A	N/A

Comments: #3 Can Unmeasurable Amount

Date: 9/8/18
Int. DE/EF

Field Inspection Report Form
SG/VLF 2/LDS

Squaw Gulch

VLF 2 LVLC -
6:43 AM

Totalizer/Gpm 1677477/0 GPM
Pump 1 8.3
Pump 2 8.6

VLF 2

Squaw Gulch Pump Back -

6:57 am

Totalizer/Gpm 157737
Pump 1 13.4
Pump 2 13.7

VLF 2 Leak Detection System

		Total Gallons	Sampled	Time	pH	Temp. C	Cond	D.O.	O & G
Water Observed									
			Y (N)		N/A	N/A	N/A	N/A	N/A
#1	Y (N)	Dry	N/A	Y (N)	6:30 AM	N/A	N/A	N/A	N/A
#2	Y (N)	Dry	N/A	Y (N)	6:30 AM	N/A	N/A	N/A	N/A
#3	(Y) N	Damp	N/A	Y (N)	6:37 AM	N/A	N/A	N/A	N/A

Comments: #3 Can Has A Unmeasurable Amount

Date: 9-9-18

Int. 87

Field Inspection Report Form
SG/VLF 2/LDS

Squaw Gulch

VLF 2 LVLC -

Totalizer/Gpm 1681792

Pump 1 10.8-

Pump 2 11.0-

VLF 2

Squaw Gulch Pump Back -

Totalizer/Gpm 1157737

Pump 1 13.3

Pump 2 13.7

6:39am

7:34am

VLF 2 Leak Detection System

		Total Gallons	Sampled	Time	pH	Temp. C	Cond	D.O.	O & G
Water Observed									
		NO	Y (N)	:	N/a	N/a	N/a	N/a	N/a
#1	Y (N)	NO	Y (N)	6:27am	N/a	N/a	N/a	N/a	N/a
#2	Y (N)	NO	Y (N)	6:54am	N/a	N/a	N/a	N/a	N/a
#3	(Y) N	NO	Y (N)	7:13am	N/a	N/a	N/a	N/a	N/a
Not measurable									

Comments:

Date: 9-10-18

Int. BP

Field Inspection Report Form
SG/VLF 2/LDS

Squaw Gulch

VLF 2 LVLC -

Totalizer/Gpm 1686156.0 gpm
Pump 1 11.5
Pump 2 11.8

VLF 2

Squaw Gulch Pump Back -

Totalizer/Gpm 1157737.0 gpm
Pump 1 13.4
Pump 2 13.7

VLF 2 Leak Detection System

Water Observed		Comments	Total Gallons	Sampled	Time	pH	Temp. C	Cond	D.O.	O & G
#1	Y <u>(M)</u>			Y <u>(N)</u>	7 : 00					
#2	Y <u>(N)</u>			Y <u>(N)</u>	7 : 05					
#3	<u>(Y)</u> N			Y <u>(N)</u>	7 : 10					

Comments: LDS#3 has 1" of solution not enough to pump out.

Date: 9-11-18

Int. BP

Field Inspection Report Form
SG/VLF 2/LDS

Squaw Gulch

VLF 2 LVLC -

Totalizer/Gpm 1691055-0 gpm
Pump 1 13.2
Pump 2 13.5

VLF 2

Squaw Gulch Pump Back - Totalizer/Gpm 1157737-0 gpm
Pump 1 13.4
Pump 2 13.7

VLF 2 Leak Detection System

		Total Gallons	Sampled	Time	pH	Temp. C	Cond	D.O.	O & G
Water Observed		Comments	Y N	:					
#1	Y ☒ N		Y ☒ N	10 : 30					
#2	Y ☒ N		Y ☒ N	10 : 35					
#3	☒ Y N	one inch water	Y ☒ N	10 : 40					

Comments: LDS#3 has one inch of water not enough to pump out

Date: 9-12-18

Int. BP

Field Inspection Report Form

SG/VLF 2/LDS

Squaw Gulch

VLF 2 LVLC -

Totalizer/Gpm 1694973-0gpm

Pump 1 11.5

Pump 2 11.6

VLF 2

Squaw Gulch Pump Back - Totalizer/Gpm 1157732-0gpm

Pump 1 13.4

Pump 2 13.7

VLF 2 Leak Detection System

		Total Gallons	Sampled		Time	pH	Temp. C	Cond	D.O.	O & G
Water Observed		Comments		Y	N	:				
#1	Y	17		Y	17	7 : 30				
#2	Y	17		Y	17	7 : 35				
#3	17	N	one inch	Y	17	7 : 40				

Comments: LOS#3 has one inch of water not enough to pump out.

Date: 9-13-18

Int. C. Chess

Field Inspection Report Form

SG/VLF 2/LDS

Squaw Gulch

VLF 2 LVLC -

Totalizer/Gpm 1699294

Pump 1 10.2

Pump 2 10.5

VLF 2

Squaw Gulch Pump Back - Totalizer/Gpm 1157737

Pump 1 13.4

Pump 2 13.7

VLF 2 Leak Detection System

		Total Gallons	Sampled	Time	pH	Temp. C	Cond	D.O.	O & G
Water Observed		Comments	Y N	:					
#1	Y <u>(N)</u>		Y N	<u>7:45</u>					
#2	Y <u>(N)</u>		Y N	<u>7:50</u>					
#3	Y <u>(N)</u>		Y N	<u>7:55</u>					

Comments:

Date: 9-14-18

Int. ZS

Field Inspection Report Form
SG/VLF 2/LDS

Squaw Gulch

VLF 2 LVLC -

Totalizer/Gpm 1703622

Pump 1 10.0

Pump 2 10.3

VLF 2

Squaw Gulch Pump Back - Totalizer/Gpm 1157737

Pump 1 13.4

Pump 2 13.7

VLF 2 Leak Detection System

Water Observed		Comments	Total Gallons	Sampled	Time	pH	Temp. C	Cond	D.O.	O & G
				Y N	:					
#1	Y	(N)		Y	8:13					
#2	Y	(N)		Y	8:17					
#3	Y	(N)		Y	8:25					

Comments:

Date: 9-15-18

Int. ZC

Field Inspection Report Form

SG/VLF 2/LDS

Squaw Gulch

VLF 2 LVLC -

Totalizer/Gpm

1708543/18

Pump 1 11.9

Pump 2 12.3

VLF 2

Squaw Gulch Pump Back -

Totalizer/Gpm

1157737/0

Pump 1 13.4

Pump 2 13.7

VLF 2 Leak Detection System

		Total Gallons	Sampled		Time	pH	Temp. C	Cond	D.O.	O & G
Water Observed		Comments	Y	N	:					
#1	Y	Ⓢ	Y	Ⓢ	10:25					
#2	Y	Ⓢ	Y	Ⓢ	10:29					
#3	Ⓢ	N	Y	Ⓢ	10:42					

Comments: Water observed in LBS can #3 not enough to sample

Date: 9-16-18
Int. 2c

Field Inspection Report Form
SG/VLF 2/LDS

Squaw Gulch

VLF 2 LVLC -

Totalizer/Gpm 1713133 / 18
Pump 1 8.9
Pump 2 9.3

VLF 2

Squaw Gulch Pump Back -

Totalizer/Gpm 1157737 / 0
Pump 1 13.4
Pump 2 13.7

VLF 2 Leak Detection System

Water Observed		Comments	Total Gallons	Sampled	Time	pH	Temp. C	Cond	D.O.	O & G
				Y N	:					
#1	Y	Ⓢ		Y	11:02					
#2	Y	Ⓢ		Y	11:06					
#3	Ⓢ	N		Y	11:14					

Comments: water observed in LDS can #3 not enough to sample

Field Inspection Report Form

SG/VLF 2/LDS

Date: 17 SEPT 2018

Int. JOHNSON

Squaw Gulch

0710

VLF 2 LVLC -

Totalizer/Gpm 0643
1716807/0

Pump 1 9.1

Pump 2 9.5

VLF 2

Squaw Gulch Pump Back - Totalizer/Gpm 1157737/0

Pump 1 13.4

Pump 2 13.7

VLF 2 Leak Detection System

				Total Gallons	Sampled	Time	pH	Temp. C	Cond	D.O.	O & G
Water Observed		Comments			Y N	:					
#1	Y	(N)	N/A	0	Y (N)	06 : 57	N/A	N/A	N/A	N/A	N/A
#2	Y	(N)	N/A	0	Y (N)	06 : 41	N/A	N/A	N/A	N/A	N/A
#3	(Y)	N	NOT ENOUGH TO	1-2"	Y (N)	06 : 51	N/A	N/A	N/A	N/A	N/A

Comments:

SAMPLE

Date: 18 SEPT 2018

Int. JOHNSON

Field Inspection Report Form
SG/VLF 2/LDS

Squaw Gulch

VLF 2 LVLC -

0639
Totalizer/Gpm 1721150/0

Pump 1 13.2

Pump 2 13.3

VLF 2

Squaw Gulch Pump Back -

0721
Totalizer/Gpm 1157737/0

Pump 1 13.4

Pump 2 13.7

VLF 2 Leak Detection System

		Total Gallons	Sampled		Time	pH	Temp. C	Cond	D.O.	O & G
Water Observed		Comments	Y	N	:					
#1	Y ☒		N/A	☒	07 : 34	N/A	N/A	N/A	N/A	N/A
#2	Y ☒		N/A	☒	06 : 35	N/A	N/A	N/A	N/A	N/A
#3	☒ N	NOT ENOUGH	1-2"	☒	06 : 45	N/A	N/A	N/A	N/A	N/A

Comments:

Date: 9-19-18
Int. ES

Field Inspection Report Form
SG/VLF 2/LDS

Squaw Gulch

VLF 2 LVLC -

Totalizer/Gpm 725884

Pump 1 7.2

Pump 2 7.6

VLF 2

Squaw Gulch Pump Back -

Totalizer/Gpm 1157737

Pump 1 13.4

Pump 2 13.7

7:13 am

6:56 am

VLF 2 Leak Detection System

		Total Gallons	Sampled		Time	pH	Temp. C	Cond	D.O.	O & G
Water Observed		Comments	Y	N						
#1	Y <u>N</u>		Y	<u>N</u>	<u>7:09 am</u>	<u>N/A</u>	<u>N/A</u>	<u>N/A</u>	<u>N/A</u>	<u>N/A</u>
#2	Y <u>N</u>		Y	<u>N</u>	<u>7:07 am</u>	<u>N/A</u>	<u>N/A</u>	<u>N/A</u>	<u>N/A</u>	<u>N/A</u>
#3	<u>Y</u> N	<u>NOT measurable</u>	Y	<u>N</u>	<u>7:18 am</u>	<u>N/A</u>	<u>N/A</u>	<u>N/A</u>	<u>N/A</u>	<u>N/A</u>

Comments:

Date: 9/20/18

Int. DE

Field Inspection Report Form

SG/VLF 2/LDS

Squaw Gulch

VLF 2 LVLC -

7:23 AM

Totalizer/Gpm 1730424/0 GPM

Pump 1 8.9

Pump 2 9.3

VLF 2

Squaw Gulch Pump Back -

7:28 AM

Totalizer/Gpm 1157737/0 GPM

Pump 1 13.4

Pump 2 13.7

VLF 2 Leak Detection System

Water Observed		Comments	Total Gallons	Sampled	Time	pH	Temp. C	Cond	D.O.	O & G
			<u>N/A</u>	Y <u>(N)</u>	<u>7:16 AM</u>	<u>N/A</u>	<u>N/A</u>	<u>N/A</u>	<u>N/A</u>	<u>N/A</u>
#1	Y <u>(N)</u>	<u>Dry</u>	<u>N/A</u>	Y <u>(N)</u>	<u>7:16 AM</u>	<u>N/A</u>	<u>N/A</u>	<u>N/A</u>	<u>N/A</u>	<u>N/A</u>
#2	Y <u>(N)</u>	<u>Dry</u>	<u>N/A</u>	Y <u>(N)</u>	<u>7:30 AM</u>	<u>N/A</u>	<u>N/A</u>	<u>N/A</u>	<u>N/A</u>	<u>N/A</u>
#3	<u>(Y)</u> N	<u>Damp</u>	<u>N/A</u>	Y <u>(N)</u>	<u>7:30 AM</u>	<u>N/A</u>	<u>N/A</u>	<u>N/A</u>	<u>N/A</u>	<u>N/A</u>

Comments: #3 Can Has A Unmeasurable Amount

Date: 9/21/18

Int. Cody Jannette

Field Inspection Report Form
SG/VLF 2/LDS

Squaw Gulch

VLF 2 LVLC -

Totalizer/Gpm 17 3 47 44 / 0

Pump 1 11.3

Pump 2 11.4

VLF 2

Squaw Gulch Pump Back - Totalizer/Gpm 11 577 37

Pump 1 13.4

Pump 2 13.7

VLF 2 Leak Detection System

Water Observed		Comments	Total Gallons	Sampled	Time	pH	Temp. C	Cond	D.O.	O & G
				Y N	:					
#1	Y	(N)		Y N	6 : 30					
#2	Y	(N)		Y N	6 : 38					
#3	Y	(N)		Y N	6 : 47					

Comments:

Date: 9/22/18

Int. PA

Field Inspection Report Form

SG/VLF 2/LDS

Squaw Gulch

VLF 2 LVLC -

Totalizer/Gpm 1736258

Pump 1 11.2

Pump 2 11.3

VLF 2

Squaw Gulch Pump Back -

Totalizer/Gpm 1157737

Pump 1 13.4

Pump 2 13.7

VLF 2 Leak Detection System

Water Observed		Comments	Total Gallons	Sampled	Time	pH	Temp. C	Cond	D.O.	O & G
				Y N	:					
#1	Y	(N)		Y (N)	9:00					
#2	Y	(N)		Y (N)	9:05					
#3	Y	(N)		Y (N)	9:10					

Comments:

Date: 9/23/18

Int. Cody Jannetti

Field Inspection Report Form
SG/VLF 2/LDS

Squaw Gulch

VLF 2 LVLC -

Totalizer/Gpm 1743553 / 0

Pump 1 10.2

Pump 2 10.3

VLF 2

Squaw Gulch Pump Back - Totalizer/Gpm 1157737 / 0

Pump 1 13.4

Pump 2 13.7

VLF 2 Leak Detection System

Water Observed		Comments	Total Gallons	Sampled	Time	pH	Temp. C	Cond	D.O.	O & G
				Y N	:					
#1	Y	(N)		Y N	6 : 50					
#2	Y	(N)		Y N	6 : 56					
#3	Y	(N)		Y N	7 : 02					

Comments:

Date: 9-24-2018

Int. Zach Stanley

Field Inspection Report Form

SG/VLF 2/LDS

Squaw Gulch

VLF 2 LVLC -

Totalizer/Gpm 1748092

Pump 1 9.3

Pump 2 9.5

VLF 2

Squaw Gulch Pump Back - Totalizer/Gpm 1157737

Pump 1 13.4

Pump 2 13.5

VLF 2 Leak Detection System

		Total Gallons	Sampled		Time	pH	Temp. C	Cond	D.O.	O & G
Water Observed		Comments	Y	N	:					
#1	Y (N)		Y	(N)	6 : 15					
#2	Y (N)		Y	(N)	6 : 20					
#3	(Y) N	1" in the bottom	Y	(N)	6 : 27					

Comments: water observed in LDS can #3 not enough to sample

Date: 9-25-2018

Int. Zach Stanley

Field Inspection Report Form
SG/VLF 2/LDS

Squaw Gulch

VLF 2 LVLC -

Totalizer/Gpm 1753212

Pump 1 11.3

Pump 2 11.4

VLF 2

Squaw Gulch Pump Back - Totalizer/Gpm 1157737/0

Pump 1 13.2

Pump 2 13.5

VLF 2 Leak Detection System

		Total Gallons	Sampled		Time	pH	Temp. C	Cond	D.O.	O & G
Water Observed		Comments	Y	N	:					
#1	Y (N)		Y	(N)	10:15					
#2	Y (N)		Y	(N)	10:20					
#3	(Y) N	1" in the bottom	Y	(N)	10:32					

Comments: water observed in LDS #3 can not enough to sample

Date: 9-26-18

Int. DN

Field Inspection Report Form
SG/VLF 2/LDS

Squaw Gulch

VLF 2 LVLC -

Totalizer/Gpm 1756935-0
Pump 1 7.4
Pump 2 7.8

VLF 2

Squaw Gulch Pump Back - Totalizer/Gpm 1157737-0
Pump 1 13.2
Pump 2 13.5

VLF 2 Leak Detection System

Water Observed		Comments	Total Gallons	Sampled		Time	pH	Temp. C	Cond	D.O.	O & G
				Y	N	:					
#1	Y	(N)		Y	(N)	6:35					
#2	Y	(N)		Y	(N)	6:40					
#3	Y	(N)		Y	(N)	7:00					

Comments:

Date: 9-27-18

Int. IN

Field Inspection Report Form

SG/VLF 2/LDS

Squaw Gulch

VLF 2 LVLC -

Totalizer/Gpm 1761442 - 0

Pump 1 11.7

Pump 2 12.0

VLF 2

Squaw Gulch Pump Back - Totalizer/Gpm 1157737 - 0

Pump 1 13.2

Pump 2 13.5

VLF 2 Leak Detection System

Water Observed			Total Gallons		Sampled		Time	pH	Temp. C	Cond	D.O.	O & G
					Y	N	8:22					
#1	Y	(N)			Y	(N)	8:14					
#2	Y	(N)			Y	(N)	8:21					
#3	Y	(N)			Y	(N)	8:35					

Comments:

Date: 9-28-18

Int. BP

Field Inspection Report Form

SG/VLF 2/LDS

Squaw Gulch

VLF 2 LVLC -

Totalizer/Gpm 1765594-0gpm

Pump 1 12.3

Pump 2 12.5

VLF 2

Squaw Gulch Pump Back - Totalizer/Gpm 1157737-0gpm

Pump 1 13.2

Pump 2 13.5

VLF 2 Leak Detection System

		Total Gallons	Sampled		Time	pH	Temp. C	Cond	D.O.	O & G
Water Observed		Comments	Y	N	:					
#1	Y <u>(N)</u>		Y	<u>(N)</u>	<u>6:45</u>					
#2	Y <u>(N)</u>		Y	<u>(N)</u>	<u>6:50</u>					
#3	Y <u>(N)</u>		Y	<u>(N)</u>	<u>6:55</u>					

Comments:

Date: 9-29-18

Int. C. Chess

Field Inspection Report Form
SG/VLF 2/LDS

Squaw Gulch

VLF 2 LVLC -

Totalizer/Gpm 176 9900
Pump 1 13.0
Pump 2 13.1

VLF 2

Squaw Gulch Pump Back -

Totalizer/Gpm 115 7737
Pump 1 13.2
Pump 2 13.5

VLF 2 Leak Detection System

		Total Gallons	Sampled		Time	pH	Temp. C	Cond	D.O.	O & G
Water Observed		Comments	Y	N	:					
#1	Y (N)		Y	N	6 : 35					
#2	Y (N)		Y	N	6 : 40					
#3	Y (N)		Y	N	6 : 45					

Comments:

Date: 9-30-18

Int. C. Chess

Field Inspection Report Form
SG/VLF 2/LDS

Squaw Gulch

VLF 2 LVLC -

Totalizer/Gpm 1774415
Pump 1 8.7
Pump 2 8.8

VLF 2

Squaw Gulch Pump Back - Totalizer/Gpm 1157737
Pump 1 13.2
Pump 2 13.5

VLF 2 Leak Detection System

		Total Gallons	Sampled		Time	pH	Temp. C	Cond	D.O.	O & G
Water Observed		Comments	Y	N	:					
#1	Y <u>(N)</u>		Y	N	<u>7:00</u>					
#2	Y <u>(N)</u>		Y	N	<u>7:05</u>					
#3	Y <u>(N)</u>		Y	N	<u>7:10</u>					

Comments:



STATE OF
COLORADO

Cazier - DNR, Tim <tim.cazier@state.co.us>

September LDS inspection Forms

1 message

Justin Bills <Justin.Bills@newmont.com>
To: "Cazier - DNR, Tim" <tim.cazier@state.co.us>

Wed, Oct 3, 2018 at 8:52 AM

Tim,

Attached please find September's LDS daily inspection forms.

Thank you,



Justin Bills

Senior Environmental Specialist

Cripple Creek and Victor Gold Mining Co.

T 719.689.4046

M 719.306.3388

www.newmont.com

Newmont Mining Corporation

Cripple Creek and Victor Gold Mining Co.

100 North 3rd Street

Victor, CO 80860

Please consider the environment before printing this e-mail.



September_LDS1.pdf
1702K