

JRS Mining LLC - Sullivan Aggregate Pit
49001 Hwy 9 Fair play co. 80440 Permit # M 2015-017

RECEIVED

OCT 17 2017

DIVISION OF RECLAMATION
MINING AND SAFETY

Access Road completed



River crossing has been completed
Waterline has been buried under river

* - mined area

All tailings have been removed
area has been graded and ready for top soil.