

Pinon Ridge Mining LLC
PO Box 825
31161 Highway 90
Nucla, CO. 81424

October 17, 2018

Colorado Division of Reclamation
Mining and Safety
1313 Sherman St. Room 215
Denver, CO 80203

Sunday Mine – Permit No. M-1977-285

In reference to my letter on August 1, 2018, the surface waste rock pile was characterized at the Sunday Mine. This project was performed and completed on October 12, 2018. A XRF hand held unit was used. The concerned area consisted of 40 x 40 ft. blocks, taking five different samples in each of those blocks to get an average of the value of grade.

I have provided the average samples on the attached map. I believe the averages on the surface of the waste pile to be very low grade.

If you have any questions, please feel free to contact me.



Mike Rutter
Vice President, Operations

