Minerals Reclamation Permit Annual Report



Disclaimer

Under the terms of your NOI or Reclamation Permit and Colorado Statutes, you must submit Annual Fees and Annual Reports (including a map). You must pay the Annual Fee and submit an Annual Report each year until reclamation responsibility release is granted. The Annual Fee is not a renewal fee. The Fee and Report are for LAST YEAR'S mining and reclamation season, and MUST be paid even if your operation was inactive.

If you have requested reclamation responsibility release from the Division of Reclamation, Mining and Safety ("Division") but your permit is not released by the anniversary date listed below, the Annual Fee MUST be paid. If the permit is released before the anniversary date, then by Statute, it is not necessary to pay an Annual Fee or submit an Annual Report for that year.

Division records indicate the following is due:

Select Permit Number *

Only Permit Numbers with currently due Annual Fees will be listed. If the Permit Number is not listed, then the Annual Fees are not due, the Permit Number has already been submitted, or the Permit Number Annual Fee payment has been processed.

M2003058

Select Anniversary Date *

12-04-2018

PLEASE REMEMBER TO CLICK "SUBMIT" AFTER YOU HAVE COMPLETED YOUR REPORT AND PAYMENT.

Please check the box indicating you have read and understand the terms of the Annual Report and Annual Fee $^{\mbox{*}}$

▼ I understand and agree to the terms

General Information

Permittee Name

Glenn E Sessions & Sons, Inc.

Operation Name

Fairbanks Pit

Permit Number	Fee Due	Permit Acreage
---------------	---------	----------------

M2003058 791.00 19.06

County Anniversary Date Current Bond Amount

Jackson 12-04-2018 25420.00

Permittee Contact Information

Permitting Contact Name

Jaime Sessions

Glenn E Sessions & Sons, Inc. Address 1 33492 Hwy 125 Address 2 P.O. Box 1076 City State Zip Code Walden CO 804800000 Phone # Fax # 9707234944 9707238344 Permitting Contact Email Address jaime_sessions@yahoo.com Is the Permitting Contact information listed above correct? If it is not correct your organization's Administrator will receive an email notification. * 6 Yes C No Annual Report Questions Information contained in this report is required and will be reviewed by the Division upon receipt and prior to the next compliance inspection of the site. If, while completing this report, you learn that your site is not in compliance with the rules and the act, it is advisable that the issues be rectified promptly to avoid possible enforcement action. 1. Is the site identification sign posted in accordance with Rule 3.1.12(1). * 6 Yes C No 2. Is the affected area boundary clearly marked in accordance with Rule 3.1.12(2). * 6 Yes C No 3. Is the mine site in final reclamation (all material extraction and stockpile removal is complete)? * If YES,* please note time limits related to completion of reclamation, Rule 3.1.3. C Yes C No 5. Does the mine operate more than 180 days per year? * If YOF, please review Rule 1.13 to assure that your mine is in compliance. G Yes C No 5. Does the mine operate more than 180 days per year? * If YOF, please review Rule 1.13 to assure that your mine is in compliance. G Yes C No 6. Has this mine been granted approval of TEMPORARY CESSATION Status? *					
Address 1 33492 Hwy 125 Address 2 P.O. Box 1076 City State Zip Code Walden CO 804800000 Phone # Fax # 970723844 9707238344 Permitting Contact Email Address jaime_sessions@yahoo.com Is the Permitting Contact information listed above correct? If it is not correct your organization's Administrator will receive an email notification. * 6 Yes C No Annual Report Questions Information contained in this report is required and will be reviewed by the Division upon receipt and prior to the next compliance inspection of the site. If, while completing this report, you learn that your site is not in compliance with the rules and the act, it is advisable that the issues be rectified promptly to avoid possible enforcement action. 1. Is the site identification sign posted in accordance with Rule 3.1.12(1). * 6 Yes C No 2. Is the affected area boundary clearly marked in accordance with Rule 3.1.12(2). * 6 Yes C No 3. Is the mine site in final reclamation (all material extraction and stockpile removal is complete)? * If "YES," please note time limits related to completion of reclamation, Rule 3.1.3. C Yes C No 5. Does the mine operate more than 180 days per year? * If "NO", please review Rule 1.13 to assure that your mine is in compliance. 6 Yes C No 6. Has this mine been granted approval of TEMPORARY CESSATION Status? * C Yes C No 6. Has this mine been granted approval of TEMPORARY CESSATION Status? *	Company				
Address 2 P.O. Box 1076 City State Zip Code Walden CO 804800000 Phone # Fax # 9707234944 9707238344 Permitting Contact Email Address jaime_sessions@yahoo.com Us the Permitting Contact information listed above correct? If it is not correct your organization's Administrator will receive an email notification. * G Yes C No Annual Report Questions Information contained in this report is required and will be reviewed by the Division upon receipt and prior to the next compliance inspection of the site. If, while completing this report, you learn that your site is not in compliance with the rules and the act, it is advisable that the issues be rectified promptly to avoid possible enforcement action. 1. Is the site identification sign posted in accordance with Rule 3.1.12(1). * G Yes C No 2. Is the affected area boundary clearly marked in accordance with Rule 3.1.12(2). * G Yes C No 3. Is the mine site in final reclamation (all material extraction and stockpile removal is complete)? * If Yes, *please note time limits related to completion of reclamation, Rule 3.1.3. C Yes C No 5. Does the mine operate more than 180 days per year? * If Yor, *please review Rule 1.13 to assure that your mine is in compliance. G Yes C No 6. Has this mine been granted approval of TEMPORARY CESSATION Status? * C Yes G No	Glenn E Sessions &	Sons, Inc.			
Address 2 P.O. Box 1076 City State Zip Code Walden CO 804800000 Phone # Fax # 9707234944 9707238344 Permitting Contact Email Address jaime_sessions@yahoo.com Is the Permitting Contact information listed above correct? If it is not correct your organization's Administrator will receive an email notification. * © Yes C No Annual Report Questions Information contained in this report is required and will be reviewed by the Division upon receipt and prior to the next compliance inspection of the site. If, while completing this report, you learn that your site is not in compliance with the rules an the act, it is advisable that the issues be rectified promptly to avoid possible enforcement action. 1. Is the site identification sign posted in accordance with Rule 3.1.12(1). * © Yes C No 2. Is the affected area boundary clearly marked in accordance with Rule 3.1.12(2). * © Yes C No 3. Is the mine site in final reclamation (all material extraction and stockpile removal is complete)? * If "Yes," please note time limits related to completion of reclamation, Rule 3.1.3. C Yes C No 4. Has excavation, processing or hauling activity commenced at the site? * C Yes C No 5. Does the mine operate more than 180 days per year? * If "No", please review Rule 1.13 to assure that your mine is in compliance. © Yes C No 6. Has this mine been granted approval of TEMPORARY CESSATION Status? * C Yes C No	Address 1				
P.O. Box 1076 City State Zip Code Walden CO 804800000 Phone # Fax # 9707234944 9707238344 Permitting Contact Email Address jaime_sessions@yahoo.com Is the Permitting Contact information listed above correct? If it is not correct your organization's Administrator will receive an email notification. * 6 Yes C No Annual Report Questions Information contained in this report is required and will be reviewed by the Division upon receipt and prior to the next compliance inspection of the site. If, while completing this report, you learn that your site is not in compliance with the rules an the act, it is advisable that the issues be rectified promptly to avoid possible enforcement action. 1. Is the site identification sign posted in accordance with Rule 3.1.12(1). * 6 Yes C No 2. Is the affected area boundary clearly marked in accordance with Rule 3.1.12(2). * 6 Yes C No 3. Is the mine site in final reclamation (all material extraction and stockpile removal is complete)? * If "YES," please note time limits related to completion of reclamation, Rule 3.1.3. C Yes C No 4. Has excavation, processing or hauling activity commenced at the site? * C Yes C No 5. Does the mine operate more than 180 days per year? * If "NOT, please review Rule 1.13 to assure that your mine is in compliance. 6 Yes C No 6. Has this mine been granted approval of TEMPORARY CESSATION Status? * C Yes C No	33492 Hwy 125				
City State Zip Code Walden CO 804800000 Phone # Fax # 9707234944 9707238344 Permitting Contact Email Address jaime_sessions@yahoo.com Is the Permitting Contact information listed above correct? If it is not correct your organization's Administrator will receive an email notification. * © Yes C No Annual Report Questions Information contained in this report is required and will be reviewed by the Division upon receipt and prior to the next compliance inspection of the site. If, while completing this report, you karm that your site is not in compliance with the rules an the act, it is advisable that the issues be rectified promptly to avoid possible enforcement action. 1. Is the site identification sign posted in accordance with Rule 3.1.12(1). * © Yes C No 2. Is the affected area boundary clearly marked in accordance with Rule 3.1.12(2). * © Yes C No 3. Is the mine site in final reclamation (all material extraction and stockpile removal is complete)? * If "YES," please note time limits related to completion of reclamation, Rule 3.1.3. C Yes C No 4. Has excavation, processing or hauling activity commenced at the site? * C Yes C No 5. Does the mine operate more than 180 days per year? * If "NO", please review Rule 1.13 to assure that your mine is in compliance. © Yes C No 6. Has this mine been granted approval of TEMPORARY CESSATION Status? * C Yes C No	Address 2				
Phone # Fax # 9707234944 9707238344 Permitting Contact Email Address jaime_sessions@yahoo.com Is the Permitting Contact information listed above correct? If it is not correct your organization's Administrator will receive an email notification. * 6 Yes C No Annual Report Questions Information contained in this report is required and will be reviewed by the Division upon receipt and prior to the next compliance inspection of the site. If, while completing this report, you learn that your site is not in compliance with the rules an the act, it is advisable that the issues be rectified promptly to avoid possible enforcement action. 1. Is the site identification sign posted in accordance with Rule 3.1.12(1). * 6 Yes C No 2. Is the affected area boundary clearly marked in accordance with Rule 3.1.12(2). * 6 Yes C No 3. Is the mine site in final reclamation (all material extraction and stockpile removal is complete)? * If "YES," please note time limits related to completion of reclamation, Rule 3.1.3. C Yes C No 4. Has excavation, processing or hauling activity commenced at the site? * C Yes C No 5. Does the mine operate more than 180 days per year? * If "No", please review Rule 1.13 to assure that your mine is in compliance. 6 Yes C No 6. Has this mine been granted approval of TEMPORARY CESSATION Status? * C Yes C No	P.O. Box 1076				
Phone # Fax # 9707234944 9707238344 Permitting Contact Email Address jaime_sessions@yahoo.com Is the Permitting Contact information listed above correct? If it is not correct your organization's Administrator will receive an email notification. * 6 Yes C No Annual Report Questions Information contained in this report is required and will be reviewed by the Division upon receipt and prior to the next compliance inspection of the site. If, while completing this report, you learn that your site is not in compliance with the rules an the act, it is advisable that the issues be rectified promptly to avoid possible enforcement action. 1. Is the site identification sign posted in accordance with Rule 3.1.12(1). * 6 Yes C No 2. Is the affected area boundary clearly marked in accordance with Rule 3.1.12(2). * 6 Yes C No 3. Is the mine site in final reclamation (all material extraction and stockpile removal is complete)? * If "YES," please note time limits related to completion of reclamation, Rule 3.1.3. C Yes C No 4. Has excavation, processing or hauling activity commenced at the site? * C Yes C No 5. Does the mine operate more than 180 days per year? * If "No", please review Rule 1.13 to assure that your mine is in compliance. 6 Yes C No 6. Has this mine been granted approval of TEMPORARY CESSATION Status? * C Yes C No					
Phone # Fax # 9707234944 9707238344 Permitting Contact Email Address jaime_sessions@yahoo.com Is the Permitting Contact information listed above correct? If it is not correct your organization's Administrator will receive an email notification. * © Yes © No Annual Report Questions Information contained in this report is required and will be reviewed by the Division upon receipt and prior to the next compliance inspection of the site. If, while completing this report, you learn that your site is not in compliance with the rules an the act, it is advisable that the issues be rectified promptly to avoid possible enforcement action. 1. Is the site identification sign posted in accordance with Rule 3.1.12(1). * © Yes © No 2. Is the affected area boundary clearly marked in accordance with Rule 3.1.12(2). * © Yes © No 3. Is the mine site in final reclamation (all material extraction and stockpile removal is complete)? * If "YES," please note time limits related to completion of reclamation, Rule 3.1.3. C Yes © No 5. Does the mine operate more than 180 days per year? * If "No", please review Rule 1.13 to assure that your mine is in compliance. © Yes © No 6. Has this mine been granted approval of TEMPORARY CESSATION Status? * C Yes © No	City	State	Zip Code		
9707234944 9707238344 Permitting Contact Email Address jaime_sessions@yahoo.com Is the Permitting Contact information listed above correct? If it is not correct your organization's Administrator will receive an email notification. * © Yes © No Annual Report Questions Information contained in this report is required and will be reviewed by the Division upon receipt and prior to the next compliance inspection of the site. If, while completing this report, you learn that your site is not in compliance with the rules and the act, it is advisable that the issues be rectified promptly to avoid possible enforcement action. 1. Is the site identification sign posted in accordance with Rule 3.1.12(1). * © Yes © No 2. Is the affected area boundary clearly marked in accordance with Rule 3.1.12(2). * © Yes © No 3. Is the mine site in final reclamation (all material extraction and stockpile removal is complete)? * If "YES," please note time limits related to completion of reclamation, Rule 3.1.3. © Yes © No 4. Has excavation, processing or hauling activity commenced at the site? * © Yes © No 5. Does the mine operate more than 180 days per year? * If "No", please review Rule 1.13 to assure that your mine is in compliance. © Yes © No 6. Has this mine been granted approval of TEMPORARY CESSATION Status? * © Yes © No	Walden	СО	804800000		
9707234944 9707238344 Permitting Contact Email Address jaime_sessions@yahoo.com Is the Permitting Contact information listed above correct? If it is not correct your organization's Administrator will receive an email notification. * © Yes © No Annual Report Questions Information contained in this report is required and will be reviewed by the Division upon receipt and prior to the next compliance inspection of the site. If, while completing this report, you learn that your site is not in compliance with the rules and the act, it is advisable that the issues be rectified promptly to avoid possible enforcement action. 1. Is the site identification sign posted in accordance with Rule 3.1.12(1). * © Yes © No 2. Is the affected area boundary clearly marked in accordance with Rule 3.1.12(2). * © Yes © No 3. Is the mine site in final reclamation (all material extraction and stockpile removal is complete)? * If "YES," please note time limits related to completion of reclamation, Rule 3.1.3. © Yes © No 4. Has excavation, processing or hauling activity commenced at the site? * © Yes © No 5. Does the mine operate more than 180 days per year? * If "No", please review Rule 1.13 to assure that your mine is in compliance. © Yes © No 6. Has this mine been granted approval of TEMPORARY CESSATION Status? * © Yes © No					
Permitting Contact Email Address jaime_sessions@yahoo.com Is the Permitting Contact information listed above correct? If it is not correct your organization's Administrator will receive an email notification. * © Yes © No Annual Report Questions Information contained in this report is required and will be reviewed by the Division upon receipt and prior to the next compliance inspection of the site. If, while completing this report, you learn that your site is not in compliance with the rules and the act, it is advisable that the issues be rectified promptly to avoid possible enforcement action. 1. Is the site identification sign posted in accordance with Rule 3.1.12(1). * © Yes © No 2. Is the affected area boundary clearly marked in accordance with Rule 3.1.12(2). * © Yes © No 3. Is the mine site in final reclamation (all material extraction and stockpile removal is complete)? * If "YES," please note time limits related to completion of reclamation, Rule 3.1.3. C Yes © No 4. Has excavation, processing or hauling activity commenced at the site? * C Yes © No 5. Does the mine operate more than 180 days per year? * If "NO", please review Rule 1.13 to assure that your mine is in compliance. © Yes © No 6. Has this mine been granted approval of TEMPORARY CESSATION Status? * C Yes © No	Phone #	Fax #	:		
Jaime_sessions@yahoo.com Is the Permitting Contact information listed above correct? If it is not correct your organization's Administrator will receive an email notification. * Yes C No Annual Report Questions Information contained in this report is required and will be reviewed by the Division upon receipt and prior to the next compliance inspection of the site. If, while completing this report, you learn that your site is not in compliance with the rules and the act, it is advisable that the issues be rectified promptly to avoid possible enforcement action. I. Is the site identification sign posted in accordance with Rule 3.1.12(1). * Yes C No Is the affected area boundary clearly marked in accordance with Rule 3.1.12(2). * Yes C No Is the mine site in final reclamation (all material extraction and stockpile removal is complete)? * If "YES," please note time limits related to completion of reclamation, Rule 3.1.3. Yes C No Has excavation, processing or hauling activity commenced at the site? * Yes C No Does the mine operate more than 180 days per year? * If "No", please review Rule 1.13 to assure that your mine is in compliance. Yes C No Has this mine been granted approval of TEMPORARY CESSATION Status? * C Yes C No	9707234944	970723	38344		
Jaime_sessions@yahoo.com Is the Permitting Contact information listed above correct? If it is not correct your organization's Administrator will receive an email notification. * Yes C No Annual Report Questions Information contained in this report is required and will be reviewed by the Division upon receipt and prior to the next compliance inspection of the site. If, while completing this report, you learn that your site is not in compliance with the rules and the act, it is advisable that the issues be rectified promptly to avoid possible enforcement action. I. Is the site identification sign posted in accordance with Rule 3.1.12(1). * Yes C No Is the affected area boundary clearly marked in accordance with Rule 3.1.12(2). * Yes C No Is the mine site in final reclamation (all material extraction and stockpile removal is complete)? * If "YES," please note time limits related to completion of reclamation, Rule 3.1.3. Yes C No Has excavation, processing or hauling activity commenced at the site? * Yes C No Does the mine operate more than 180 days per year? * If "No", please review Rule 1.13 to assure that your mine is in compliance. Yes C No Has this mine been granted approval of TEMPORARY CESSATION Status? * C Yes C No					
Is the Permitting Contact information listed above correct? If it is not correct your organization's Administrator will receive an email notification. * © Yes © No Annual Report Questions Information contained in this report is required and will be reviewed by the Division upon receipt and prior to the next compliance inspection of the site. If, while completing this report, you learn that your site is not in compliance with the rules and the act, it is advisable that the issues be rectified promptly to avoid possible enforcement action. 1. Is the site identification sign posted in accordance with Rule 3.1.12(1). * © Yes © No 2. Is the affected area boundary clearly marked in accordance with Rule 3.1.12(2). * © Yes © No 3. Is the mine site in final reclamation (all material extraction and stockpile removal is complete)? * If "YES," please note time limits related to completion of reclamation, Rule 3.1.3. C Yes © No 4. Has excavation, processing or hauling activity commenced at the site? * C Yes © No 5. Does the mine operate more than 180 days per year? * If "No", please review Rule 1.13 to assure that your mine is in compliance. © Yes © No 6. Has this mine been granted approval of TEMPORARY CESSATION Status? * C Yes © No					
Administrator will receive an email notification. * © Yes © No Annual Report Questions Information contained in this report is required and will be reviewed by the Division upon receipt and prior to the next compliance inspection of the site. If, while completing this report, you learn that your site is not in compliance with the rules and the act, it is advisable that the issues be rectified promptly to avoid possible enforcement action. 1. Is the site identification sign posted in accordance with Rule 3.1.12(1). * © Yes © No 2. Is the affected area boundary clearly marked in accordance with Rule 3.1.12(2). * © Yes © No 3. Is the mine site in final reclamation (all material extraction and stockpile removal is complete)? * If "YES," please note time limits related to completion of reclamation, Rule 3.1.3. C Yes © No 4. Has excavation, processing or hauling activity commenced at the site? * C Yes © No 5. Does the mine operate more than 180 days per year? * If "No", please review Rule 1.13 to assure that your mine is in compliance. © Yes © No 6. Has this mine been granted approval of TEMPORARY CESSATION Status? * C Yes © No					
Annual Report Questions Information contained in this report is required and will be reviewed by the Division upon receipt and prior to the next compliance inspection of the site. If, while completing this report, you learn that your site is not in compliance with the rules and the act, it is advisable that the issues be rectified promptly to avoid possible enforcement action. 1. Is the site identification sign posted in accordance with Rule 3.1.12(1). * 6 Yes C No 2. Is the affected area boundary clearly marked in accordance with Rule 3.1.12(2). * 6 Yes C No 3. Is the mine site in final reclamation (all material extraction and stockpile removal is complete)? * If "YES," please note time limits related to completion of reclamation, Rule 3.1.3. C Yes C No 4. Has excavation, processing or hauling activity commenced at the site? * C Yes C No 5. Does the mine operate more than 180 days per year? * If "NO", please review Rule 1.13 to assure that your mine is in compliance. 6 Yes C No 6. Has this mine been granted approval of TEMPORARY CESSATION Status? * C Yes C No					
Annual Report Questions Information contained in this report is required and will be reviewed by the Division upon receipt and prior to the next compliance inspection of the site. If, while completing this report, you learn that your site is not in compliance with the rules and the act, it is advisable that the issues be rectified promptly to avoid possible enforcement action. 1. Is the site identification sign posted in accordance with Rule 3.1.12(1). * 6 Yes C No 2. Is the affected area boundary clearly marked in accordance with Rule 3.1.12(2). * 6 Yes C No 3. Is the mine site in final reclamation (all material extraction and stockpile removal is complete)? * If "YES," please note time limits related to completion of reclamation, Rule 3.1.3. C Yes C No 4. Has excavation, processing or hauling activity commenced at the site? * C Yes C No 5. Does the mine operate more than 180 days per year? * If "NO", please review Rule 1.13 to assure that your mine is in compliance. C Yes C No 6. Has this mine been granted approval of TEMPORARY CESSATION Status? * C Yes C No		i receive an email not	incation. "		
Information contained in this report is required and will be reviewed by the Division upon receipt and prior to the next compliance inspection of the site. If, while completing this report, you learn that your site is not in compliance with the rules and the act, it is advisable that the issues be rectified promptly to avoid possible enforcement action. 1. Is the site identification sign posted in accordance with Rule 3.1.12(1). * © Yes © No 2. Is the affected area boundary clearly marked in accordance with Rule 3.1.12(2). * © Yes © No 3. Is the mine site in final reclamation (all material extraction and stockpile removal is complete)? * If "YES," please note time limits related to completion of reclamation, Rule 3.1.3. © Yes © No 4. Has excavation, processing or hauling activity commenced at the site? * © Yes © No 5. Does the mine operate more than 180 days per year? * If "No", please review Rule 1.13 to assure that your mine is in compliance. © Yes © No 6. Has this mine been granted approval of TEMPORARY CESSATION Status? * © Yes © No	Yes O No				
compliance inspection of the site. If, while completing this report, you learn that your site is not in compliance with the rules and the act, it is advisable that the issues be rectified promptly to avoid possible enforcement action. 1. Is the site identification sign posted in accordance with Rule 3.1.12(1). * ② Yes ③ No 2. Is the affected area boundary clearly marked in accordance with Rule 3.1.12(2). * ③ Yes ⑤ No 3. Is the mine site in final reclamation (all material extraction and stockpile removal is complete)? * If "YES," please note time limits related to completion of reclamation, Rule 3.1.3. ② Yes ⑥ No 4. Has excavation, processing or hauling activity commenced at the site? * ② Yes ⑥ No 5. Does the mine operate more than 180 days per year? * If "NO", please review Rule 1.13 to assure that your mine is in compliance. ③ Yes ⑥ No 6. Has this mine been granted approval of TEMPORARY CESSATION Status? * C Yes ⑥ No	Annual Rep	ort Questions			
2. Is the affected area boundary clearly marked in accordance with Rule 3.1.12(2). * ② Yes ③ No 3. Is the mine site in final reclamation (all material extraction and stockpile removal is complete)? * If "YES," please note time limits related to completion of reclamation, Rule 3.1.3. ② Yes ⑤ No 4. Has excavation, processing or hauling activity commenced at the site? * ② Yes ⑥ No 5. Does the mine operate more than 180 days per year? * If "NO", please review Rule 1.13 to assure that your mine is in compliance. ③ Yes ⑥ No 6. Has this mine been granted approval of TEMPORARY CESSATION Status? * ③ Yes ⑥ No					
2. Is the affected area boundary clearly marked in accordance with Rule 3.1.12(2).* 3. Is the mine site in final reclamation (all material extraction and stockpile removal is complete)?* If "YES," please note time limits related to completion of reclamation, Rule 3.1.3. Yes No 4. Has excavation, processing or hauling activity commenced at the site?* Yes No 5. Does the mine operate more than 180 days per year?* If "NO", please review Rule 1.13 to assure that your mine is in compliance. Yes No 6. Has this mine been granted approval of TEMPORARY CESSATION Status?* Yes No	1 Te the cite iden	tification sign posted	in accordance with Pule 3.1.12(1) *		
2. Is the affected area boundary clearly marked in accordance with Rule 3.1.12(2). * ② Yes ② No 3. Is the mine site in final reclamation (all material extraction and stockpile removal is complete)? * If "YES," please note time limits related to completion of reclamation, Rule 3.1.3. ② Yes ③ No 4. Has excavation, processing or hauling activity commenced at the site? * ② Yes ⑤ No 5. Does the mine operate more than 180 days per year? * If "NO", please review Rule 1.13 to assure that your mine is in compliance. ③ Yes ③ No 6. Has this mine been granted approval of TEMPORARY CESSATION Status? * ② Yes ⑤ No					
3. Is the mine site in final reclamation (all material extraction and stockpile removal is complete)? * If "YES," please note time limits related to completion of reclamation, Rule 3.1.3. O Yes O No 4. Has excavation, processing or hauling activity commenced at the site? * O Yes O No 5. Does the mine operate more than 180 days per year? * If "NO", please review Rule 1.13 to assure that your mine is in compliance. O Yes O No 6. Has this mine been granted approval of TEMPORARY CESSATION Status? * O Yes O No					
3. Is the mine site in final reclamation (all material extraction and stockpile removal is complete)? * If "YES," please note time limits related to completion of reclamation, Rule 3.1.3. O Yes O No 4. Has excavation, processing or hauling activity commenced at the site? * O Yes O No 5. Does the mine operate more than 180 days per year? * If "NO", please review Rule 1.13 to assure that your mine is in compliance. O Yes O No 6. Has this mine been granted approval of TEMPORARY CESSATION Status? * O Yes O No		area boundary clearly	y marked in accordance with Rule 3.1.12(2). *		
If "YES," please note time limits related to completion of reclamation, Rule 3.1.3. O Yes O No 4. Has excavation, processing or hauling activity commenced at the site? * O Yes O No 5. Does the mine operate more than 180 days per year? * If "NO", please review Rule 1.13 to assure that your mine is in compliance. O Yes O No 6. Has this mine been granted approval of TEMPORARY CESSATION Status? * O Yes O No	⊙ Yes ♡ No				
O Yes ⊙ No 4. Has excavation, processing or hauling activity commenced at the site? * O Yes ⊙ No 5. Does the mine operate more than 180 days per year? * If "NO", please review Rule 1.13 to assure that your mine is in compliance. ⊙ Yes ⊙ No 6. Has this mine been granted approval of TEMPORARY CESSATION Status? * O Yes ⊙ No	3. Is the mine site	e in final reclamation ((all material extraction and stockpile removal is complete)? *		
4. Has excavation, processing or hauling activity commenced at the site? * O Yes O No 5. Does the mine operate more than 180 days per year? * If "NO", please review Rule 1.13 to assure that your mine is in compliance. O Yes O No 6. Has this mine been granted approval of TEMPORARY CESSATION Status? * O Yes O No	If "YES," please note time limits related to completion of reclamation, Rule 3.1.3.				
 O Yes ⊙ No 5. Does the mine operate more than 180 days per year? * If "NO", please review Rule 1.13 to assure that your mine is in compliance. ⊙ Yes ⊙ No 6. Has this mine been granted approval of TEMPORARY CESSATION Status? * ⊙ Yes ⊙ No 	C Yes ⊙ No	unie ilinits related to compit			
5. Does the mine operate more than 180 days per year? * If "NO", please review Rule 1.13 to assure that your mine is in compliance. Yes O No 6. Has this mine been granted approval of TEMPORARY CESSATION Status? * O Yes O No	4. Has excavation, processing or hauling activity commenced at the site? *				
If "NO", please review Rule 1.13 to assure that your mine is in compliance. • Yes • No • Has this mine been granted approval of TEMPORARY CESSATION Status? • Yes • No	C Yes O No	·			
 O Yes O No 6. Has this mine been granted approval of TEMPORARY CESSATION Status? * O Yes ⊙ No 		·			
6. Has this mine been granted approval of TEMPORARY CESSATION Status? * ○ Yes ○ No	5. Does the mine	n, processing or haulir	ng activity commenced at the site? *		
C Yes ⊙ No		n, processing or haulir operate more than 18	ng activity commenced at the site?* 30 days per year?*		
C Yes ⊙ No	If "NO", please review	n, processing or haulir operate more than 18	ng activity commenced at the site? * 30 days per year? *		
	If "NO", please review • Yes • No	operate more than 18 Rule 1.13 to assure that yo	ng activity commenced at the site? * 30 days per year? * our mine is in compliance.		
	If "NO", please review • Yes © No	operate more than 18 Rule 1.13 to assure that yo	ng activity commenced at the site? * 30 days per year? * our mine is in compliance.		

For the following questions, please note that numeric values must include one decimal place, such as "0.0" for zero acres, or 10.2 instead of 10.23.

C Yes © No

8. Number of acres currently affected (mining + incomplete and or unreleased reclamation). $*$ (?) 7.0
9. Number of acres that were newly affected during the current report year * (?) 0.0
10. Number of acres that were reclaimed during the current report year. $\overset{\bigstar}{}$ (?) 0.0
11. Estimated new acreage to be affected in the next report year. * (?) 0.0
12. Estimated acres to be reclaimed in the next report year. * (?) 0.0
13. Total acres in various stages of reclamation, since permitted mining activities began:
Total acres backfilled * (?) 0.0
Total acres graded * (?) 0.0
Total acres seeded with approved mix * (?) 0.0
Seed Application Method * NA
Total acres fertilized with aproved fertilizer * (?) 0.0
Fertilizer Application Method * NA
Total acres with topsoil replaced * (?) 0.0
Topsoil replacement depth (in.) * (?) 0.0
Total acres mulched with approved mulch * (?) 0.0
Mulch application rate (tons/ac) * (?) 0.0
Mulch Application Method * NA
14. Is weed control being conducted in accordance with an approved Weed Control Plan? * If "YES", indicate the weed species, control area, control type, application rate and treatment date on the report map. O Yes O No O N/A
15. Is adequate topsoil reserved for reclamation, based on your approved permit? *

16. Is the reserved topsoil vegetated/stabilized in accordance of "NO", please explain • Yes • No • N/A	with Rule 3.1.9(1)? *		
17. If mining has exposed groundwater, is the site in compliance with the approved mining plan and Office of the State Engineer (Well Permit, S.W.S.P., and/or Permanent Augmentation Plan)? ★ ○ Yes ○ No ○ N/A			
18. Are all hazardous materials stored within approved spill containment structures? * ○ Yes ○ No ○ N/A			
19. Is your financial warranty value sufficient to cover the cost to complete reclamation? ★ ⊙ Yes ○ No ○ N/A			
20. Is your basis for legal right to enter still valid? *Yes C No			
21. Does your permit require you to submit monitoring information of Yes • No • N/A	ion annually? *		
22. As required by Colorado Mined Land Reclamation Act and/or Extraction of Construction Materials (C.R.S.34-32-116 or 34-32 accurately depicts the permit boundary, current affected area be specified in items 8-12 and 15. *	5-116), attach a map to this report that		
Only PDF formatted files can be uploaded. 2018 Fairbanks Pit Annual Report.pdf	221.17KB		
23. If you have supplemental information you would like to prov Only PDF formatted files can be uploaded.	ide, please upload it here.		
24. Rule 5.7 requires submittal of final abandonment reports wit artesian flows and no later than 12 months for all other complet component of your exploration/prospecting activities, have the	ed drill holes. If drill holes are a		
C Yes C No € NA Annual Fee Payment			
Payment Confirmation Number * (?) 98591814			
Signature			
Submittal Date 11-29-2018			
 I, the undersigned, hereby state that the information provide and that site operations are being conducted in accordance vertical reclamation plans. I Agree If you do not see the "Submit" button after completing your report, try to un- 	vith the Division approved mining and		