



---

## Notification of Water Quality Parameter Exceedance

---

**Ronald Parratt** <Ronald.Parratt@newmont.com>  
To: "Eschberger - DNR, Amy" <amy.eschberger@state.co.us>  
Cc: Justin Raglin <Justin.Raglin@newmont.com>

Thu, Dec 13, 2018 at 8:54 AM

Dear Mrs. Eschberger,

Please see the attached document for notification of water quality parameter exceedance for a groundwater sample collected in Q4, 2018.

If you have any questions please reach out to me via phone at 719.689.4019.

Best Regards,

Ron



**Ronald Parratt**

Environmental Specialist

Cripple Creek and Victor Gold Mining Co.

T 719.689.4019

C 719.429-8522

[www.newmont.com](http://www.newmont.com)

**Newmont Mining Corporation**  
Cripple Creek and Victor Gold Mining Co.

100 North 3<sup>rd</sup> Street

Victor, CO 80860

*Please consider the environment before printing this e-mail.*

=====

The content of this message may contain the private views and opinions of the sender and does not constitute a formal view and/or opinion of the company unless specifically stated.

The contents of this email and any attachments may contain confidential and/or proprietary information, and is intended only for the person/entity to whom it was originally addressed. Any dissemination, distribution or copying of this communication is strictly prohibited.

If you have received this email in error please notify the sender immediately by return e-mail and delete this message and any attachments from your system.

=====



**DRMS Water Quality Exceedance Notification 12-13-18.pdf**

128K



Newmont Mining Corporation  
Cripple Creek & Victor Gold Mine  
100 North 3<sup>rd</sup> Street P O Box 191  
T 719-689-4029  
F 719-689-3254  
www.newmont.com

December 13, 2018

SENT VIA EMAIL

Mrs. Amy Eschberger  
Environmental Protection Specialist  
Colorado Department of Natural Resources  
Division of Reclamation, Mining and Safety  
Office of Mined Land Reclamation  
1313 Sherman Street, Room 215  
Denver, Colorado 80203

**Re: Permit No. M-1980-244; Cripple Creek & Victor Gold Mining Company ("CC&V"); Cresson Project  
– Notification of Water Quality Analysis Parameter Exceedances December 12, 2018**

Dear Mrs. Eschberger:

In accordance with Rule 9, Section 3.1.7 of the Mineral Rules and Regulations of the Colorado Mined Land Reclamation Board for Hard Rock, Metal, and Designated Mining Operations (Rules), the Cripple Creek and Victor Gold Mining Company (CC&V) hereby provides the Division of Reclamation, Mining and Safety (Division) with a formal notification of water quality parameter exceedances.

CC&V collected fourth quarter compliance groundwater samples from monitoring well GVMW-22A on November 26<sup>th</sup>, 2018. CC&V received the lab report for these analyses on December 11, 2018, and upon review, determined that GVMW-22A exceeded established numeric protection limits for fluoride. The table below lists the exceedance for the location and the associated parameter and the attached graph demonstrates the parameter trend from Q1 2017 to present.

Location	Sample Date	Parameter	Value (mg/L)	NPL (mg/L)	Table Standard (mg/L)
GVMW-22A	11/26/2018	Fluoride	2.21	2	2

Should you require further information please do not hesitate to contact Ronald Parratt at 719.689.4019 or [ronald.parratt@newmont.com](mailto:ronald.parratt@newmont.com) or myself at 719.689.4042 or [justin.raglin@newmont.com](mailto:justin.raglin@newmont.com).

Sincerely,

A handwritten signature in black ink, appearing to read 'JR', with a long horizontal line extending to the right.

Justin Raglin  
Senior Environmental Manager  
Cripple Creek and Victor Gold Mine

JR/RP

cc: Amy Eschberger, DRMS

## **Attachments**

# GVMMW-22A

