





PROJECT LOCATION MAP
(NOT TO SCALE)



SITE LOCATION MAP
(NOT TO SCALE)

SOURCE:
USGS DIGITAL RASTER GRAPHIC,
MORRISON QUADRANGLE

DRAWING LIST:

- SHEET 1 COVER SHEET
- SHEET 2 NORTH QUARRY
- SHEET 3 CENTRAL QUARRY
- SHEET 4 SOUTH QUARRY

Morrison Quarry 2018 Annual Report
DRMS Permit M-1973-021

Aggregate Industries




Project 1804111

SITE LOCATION

December 2018

Sheet 1



PLAN
NORHT QUARRY AREA





FIGURE 1
RECLAMATION





FIGURE 2
RECLAMATION



- LEGEND:
- FIGURE 1 - RECLAMATION
 - FIGURE 2 - RECLAMATION
 - NORTH FILL SLOPE
 - NORTH REPOSITORY AREA
 - HAUL ROAD RECLAMATION AREA

- NOTES:
1. NO MINING PLANNED FOR 2018. RECLAMATION PLANS INCLUDE WASTE ROCK FILL IN NORTH REPOSITORY.
 2. BOUNDARIES ARE BASED ON INFORMATION PROVIDED BY AGGREGATE INDUSTRIES.
 3. TOPOGRAPHY SHOWN IS FROM AUGUST 2016.
 4. NO AREAS DISTURBED OR RECLAIMED IN 2017.

Morrison Quarry 2018 Annual Report
DRMS Permit M-1973-021

Aggregate Industries




Project 1804111

NORTH QUARRY

December 2018

Sheet 2




LEGEND:

- 80:120 COMPLETE BACKFILL AND REVEGETATED
- FILL TO EL 6500
- LAI D BACK AND STABILIZED

NOTES:

1. NO MINING OR RECLAMATION PLANNED FOR 2018.
2. BOUNDARIES ARE BASED ON INFORMATION PROVIDED BY AGGREGATE INDUSTRIES.
3. TOPOGRAPHY SHOWN IS FROM AUGUST 2016.
4. NO AREAS DISTURBED OR RECLAIMED IN 2017.



Morrison Quarry 2018 Annual Report
DRMS Permit M-1973-021

Aggregate Industries




Project 1804111

CENTRAL QUARRY

December 2018

Sheet 3



- LEGEND:
- PREVIOUSLY RECLAIMED
 - PREVIOUSLY, PARTIALLY RECLAIMED
 - 2018 AREA DISTURBED
 - 2019 AREA TO BE DISTURBED

NOTE:

1. TOPOGRAPHY OBTAINED USING PHOTOGRAMMETRY FROM PHOTOGRAPHS OBTAINED USING UNMANNED AERIAL SYSTEMS (UAS). PHOTOGRAPHS OBTAINED BY GEI USING PHANTOM 4 PRO UAS ON MAY 4, 2017 AND NOVEMBER 29, 2018.

2. TOPOGRAPHY OF UNCHANGED AREAS IN SOUTH QUARRY OBTAINED BY AGGREGATE INDUSTRIES, OCTOBER 2017.



Morrison Quarry 2018 Annual Report DRMS Permit M-1973-021	 GEI Consultants	SOUTH QUARRY	
		Project 1804111	December 2018
Aggregate Industries			Sheet 4