

## **DELTA COUNTY, COLORADO**

## Office of the County Engineer

Delta County Courthouse
501 Palmer Street, Suite 124
Delta, Colorado 81416-1796
Phone: 970-874-5914 or 874-2035 FAX 970-874-2455

February 15, 2019

Division of Reclamation, Mining and Safety 1313 Sherman St., Room 215 Denver, CO 80203

Re:

Annual Report Mott Gravel Pit

Permit No.: M-1980-049

## Included are:

- 1. Annual Fee and Report Request;
- 2. Map site location
- 3. Map location activity
- 4. Annual fee of \$323.


Included is the location activity map showing mining activity for the year at the County's Mott Gravel Pit location.

Mined inventory quantities of gravel are on hand and being used for road projects.


If you have any questions, please contact me.

Regards,

Bob Basher 970.874.5914 OFFICE OF THE COUNTY ENGINEER DELTA COUNTY



Page 2 of 2 M:\Engineering\mining & mineral extraction\County gravel pits\Div of Rec Annual Reports\2018\Mott\2018\_AnnualReport\_Mott.doc



## 112c Annual Report

	Permit Number:	M-1980-049
	Permittee Name:	Delta County
	Operation Name:	Mott Pit
	County:	Delta
	Anniversary Date:	February 18, 2019
	Current Bond Amount:	\$11,701.70
	Annual Fee Due:	\$323.00
(DRMS Office Use Only)	Permit Acreage:	9.74
	DRMS Specialist:	SJM

According to C.R.S. 34-32.5-116 or 34-32-116, each year, on the anniversary date of the permit, an operator shall submit the Annual Fee, an Annual Report and map showing the extent of current disturbances to affected land, required monitoring information, reclamation accomplished to date and during the preceding year, any new disturbance that is anticipated to occur during the upcoming year, any reclamation that will be performed during the upcoming year, the dates for the beginning of active operations, and the date active operations ceased for the year.

Information contained in this report will be reviewed by the Division upon receipt and prior to the next compliance inspection of the site. If, while completing this report, you learn that your site is not in compliance with the rules and the act, it is advisable that the issues be rectified promptly to avoid possible enforcement action.

1.	Is the site identification sign posted in accordance with Rule 3.1.12(1)?	YES NO		
2.	Is the affected area boundary clearly marked in accordance with Rule 3.1.12(2)?	YES NO		
3.	Is the mine site in final reclamation (all material extraction and stockpile removal is comple	te)? YES NO		
	If "YES," please note time limits related to completion of reclamation, Rule 3.1.3.			
4.	What was the date of last excavation, processing or hauling activity at the mine?	12/17/18		
5.				
	If "NO," please review Rule 1.13 to assure that your mine is in compliance.			
6.	Has the mine been granted:			
	a. Approval of TEMPORARY CESSATION Status?	YES NO		
	b. Approval for INTERMITTENT OPERATION?	YES NO		
7.	Number of acres currently affected (mining + incomplete and or unreleased reclamation):	_6.15		
8.	Number of acres that were newly affected during the current report year:	1.41		
9.	Number of acres that were reclaimed during the current report year:	$\mathcal{O}$		
10.	Estimated new acreage to be affected in the next report year:	$\mathcal{O}$		
11.	Estimated acres to be reclaimed in the next report year:	Ŏ		
12.	Total acres in various stages of reclamation, since permitted mining activities began:			
	Total acres backfilled:			
	Total acres seeded with approved mix:			
	Total acres with topsoil replaced:	O		
	Total acres mulched with approved mulch:			
	Total acres graded:			

13.	Total acres fertilized with approved fertilizer:		0			
	Topsoil replacement depth (inches):	-	0	<del></del> 8i		
	Mulch application rate (tons):		0			
	Seed application method:		IA			
	Fertilizer application method:		1117			
	Mulch application method:	_1	1/17	ā		
14.	Is weed control being conducted in accordance with an approved Weed Control Plan?  If "YES," indicate the weed species, control area, control type, application rate and treatment map. SEE ANNUAL REPORT	YES ent date o	NO n the r	N/A eport		
15.	Is adequate topsoil reserved for reclamation, based on your approved permit?  If "NO," please explain:	(	YES	NO		
16.	Is the reserved topsoil vegetated/stabilized in accordance with Rule 3.1.9(1)?  If "NO," please explain:	YES	NO	N/A		
17.	If mining has exposed groundwater, is the site in compliance with the approved mining plane Engineer (Well Permit, S.W.S.P., and/or Permanent Augmentation Plan)?	n and Off YES	ice of t NO	he State		
10	Is all hazardous material stored within approved spill containment structures?	YES	NO	N/A		
	Is your financial warranty value sufficient to cover the cost to complete reclamation?	YES	NO	N/A		
	Is your basis for legal right to enter still valid?	<u> </u>	YES	NO		
	Does your permit require you to submit monitoring information annually?		-1-29			
	If "YES," please attach the required monitoring results to this Annual Report.	YES	NO /	N/A		
22.	As required by Colorado Mined Land Reclamation Act and/or Colorado Land Reclamation A	ct for the	Extrac	tion of		
	Construction Materials (C.R.S. 34-32-116 or 34-32.5-116), attach a map to this report that accurately depicts the					
	permit boundary, current affected area boundary and location of the acreages specified in items 7 – 12 and 14.  UPDATED MAP ATTACHED:					