

General Information

Disclaimer

Under the terms of your NOI or Reclamation Permit and Colorado Statutes, you must submit Annual Fees and Annual Reports (including a map). You must pay the Annual Fee and submit an Annual Report each year until reclamation responsibility release is granted. The Annual Fee is not a renewal fee. The Fee and Report are for LAST YEAR'S mining and reclamation season, and MUST be paid even if your operation was inactive.

If you have requested reclamation responsibility release from the Division of Reclamation, Mining and Safety ("Division") but your permit is not released by the anniversary date listed below, the Annual Fee MUST be paid. If the permit is released before the anniversary date, then by Statute, it is not necessary to pay an Annual Fee or submit an Annual Report for that year.

Division records indicate the following is due:

Select Permit Number *

Only Permit Numbers with currently due Annual Reports and Fees will be listed. If nothing appears in the dropdown box below, there are no annual fees or reports due for any of your permits.

M1977424

Select Anniversary Date *

03-28-2019

PLEASE REMEMBER TO CLICK "SUBMIT" AFTER YOU HAVE COMPLETED YOUR REPORT AND PAYMENT.

Please check the box indicating you have read and understand the terms of the Annual Report and Annual Fee *

✓ I understand and agree to the terms

General Information

Permittee Name

Occidental Oil Shale, Inc.

Operation Name

Logan Wash

| Permit Number | Fee Due | Permit Acreage |
|---------------|------------------|---------------------|
| M1977424 | 633.00 | 108.55 |
| County | Anniversary Date | Current Bond Amount |
| Garfield | 03-28-2019 | 236752.00 |

Proceed

Contact Information

Here is the contact information we have on file for this permit. If any of it is inaccurate, you will have the opportunity to correct it after this form has been submitted.

- 1. Upon submission of this form you will be presented with a link to the contact information update form.
- 2. There is a question asking about the accuracy of this information at the bottom of this page. Indicating that it is inaccurate will send an e-mail to notify your administrator to make the appropriate changes.

| Permittee Contact Information | | |
|---|------------------|----------------|
| Permittee Contact Nan Mike Anderson | ne | |
| Permittee Company Occidental Oil Shale, Inc. | | |
| Permittee Address 1 c/o Glenn Springs Holding | js, Inc. | |
| Permittee Address 2 5 Greenway Plaza, Suite 1 | 110 | |
| Permittee City | Permittee State | Permittee Zip |
| Houston | тх | 770460000 |
| Permittee Phone # | Permittee Fa | ıx # |
| 7133665143 | 7139858980 | |
| Permittee Contact Ema roger_smith@oxy.com | | |
| Permitting Cor | | |
| Permitting Contact Nate Bruce Smith | me | |
| Permitting Company Western Water & Land, In | IC. | |
| Permitting Address 1 | | |
| 743 HorizonCt. Ste 330 | | |
| Permitting Address 2 | | |
| | | |
| Permitting City | Permitting State | Permitting Zip |
| Grand Junction | СО | 815060000 |
| Permitting Phone # | Permitting Fa | ax # |
| 9702420170 | 9702420270 | |

| Permitting Contact Email Address bsmith@westernwaterandland.com | | |
|--|--|---|
| Inspection Contact Info | | |
| Inspection Contact N Bruce Smith | lame | |
| Inspection Company Western Water & Land, | | |
| Inspection Address 1 743 Horizon Ct., Suite 3 | | |
| Inspection Address 2 | 2 | |
| Inspection City | Inspection State | Inspection Zip |
| Grand Junction | CO | 815060000 |
| Inspection Phone # | Inspection F | ax # |
| 9702420170 | 9702420270 | |
| Inspection Contact E bsmith@westernwaterar | | |
| Administrator will red | ntact information listed al ceive an email notification | pove correct? If it is not correct your organization's n. * |
| ⊙ Yes ○ No Previous Proceed | | |
| | | |
| | | |
| | | |
| | | |
| | | |
| | | |
| | | |
| | | |
| | | |

Annual Report Questions

Annual Report Questions

Information contained in this report is required and will be reviewed by the Division upon receipt and prior to the next compliance inspection of the site. If, while completing this report, you learn that your site is not in compliance with the rules and the act, it is advisable that the issues be rectified promptly to avoid possible enforcement action.


| Is the site identification sign posted in accordance with Rule 3.1.12(1). * Yes O No |
|---|
| 2. Is the affected area boundary clearly marked in accordance with Rule 3.1.12(2). * \odot Yes \odot No |
| 3. Is the mine site in final reclamation (all material extraction and stockpile removal is complete)? * If "YES," please note time limits related to completion of reclamation, Rule 3.1.3. Yes O No |
| 4. Has excavation, processing or hauling activity commenced at the site? * Image: Yes O No |
| What was the date of last excavation, processing or hauling activity at the mine? * 3/2/1982 |
| 5. Does the mine operate more than 180 days per year? * If "NO", please review Rule 1.13 to assure that your mine is in compliance. C Yes O No |
| 6. Has this mine been granted approval of TEMPORARY CESSATION Status? * C Yes © No |
| 7. Has this mine been granted approval for INTERMITTENT OPERATION? * C Yes O No |
| For the following questions, please note that numeric values must include one decimal place, such as "0.0" for zero acres, or 10.2 instead of 10.23. |
| |
| 8. Number of acres currently affected (mining + incomplete and or unreleased reclamation). * (?) 42.5 |
| 8. Number of acres currently affected (mining + incomplete and or unreleased reclamation). * $(?)$ |
| 8. Number of acres currently affected (mining + incomplete and or unreleased reclamation). * (?) 42.5 9. Number of acres that were newly affected during the current report year * (?) |
| 8. Number of acres currently affected (mining + incomplete and or unreleased reclamation). * (?) 42.5 9. Number of acres that were newly affected during the current report year * (?) 0.0 10. Number of acres that were reclaimed during the current report year. * (?) |
| 8. Number of acres currently affected (mining + incomplete and or unreleased reclamation). * (?) 42.5 9. Number of acres that were newly affected during the current report year * (?) 0.0 10. Number of acres that were reclaimed during the current report year. * (?) 0.0 11. Estimated new acreage to be affected in the next report year. * (?) |
| 8. Number of acres currently affected (mining + incomplete and or unreleased reclamation). * (?) 42.5 9. Number of acres that were newly affected during the current report year * (?) 0.0 10. Number of acres that were reclaimed during the current report year. * (?) 0.0 11. Estimated new acreage to be affected in the next report year. * (?) 0.0 12. Estimated acres to be reclaimed in the next report year. * (?) |

```
Total acres graded * (?)
14.8
Total acres seeded with approved mix * (?)
30.2
Seed Application Method *
Broadcast seeding
Total acres fertilized with aproved fertilizer * (?)
20.8
Fertilizer Application Method *
Hydro spreader
Total acres with topsoil replaced * (?)
14.7
Topsoil replacement depth (in.) * (?)
6.0
Total acres mulched with approved mulch * (?)
16.8
Mulch application rate (tons/ac) * (?)
2.0
Mulch Application Method *
```

Hydromulching

Previous Proceed

Annual Report Questions



Extraction of Construction Materials (C.R.S.34-32-116 or 34-32.5-116), attach a map to this report that accurately depicts the permit boundary, current affected area boundary and location of the acreages specified in items 8-12 and 15. *

| Only PDF formatted files can be uploaded. | |
|---|--------|
| Figure 2_Logan Wash Facilities.pdf | 3.27MB |
| Figure 3_Logan Wash Mine Wells.pdf | 6.19MB |
| Figure 4A_Reclamation Status.pdf | 2.98MB |
| Figure 4B_Reclamation Status.pdf | 3.26MB |

23. If you have supplemental information you would like to provide, please upload it here.

| Only PDF formatted files can be uploaded. | |
|---|---------|
| DRMSLWannI19_032719_All2.pdf | 22.06MB |
| Appendix A Logan Wash Evap Pond Reline As-Built_All_Final.pdf | 21.04MB |

24. Rule 5.7 requires submittal of final abandonment reports within 60 days for any drill hole(s) with artesian flows and no later than 12 months for all other completed drill holes. If drill holes are a component of your exploration/prospecting activities, have they been properly abandoned?

⊙ Yes ○ No ○ NA

| Previous | Proceed |
|----------|---------|
|----------|---------|

| Annual Fee Payment |
|---|
| Annual Fee Payment |
| Payment Confirmation Number * (?) |
| 105250408 |
| Signature |
| I, the undersigned, hereby state that the information provided in this report is true and accurate, and that site operations are being conducted in accordance with the Division approved mining and reclamation plans. * |
| ☑ I Agree |
| If you do not see the "Submit" button after completing your report, try to un-check and then re-check the "I Agree" box. |
| Previous |