



COLORADO

**Division of Reclamation,
Mining and Safety**

Department of Natural Resources

1313 Sherman Street, Room 215
Denver, CO 80203

April 12, 2019

Jim Doody
Kilgore Companies LLC dba Elam Construction
556 Struthers Ave
Grand Junction, CO 81501

RE: Surface Rock Pit, Permit No. M-1984-001, Inspection Problem Abated

Dear Mr. Doody:

On September 4, 2018 the Division of Reclamation, Mining and Safety (Division) conducted an inspection of the above referenced site. Availability of Records was cited as a problem for prolonged map deficiencies. Corrective actions required you submit updated mining and reclamation plan maps in the form of a technical revision by the corrective action date.

On April 12, 2019 the Division approved TR-2. This satisfies the corrective action and it is considered abated.

If you require additional information, or have questions or concerns, please feel free to contact me. Amy Yeldell, at the Division of Reclamation, Mining and Safety, 1313 Sherman St., Room 215, Denver, CO 80203. Direct contact can be made by phone at 970-254-8511 or via email at amy.yeldell@state.co.us

Sincerely,

Amy Yeldell

Environmental Protection Specialist

Cc: Travis Marshall, Senior EPS, Grand Junction DRMS

