

TABLE 1
 LEAK TEST DATA
 LOLOFF SLURRY WALL
 GREELEY, COLORADO

Date	Slurry Wall Test Day	Staff Gage Reading	Dewatering Pump Totalizer Reading (acre ft. pumped)	Precipitation (inches water)	Exterior Monitoring Well Readings (depth in feet to water)	Comments
1/5/2019	1		619.46			
1/6/2019	2					
1/7/2019	3		619.51			
1/8/2019	4		619.52			
1/9/2019	5		619.59			
1/10/2019	6		619.66			
1/11/2019	7		619.70	0.07		Snow
1/12/2019	8		619.74			
1/13/2019	9		619.92			
1/14/2019	10		620.06			
1/15/2019	11		620.16			
1/16/2019	12		620.28			
1/17/2019	13		620.40			
1/18/2019	14		620.50			
1/19/2019	15		620.59			
1/20/2019	16		620.69			
1/21/2019	17		620.82			
1/22/2019	18		620.90			
1/23/2019	19		620.90			
1/24/2019	20		620.99	0.02		Snow
1/25/2019	21	4	621.15			
1/26/2019	22	3'10"	621.15			
1/27/2019	23	4' 1"	621.22			
1/28/2019	24	3'9"	621.38			
1/29/2019	25	4' 2"	621.38			
1/30/2019	26	3'10"	621.45			
1/31/2019	27	4'	621.57			
2/1/2019	28		621.64			
2/2/2019	29		621.64			
2/3/2019	30	4' 2"	621.76			
2/4/2019	31	3' 11"	621.89			
2/5/2019	32	3' 9"	622.02			

TABLE 1
 LEAK TEST DATA
 LOLOFF SLURRY WALL
 GREELEY, COLORADO

Date	Slurry Wall Test Day	Staff Gage Reading	Dewatering Pump Totalizer Reading (acre ft. pumped)	Precipitation (inches water)	Exterior Monitoring Well Readings (depth in feet to water)	Comments
2/6/2019	33	3' 8"	622.13	0.01		Snow
2/7/2019	34		622.13			
2/8/2019	35		622.13			
2/9/2019	36		622.13			
2/10/2019	37		622.13			
2/11/2019	38	4' 8"	622.25			
2/12/2019	39	3' 9"	622.50			
2/13/2019	40	3'10"	622.60			
2/14/2019	41	3'8"	622.71			
2/15/2019	42	3'10"	622.82			
2/16/2019	43	3'9"	622.91			

TABLE 1
 LEAK TEST DATA
 LOLOFF SLURRY WALL
 GREELEY, COLORADO

Date	Slurry Wall Test Day	Staff Gage Reading	Dewatering Pump Totalizer Reading (acre ft. pumped)	Precipitation (inches water)	Exterior Monitoring Well Readings (depth in feet to water)	Comments
2/17/2019	44	3'9"	622.91			
2/18/2019	45	4'6"	623.12			
2/19/2019	46	4'6"	623.12			
2/20/2019	47	4'6"	623.12	0.06		
2/21/2019	48	4'6"	623.12			
2/22/2019	49	4'5"	623.25	0.01		
2/23/2019	50	4'5"	623.25	0.02		
2/24/2019	51	4'5"	623.25			
2/25/2019	52	5'0"	623.20			
2/26/2019	53	5'4"	623.68			
2/27/2019	54	5'4"	623.68			
2/28/2019	55	5'5"	623.87			
3/1/2019	56	4'6"	624.06			
3/2/2019	57	4'4"	624.17			
3/3/2019	58		624.17			
3/4/2019	59		624.17			
3/5/2019	60		624.17			
3/6/2019	61	5'5"	624.26	0.01		
3/7/2019	62	5'0"	624.70			
3/8/2019	63	4'6"	624.98	0.01		
3/9/2019	64	4'4"	625.19			
3/10/2019	65	4'10"	625.27			
3/11/2019	66	4'10"	625.27			
3/12/2019	67	4'7"	625.39	0.01		
3/13/2019	68	4'4"	625.56	0.12		
3/14/2019	69	4'11"	625.78	0.02		
3/15/2019	70	4'6"	625.92	0.04		
3/16/2019	71	4'8"	626.05			
3/17/2019	72	4'8"	626.05			
3/18/2019	73	4'0"	626.05			
3/19/2019	74	4'0"	626.15			
3/20/2019	75	4'0"	626.15			

TABLE 1
 LEAK TEST DATA
 LOLOFF SLURRY WALL
 GREELEY, COLORADO

Date	Slurry Wall Test Day	Staff Gage Reading	Dewatering Pump Totalizer Reading (acre ft. pumped)	Precipitation (inches water)	Exterior Monitoring Well Readings (depth in feet to water)	Comments
3/21/2019	76	4'0"	626.15			
3/22/2019	77	5'0"	626.25	0.02		
3/23/2019	78	5'0"	626.25			
3/24/2019	79	5'2"	626.38			
3/25/2019	80	4'4"	626.56			
3/26/2019	81	4'6"	626.73			
3/27/2019	82	4'4"	626.81			
3/28/2019	83	4'2"	626.90			
3/29/2019	84	4'4"	627.03			
3/30/2019	85	4.4"	627.03			
3/31/2019	86	4'4"	627.03			
4/1/2019	87	4'8"	627.22			
4/2/2019	88	4.4"	627.13			
4/3/2019	89	4'2"	627.21			
4/4/2019	90	4'4"	627.33			