

	General Notes	
2.	Water pond filled in October Backfill / Regrading is occurrir the East ½ of the pit - Fill Nee	ng in
	drain properly. Backfill / Regrading expected	
4.	continue in 2019. Topsoil will be imported and _l	placed
	over old lake/regrading area. North East 3 Acres topsoiled a	
	seeded in 2018.	
6. 7.	Weed Control - Mowing and w spraying activities performed times during 2018. Weeds cor of Thistle and Leafy Spurge. V spray has been 2-4-D Comme Product (Landslide) and Roun Russian Olives removed and disposed in October 2016 - so has not returned.	2 nsist Veed rcial dup.
No.	Revision	Date
CONNELL RESOURCES, INC. 7785 Highland Meadows Parkway, Suite 100 Fort Collins, Co 80528 PHONE: 970-223-3151 FAX: 970-223-3191		
Project Name and Address:		
Glass Gravel Pit Fort Collins, CO		
Project: Annual Report May 20, 2019 Permit M-1981-022		
Project	Annual Report May 20, 20 Permit M-1981-022)19
Project: Date:	Annual Report May 20, 20 Permit M-1981-022 May 15, 2019)19