

25th Avenue Site (M-2002-020) Monitoring Well Data

	Depth to Water (feet from top of casing)					
	MW-1	MW-2	MW-3	MW-4	MW-5	MW-6
6/27/2012	14.1	>10.9 dry bottom	11.9	17.4	16.1	15.0
7/20/2012	14.5	>10.9	12.2	20.9	16.6	15.4
9/24/2012	23.6	>10.9	12.3	>28.2 wet mud	26.9	21.6
12/18/2012	22.9	>10.9	12.4	>28.2	26.8	22.5
3/13/2013	22.8	>10.9	12.3	>28.2	26.0	24.2
6/19/2013	22.4	>10.9	12.2	>28.2	25.9	24.1
9/27/2013	20.5	8.8	8.7	24.4	25.2	22.9
12/23/2013	22.1	10.5	10.4	>28.2	25.8	25.0
3/27/2014	22.9	>10.9	10.5	>28.2	26.8	26.4
8/1/2014	21.4	8.7	8.0	28.2	26.4	24.9
10/23/2014	24.0	>10.9	10.3	>28.2	27.9	25.6
1/15/2015	24.4	>10.9	10.5	>28.2	28.4	27.5
4/14/2015	24.75	>10.9	11.2	>28.2	29	28.4
6/23/2015	21.8	7.8	7.2	27.9	27.3	25.6
11/4/2015	24.75	>11.0	11.3	>28.2	28.2	26.3
1/13/2016	25.0	>11.0	10.9	>28.2	28.6	27.85
5/19/2016	24.0	7.6	6.8	>28.2	28.7	(1)
6/24/2016	23.5	10.8	10.6	>28.2	28.4	(1)
11/27/2016	26.0	>11.0	11.9	>28.2	29.3	(1)
4/18/2017	26.5	>11.0	11.6	>28.2	30.3	(1)
8/2/2017	25.9	>11.0	11.5	>28.2	29.5	(1)
10/25/2017	26.0	>11.0	11.3	>28.2	29.3	(1)
2/8/2018	26.2	>11.0	11.4	>28.2	29.8	(1)
5/10/2018	26.5	>11.0	10.5	>28.2	30.4	(1)
7/25/2018	26.4	>11.0	11.6	>28.2	29.9	(1)
10/29/2018	27	>10.7	11.1	>28.2	30	(1)
1/31/2019	27.5	>10.9	12.2	>28.2	30.8	(1)
4/25/2019	27.8	>10.6	12	>28.2	31.4	(1)
(1) Lost during reclamation activities						