



COLORADO
FARMS. LLC

June 28, 2019

Patrick Lennberg
Colorado Division of Reclamation, Mining and Safety
1313 Sherman St, Room 215
Denver, CO 80203

RE: Big R Pit M-1988-052

Patrick,

Regarding the 5/15/19 inspection of the Big R Pit, specifically off-site fill materials, the fill material came from our property at 5370 Hunt Circle next to our Greenhouse.

The fill is clean and inert. Quantity of fill is 20 tons of top soil. A google earth map showing where the material is from is attached.

Please let me know if you need any further information to resolve this issue.

Best regards,

A handwritten signature in blue ink, appearing to read 'Ranko Mocevic', with a stylized, cursive script.

Ranko Mocevic
Manager
Colorado Farms LLC

