

Pinon Ridge Mining LLC
31161 Highway 90, PO Box 825
Nucla, Colorado 81424

June 9, 2019

Mr. Dustin Czapla
Division of Reclamation, Mining and Safety
101 South 3rd Street, Room 301
Grand Junction, Colorado 81501
RE: Minerals Program Inspection Report – 17 April 2019

RECEIVED
JUL 03 2019
DIVISION OF RECLAMATION
MINING AND SAFETY

Maintenance Report, Van-4 PM ID, M-1997-032

In response to your inspection report dated April 17th, 2019, Pinon Ridge Mining LLC (PRM) performed mitigation efforts on the items identified. This work was completed on June 3rd, 2019. PRM hereby submits this Mitigation Report and attached supporting photographs of the corrective actions taken. Below you will find a brief description of the repairs and/or removal of said items:

1. The hoist house west side door has been reinstalled. The front north side window where the hoist cable feeds thru is covered and the building is secured.
2. The metal shed on the west side of the shop building has been dismantled and moved off site.
3. The shop building wall on the west side has been repaired. The two man doors on the east side have been covered up and the window on the north side also is covered up and the building is secured.

On behalf of the entire team here at PRM, we thank you kindly for your observations and hope you will find these efforts to be satisfactory in achieving the standards set forth.

Please do not hesitate to contact me (435) 459-1354 or mrutter@western-uranium.com if you should have any questions or require additional information.

Regards,



Pinon Ridge Mining LLC
Mike Rutter
Vice President, Operation

Attachment

Cc: George Glasier

Pinon Ridge Mining LLC
31161 Highway 90, PO Box 825
Nucla, Colorado 81424

Mitigation Efforts | Completed June 3rd, 2019



Hoist House (North Side)



Hoist House (South Side)



Shop Building (South Side)



Shop Building (North Side)



Hoist Building (West Side)