

Engineering and Public Works Department David Benbow Interim Director

July 22, 2019

Patrick Lennberg, Environmental Protection Specialist Colorado Division of Reclamation, Mining and Safety 1313 Sherman Street, Room 215 Denver, CO 80203

RE: M-1997-081 Everhart Pit – Response to Corrective Action

Mr. Patrick Lennberg:

On May 23, 2019 an inspection was conducted on Everhart Pit. Through this inspection it was discovered that Pueblo County (Operator) had let affected land come within 25 feet of Red Creek. Corrective action for Pueblo County was to re-establish the 150-200 foot buffer along Red Creek, reclaim all affected land, and clearly identify and mark the 150-200 foot buffer zone.

Pueblo County has worked diligently to re-establish and mark the buffer zone and respectfully submits the attached photographs as proof of compliance. Attached you will find Exhibit 1 – GPS location of the 4'x150' berm, Exhibit 2 – Photograph of berm area and t-posts marking the buffer zone (looking west), Exhibit 3 – Photograph of berm area and t-posts (looking east) and Exhibit 4 – Photograph of berm area and t-posts (looking north). The berm will be seeded and monitored to ensure the revegetation of native vegetation.

Please feel free to contact me if additional information is required in order to accomplish the requirements of the corrective action.

Sincerely,

Iominga Jimenez-Darcia

Dominga Jimenez-Garcia General Services Engineer

Everhart Pit

4' x 150' Berm Placement

3147310.3 X 1569072.4 Y

100 ft

147089.5 X 1569031.8 Y

3147012.4 X 1568963.2 Y

2

3147176.3 X 1568922.7 Y

3147093.6 X 1568847.3 Y

Exhibit 1 Dept. of Engineering and Public Works

Google Earth



Looking west toward berm. Photograph by: Doming Jimenez-Garcia Date: July 18, 2019

Exhibit 2 Dept. of Engineering and Public Works



Looking east toward berm. Photograph by: Doming Jimenez-Garcia Date: July 18, 2019





Looking north toward berm. Photograph by: Doming Jimenez-Garcia Date: July 18, 2019

