

PLATTE S&H  
Annual Report Supplemental  
Year 2019

5. Mine has not operated for more than 180 days in the last year. Site has had sales of existing material piles (on site prior to the Martin Marietta lease). Material in the silt pond area has been excavated but not processed. We are working on setting up a new plant. Re-screening the remaining piles on-site will occur in September and the new plant should be operational at the end of September.

16. The new topsoil pile created in 2019 will be stabilized shortly.

21. Monitoring of ground water levels is not required.