

3809/3715 FIELD INSPECTION FORM

DATE: 7/25//2019 TIME: 1:00 PM CDRMS # P-2018-009P COC- 79120

CMC #: 259646, 259655, 278507 MINE NAME: Blue Mesa Project

TOWNSHIP: 49N RANGE: 17W SECTION: 30 Subdivision: SESW MERIDIAN: NMPM

TOWNSHIP: 49N RANGE: 17W SECTION: 31 Subdivision: NENW MERIDIAN: NMPM

CLAIMANT NAME: Hubbard Trucking, Inc. Present during Inspection: YES or **NO**

OPERATOR NAME: Hubbard Trucking, Inc. Present during Inspection: YES or **NO**

OTHERS AT INSPECTION: _____

Is the Operation active? YES or **NO** CDRMS contact: Dustin Czapla

INDICATE TYPE OF OPERATIONS BEING CONDUCTED:

EXPLORATION: X

- ☐ Claim Staking
- ☐ Clearing of timber or other vegetation
- ☐ Drill pads
- ☒ Drill holes (Plugged: **YES** or NO)
- ☐ Trenches
- ☐ Test pits
- ☐ Bulk sampling sites
- ☐ Reopen old adits/shafts (Grated: Y or N)
- ☐ New adits/shafts (Grated: Y or N)
- ☐ Explosives use or storage
- ☐ Existing roads maintained or widened
- ☐ New roads constructed
- ☐ Other- describe in General Comments

MINING: _____

- ☐ Underground mine (Grated: Y or N)
- ☐ Mine dumps
- ☐ Surface mine
- ☐ Placer mine
- ☐ Tailings pond
- ☐ Ore stockpiles
- ☐ Overburden stockpiles
- ☐ Vehicle yard area
- ☐ Adits/shafts in operation
- ☐ Explosives use or storage
- ☐ Existing roads maintained/widened
- ☐ New roads constructed
- ☐ Hazardous materials stored or in use
- ☐ Other- describe in General Comments

MILLING: _____

- ☐ Milling or processing facilities
- ☐ Leaching pad or ponds
- ☐ Powerlines
- ☐ Hazardous materials present
- ☐ Fuel tanks: _____ above or _____ below ground
Amount stored: _____ Gallons or ft³
Are tanks: _____ lined or _____ bermed
- ☐ Additional roads
- ☐ Other- describe in General Comments

STRUCTURES: _____

- ☐ Temporary camp trailers
- ☐ Buildings on skids
- ☐ Structures or buildings affixed to land
- ☐ Other camp facilities
- ☐ Sanitary facilities
- ☐ Full-time occupancy of site
- ☐ Seasonal or temporary use of site
- ☐ Occupancy identified in Notice or POO
- ☐ Other-describe in General Comments

ACCESS:

Type and location of access authorized: Access is from Hwy 141 to Montrose County Road P12 about 4 miles to Q14 Rd. Drill site is right off Q14 Rd about one mile north of P12 Rd.

Was topsoil saved/stockpiled? Yes _____ No _____ Not Enough Available _____ Not Practical X

Is access in compliance with NOI/PLAN? Yes X No _____

OPERATIONS:

Is the operation causing obvious erosion or other degradation? Yes _____ No X Describe in General Comments

Are toxic or hazardous materials stored on site? Yes _____ No X If Yes, describe: _____

Does operator/claimant have appropriate permit(s) for HAZMAT use? Yes _____ No X

Are the materials being stored/used in accordance with conditions of the permit? Yes _____ No _____ NA X If No, document on an attachment for immediate notification to HAZMAT Coordinator.

Were weapons observed on site? Yes _____ No X If Yes, describe: _____

Are operations in compliance with NOI/PLAN? Yes X No _____ If No, describe in comments/changes sections.

RECLAMATION:

Date: 7/30/10

COC-79120, 7/25/2019, B. Buria



Drill pad from county road.



Drill pad.

COC-79120, 7/25/2019, B. Buria




Drill pad looking at access from county road.



Drill pad.

COC-79120, 7/25/2019, B. Buria



Access from county road. Taken from pad.



Access from county road. Taken from county road.

COC-79120, 7/25/2019, B. Buria



Access from county road. Looking at pad from county road.