




MINERALS PROGRAM INSPECTION REPORT
PHONE: (303) 866-3567

The Division of Reclamation, Mining and Safety has conducted an inspection of the mining operation noted below. This report documents observations concerning compliance with the terms of the permit and applicable rules and regulations of the Mined Land Reclamation Board.

MINE NAME: Blue Jet Mine	MINE/PROSPECTING ID#: M-1978-135-HR	MINERAL: Gold, silver and copper	COUNTY: Moffat
INSPECTION TYPE: Monitoring	INSPECTOR(S): Amy C. Yeldell	INSP. DATE: July 18, 2019	INSP. TIME: 08:30
OPERATOR: Blue Jet Mining Inc	OPERATOR REPRESENTATIVE: Orvie Zimmerman	TYPE OF OPERATION: 110(2) - Hard Rock Limited Impact	
REASON FOR INSPECTION: Normal I&E Program	BOND CALCULATION TYPE: IT.Bondcalculationtype.CD.Desc	BOND AMOUNT: \$3,132.00	
DATE OF COMPLAINT: NA	POST INSP. CONTACTS: None	JOINT INSP. AGENCY: U.S.BLM	
WEATHER: Clear	INSPECTOR'S SIGNATURE: 	SIGNATURE DATE: August 28, 2019	

GENERAL INSPECTION TOPICS

This list identifies the environmental and permit parameters inspected and gives a categorical evaluation of each. No problems or possible violations were noted during the inspection. The mine operation was found to be in full compliance with Mineral Rules and Regulations of the Colorado Mined Land Reclamation Board for the Extraction of Construction Materials and/or for Hard Rock, Metal and Designated Mining Operations. Any person engaged in any mining operation shall notify the office of any failure or imminent failure, as soon as reasonably practicable after such person has knowledge of such condition or of any impoundment, embankment, or slope that poses a reasonable potential for danger to any persons or property or to the environment; or any environmental protection facility designed to contain or control chemicals or waste which are acid or toxic-forming, as identified in the permit.

(AR) RECORDS----- <u>Y</u>	(FN) FINANCIAL WARRANTY----- <u>Y</u>	(RD) ROADS----- <u>N</u>
(HB) HYDROLOGIC BALANCE----- <u>Y</u>	(BG) BACKFILL & GRADING----- <u>Y</u>	(EX) EXPLOSIVES----- <u>NA</u>
(PW) PROCESSING WASTE/TAILING---- <u>N</u>	(SF) PROCESSING FACILITIES----- <u>N</u>	(TS) TOPSOIL----- <u>NA</u>
(MP) GENL MINE PLAN COMPLIANCE- <u>N</u>	(FW) FISH & WILDLIFE----- <u>Y</u>	(RV) REVEGETATION---- <u>Y</u>
(SM) SIGNS AND MARKERS----- <u>Y</u>	(SP) STORM WATER MGT PLAN---- <u>N</u>	(RS) RECL PLAN/COMP-- <u>N</u>
(ES) OVERBURDEN/DEV. WASTE----- <u>N</u>	(SC) EROSION/SEDIMENTATION--- <u>Y</u>	(ST) STIPULATIONS----- <u>N</u>
(AT) ACID OR TOXIC MATERIALS----- <u>NA</u>	(OD) OFF-SITE DAMAGE----- <u>N</u>	

Y = Inspected / N = Not inspected / NA = Not applicable to this operation / PB = Problem cited / PV = Possible violation cited

OBSERVATIONS

This inspection was conducted as part of the Colorado Division of Reclamation, Mining and Safety (Division) normal monitoring program. Orvie Zimmerman represented Blue Jet Mining Inc. and accompanied Amy Yeldell of the Division and Jennifer Maiolo of the BLM on the inspection. The Blue Jet Mine is a 110(2) permitted site that includes a total of 9.9 acres in two parcels on federal lands.

Little to no site changes have occurred since last year's inspection. Very little mining surface disturbance remains as native vegetation continues to volunteered. Native vegetation is very lush with no noxious weeds. Mr. Zimmerman indicated that this parcel has not yet been grazed for the year. No equipment, fuel structures or other debris is on site. No stockpiles are present and slopes appear to be stable.

The operator may wish to conduct drilling operations in the near future. Please review the current mining plan, if drilling was not previously specified/approved, a TR will be required prior to commencing drilling activities.

No problems or violations were cited. The Division holds a bond in the amount of \$3,132.

Responses to this inspection report should be directed to: Amy Yeldell at the Division of Reclamation, Mining and Safety, 1313 Sherman St., Room 215, Denver, CO 80203. Direct contact can be made by phone at 303-866-3567 Ext 8183 or via email at amy.yeldell@state.co.us

Inspection Contact Address

Orvie Zimmerman
Blue Jet Mining Inc.
P.O. Box 181
Craig, CO 81626

Enclosure

CC:
Travis Marshall, Senior EPS, Grand Junction DRMS
Jennifer Maiolo, BLM

PHOTOGRAPHS



