



Newmont Goldcorp
Cripple Creek & Victor Mine
100 N 3rd Street
PO Box 191
Victor, CO 80860
newmontgoldcorp.com

SENT CERTIFIED RETURN RECEIPT REQUESTED
7018 0680 0000 4627 5828

September 16, 2019

Mr. Timothy Cazier, P.E.
Environmental Protection Specialist
Colorado Department of Natural Resources
Division of Reclamation, Mining and Safety
Office of Mined Land Reclamation
1313 Sherman Street, Room 215
Denver, Colorado 80203

**Re: Permit No. M-1980-244; Cripple Creek & Victor Gold Mining Company; Cresson
Project; Technical Revision 116 Preliminary Adequacy Review Response**

Dear Mr. Cazier:

On September 13, 2019 Newmont Goldcorp Corporation - Cripple Creek and Victor Gold Mining Company (CC&V) received the Division of Reclamation, Mining and Safety (DRMS) second adequacy review of Technical Revision (TR) No. 116, proposing an underground exploration project. Below are DRMS's comments in italics followed by CC&V's responses in bold.

- 1) *Figures and Maps: The response was adequate.*

No response required.

- 2) *Table 1: The response was adequate.*

No response required.

- 3) *Five support buildings: The PAR requested dimensions of the buildings, which would typically include building height. Only length and width were provided. Our demolition costs are based on building volumes. Please provide building height information.*

The below table has been updated from the table submitted in CC&V's preliminary adequacy review response to include the height of each facility structure.

Conceptual Cresson Yard and Portal Buildings					
Structure #	Description	Width (ft)	Length (ft)	Area (ft ²)	Height (ft)
1	Fixed Maintenance Shop	53	91	4,823	12
	Septic Tanks				
	Communications Building				
2	Mobile Maintenance Shop	204	90	18,360	18
	Lube Bay & Wash Bay				
	Shop, Lube, Wash Bay Apron				
3	Fuel Island	57	37	2,109	6
4	Water Tank*	143	52	7,436	6
	Compressor Housing*				
	Sump*				
5	CRF/Shotcrete Plant*	55	120	6,600	18
6	Portal Extension* - sprayed concrete directly on pit surface	18	50	900	20

*Not a building.

- 4) *Fuel Island Facility: The response was adequate. The DRMS accepts CC&V's commitment to "submit additional information similar to that submitted with TR-63 as an addendum to this TR once the fuel island design is complete."*

No response required.

- 5) *Implementation Schedule: The response was adequate.*

No response required.

Should you require further information, please do not hesitate to contact Katie Blake via phone or email at 719.689.4048 and Katie.Blake@newmont.com or myself at 719.689.4042 and Justin.Raglin@newmont.com.

Sincerely,



Justin Raglin
Senior Environmental Manager
Cripple Creek & Victor Mine

JR/kb

EC: T. Cazier – DRMS
M. Cunningham – DRMS
E. Russell – DRMS
P. Lennberg - DRMS
J. Raglin – CC&V
J. Bills – CC&V
L. White – CC&V



STATE OF
COLORADO

Russell - DNR, Elliott <elliott.russell@state.co.us>

M-1980-244, TR 116 Second Adequacy Review Response

Katie Dehlin <Katie.Blake@newmont.com>

Mon, Sep 16, 2019 at 2:28 PM

To: "Cazier - DNR, Tim" <tim.cazier@state.co.us>

Cc: "michaela.cunningham@state.co.us" <michaela.cunningham@state.co.us>, "Elliott Russell - DNR (elliott.russell@state.co.us)" <elliott.russell@state.co.us>, Patrick Lennberg - DNR <patrick.lennberg@state.co.us>, Justin Raglin <Justin.Raglin@newmont.com>, Justin Bills <Justin.Bills@newmont.com>, Linda White <Linda.White@newmont.com>

Good Afternoon,

Please see the attached scan of CC&V's second adequacy review response for TR 116. A hard copy has been sent in today's mail. If you have any questions or comments, please contact Justin Raglin at Justin.Raglin@Newmont.com or 719-689-4042, or Katie Blake at Katie.Blake@Newmont.com or 719-689-4048.

Thank you.



Katie Blake

Senior Environmental Coordinator

Cripple Creek and Victor Gold Mining Co.

T 719.689.4048

M 719.237.3442

www.newmontgoldcorp.com

Newmont Goldcorp

Cripple Creek and Victor Gold Mining Co.

100 North 3rd Street

Victor, CO 80860

Please consider the environment before printing this e-mail.

9/17/2019

State.co.us Executive Branch Mail - M-1980-244, TR 116 Second Adequacy Review Response



20190916_NMC_TR116SecondAR_Response.pdf

102K