

Newmont Goldcorp Cripple Creek & Victor Gold Mine 100 North 3<sup>rd</sup> Street P O Box 191 T 719-689-4029 F 719-689-3254 www.newmont.com

September 26, 2019

## SENT VIA EMAIL

Mr. Patrick Lennberg Environmental Protection Specialist Colorado Department of Natural Resources Division of Reclamation, Mining and Safety Office of Mined Land Reclamation 1313 Sherman Street, Room 215 Denver, Colorado 80203

## Re: <u>Permit No. M-1980-244; Cripple Creek & Victor Gold Mining Company ("CC&V"); Cresson Project –</u> Notification of Water Quality Analysis Parameter Exceedances September 26, 2019

Dear Mr. Lennberg:

In accordance with Rule 9, Section 3.1.7 of the Mineral Rules and Regulations of the Colorado Mined Land Reclamation Board for Hard Rock, Metal, and Designated Mining Operations (Rules), the Cripple Creek and Victor Gold Mining Company (CC&V) hereby provides the Division of Reclamation, Mining and Safety (Division) with a formal notification of water quality parameter exceedances.

CC&V collected third quarter compliance groundwater samples from monitoring wells SGMW-6B, on September 4, 2019. CC&V received the lab report for these analyses on September 20, 2019, and upon review, determined that SGMW-6B exceeded established numeric protection limits for fluoride, manganese, and sulfate. The table below lists the exceedance for the location and the associated parameter and the attached graph demonstrates the parameter trend from Q3 2017 to present.

Location	Sample Date	Parameter	Value (mg/L)	NPL (mg/L)	Table Standard (mg/L)
SGMW-6B	9/4/2019	Fluoride	6.53	2	2
SGMW-6B	9/4/2019	Manganese	6.36	3	0.05
SGMW-6B	9/4/2019	Sulfate	953	250	250

Should you require further information please do not hesitate to contact Ronald Parratt at 719.689.4019 or <u>ronald.parratt@newmont.com</u> or myself at 719.689.4042 or <u>justin.raglin@newmont.com</u>.

Sincerely,

C.

Justin Raglin

Senior Environmental Manager Cripple Creek and Victor Gold Mine

## JR/RP

ec: Patrick Lennberg, DRMS

## Attachments





