




MINERALS PROGRAM INSPECTION REPORT
PHONE: (303) 866-3567

The Division of Reclamation, Mining and Safety has conducted an inspection of the mining operation noted below. This report documents observations concerning compliance with the terms of the permit and applicable rules and regulations of the Mined Land Reclamation Board.

MINE NAME: Grizzly Ridge Pit	MINE/PROSPECTING ID#: M-1984-152	MINERAL: Sand and gravel	COUNTY: Montrose
INSPECTION TYPE: Monitoring	INSPECTOR(S): Stephanie Mitchell	INSP. DATE: September 12, 2019	INSP. TIME: 14:00
OPERATOR: Montrose County	OPERATOR REPRESENTATIVE: Brandon Wallace	TYPE OF OPERATION: 110c - Construction Limited Impact	
REASON FOR INSPECTION: Normal I&E Program		BOND CALCULATION TYPE: None	
DATE OF COMPLAINT: NA		BOND AMOUNT: \$0.00	
POST INSP. CONTACTS: None		JOINT INSP. AGENCY: None	
WEATHER: Clear	INSPECTOR'S SIGNATURE: 	SIGNATURE DATE: October 9, 2019	

GENERAL INSPECTION TOPICS

This list identifies the environmental and permit parameters inspected and gives a categorical evaluation of each. No problems or possible violations were noted during the inspection. The mine operation was found to be in full compliance with Mineral Rules and Regulations of the Colorado Mined Land Reclamation Board for the Extraction of Construction Materials and/or for Hard Rock, Metal and Designated Mining Operations. Any person engaged in any mining operation shall notify the office of any failure or imminent failure, as soon as reasonably practicable after such person has knowledge of such condition or of any impoundment, embankment, or slope that poses a reasonable potential for danger to any persons or property or to the environment; or any environmental protection facility designed to contain or control chemicals or waste which are acid or toxic-forming, as identified in the permit.

(AR) RECORDS----- <u>Y</u>	(FN) FINANCIAL WARRANTY----- <u>NA</u>	(RD) ROADS----- <u>Y</u>
(HB) HYDROLOGIC BALANCE----- <u>Y</u>	(BG) BACKFILL & GRADING----- <u>Y</u>	(EX) EXPLOSIVES----- <u>NA</u>
(PW) PROCESSING WASTE/TAILING---- <u>N</u>	(SF) PROCESSING FACILITIES----- <u>Y</u>	(TS) TOPSOIL----- <u>Y</u>
(MP) GENL MINE PLAN COMPLIANCE- <u>Y</u>	(FW) FISH & WILDLIFE----- <u>Y</u>	(RV) REVEGETATION---- <u>Y</u>
(SM) SIGNS AND MARKERS----- <u>Y</u>	(SP) STORM WATER MGT PLAN---- <u>N</u>	(RS) RECL PLAN/COMP-- <u>Y</u>
(ES) OVERBURDEN/DEV. WASTE----- <u>N</u>	(SC) EROSION/SEDIMENTATION--- <u>Y</u>	(ST) STIPULATIONS----- <u>N</u>
(AT) ACID OR TOXIC MATERIALS----- <u>N</u>	(OD) OFF-SITE DAMAGE----- <u>N</u>	

Y = Inspected and found in compliance / N = Not inspected / NA = Not applicable to this operation / PB = Problem cited / PV = Possible violation cited

OBSERVATIONS

This was a normal monitoring inspection of the Grizzly Ridge Pit; DRMS File No. M-1984-152 operated by Montrose County Road and Bridge. This site is located approximately 10 miles southwest of Crawford, Colorado in Montrose County. I, Stephanie Mitchell of the Colorado Division of Reclamation, Mining and Safety (Division) conducted the inspection. Mr. Brandon Wallace accompanied me on the inspection.

This is a 110c mining operation with a 9.90 permit acres with 4 acres disturbed. Several product stockpiles are on site. Topsoil is stored in the southern portion of the permit area and appears stable.

There was no fuel stored on site or equipment. Vegetation is sparse in this portion of the affected land some native grasses have established in this area.

Mining is moving to the west. The permit area is delineated by T posts and fencing.

No problems or violations were noted during this inspection.

Responses to this inspection report should be directed to Stephanie Mitchell at the Division of Reclamation, Mining and Safety, Grand Junction Field Office, 101 South 3rd Street, Room 301, Grand Junction, Colorado 81501, phone number (303)866-3567 ext 8180.

PHOTOGRAPHS



Mine ID sign



Material Stockpile

Inspection Contact Address

Brandon Wallace
Montrose County
63160 LaSalle Rd
Montrose, CO 81401