



Newmont Goldcorp
Cripple Creek & Victor Gold Mine
100 North 3rd Street P O Box 191
T 719-689-4029
F 719-689-3254
www.newmont.com

October 3, 2019

SENT VIA EMAIL

Mr. Patrick Lennberg
Environmental Protection Specialist
Colorado Department of Natural Resources
Division of Reclamation, Mining and Safety
Office of Mined Land Reclamation
1313 Sherman Street, Room 215
Denver, Colorado 80203

Re: Permit No. M-1980-244; Cripple Creek & Victor Gold Mining Company ("CC&V"); Cresson Project – Notification of Water Quality Analysis Parameter Exceedances October 3, 2019

Dear Mr. Lennberg:

In accordance with Rule 9, Section 3.1.7 of the Mineral Rules and Regulations of the Colorado Mined Land Reclamation Board for Hard Rock, Metal, and Designated Mining Operations (Rules), the Cripple Creek and Victor Gold Mining Company (CC&V) hereby provides the Division of Reclamation, Mining and Safety (Division) with a formal notification of water quality parameter exceedances.

CC&V collected third quarter compliance groundwater samples from monitoring wells CRMW-3C, SGMW-6B, and CRMW-5C, on September 18, 2019. CC&V received the lab report for these analyses on October 2, 2019, and upon review, determined that CRMW-3C exceeded established numeric protection limits for nitrite as N, SGMW-6B exceeded established numeric protection limits for fluoride, nitrite as N, and sulfate. It was also determined at CRMW-5C exceeded established numeric protection limits for fluoride. The table below lists the exceedance for the location and the associated parameter and the attached graph demonstrates the parameter trend from Q3 2017 to present.

Location	Sample Date	Parameter	Value (mg/L)	NPL (mg/L)	Table Standard (mg/L)
CRMW-3C	9/18/2019	Nitrite as N	0.104	0.05	1.0
SGMW-6B	9/18/2019	Fluoride	6.85	2	2
SGMW-6B	9/18/19	Nitrite as N	0.077	0.05	1.0
SGMW-6B	9/18/19	Sulfate	977	250	250
CRMW-5C	9/18/19	Fluoride	2.03	2.0	2.0

Should you require further information please do not hesitate to contact Ronald Parratt at 719.689.4019 or ronald.parratt@newmont.com or myself at 719.689.4042 or justin.raglin@newmont.com.

Sincerely,



Justin Raglin
Senior Environmental Manager
Cripple Creek and Victor Gold Mine


JR/RP

cc: Patrick Fennberg, DRMS


Attachments

SGMW-6B

Sulfate Sulfate - NPL/TVS




SGMW-6B




SGMW-6B

Fluoride — Fluoride - NPL/TVS



CRMW-5C

Fluoride — Fluoride - NPL/TVS



CRMW-3C

