

Notes:

Please refer to the 2019 Annual Report Map for location of the areas of disturbance in the mine. We continued to remove material from stockpiles and the mined area. No reclamation is required at this time. The markings and colors noted in the text reference areas shown on the map.

(9) Mining resumed on the south mine face in the stripped area this year on approximately 0.3 acres (cross hatched). There is 4.6 acres currently stripped (yellow), we may strip addition area, if needed, south of the current mining face. There is 17.6 acres of stockpile area in use (orange).

(10) No reclamation is required next year, the reclaimed area (green) continues to be monitored and is growing as expected.

(14) Weed control was done in June 2019 this year in accordance with the Weed Management Plan on the perimeter of the mine and spot work was done on the mine floor areas and roadways. Escort and 2-4-D was applied as needed. Weed control will continue in 2020.

(19) The current bond is \$117,150 and was last increased in January 2017 after an normal inspection indicated more was needed.