



Newmont Goldcorp  
Cripple Creek & Victor Gold Mine  
100 North 3<sup>rd</sup> Street P O Box 181  
T 719-689-4029  
F 719-689-3254  
www.newmont.com

December 2, 2019

SENT VIA EMAIL

Mr. Patrick Lennberg  
Environmental Protection Specialist  
Colorado Department of Natural Resources  
Division of Reclamation, Mining and Safety  
Office of Mined Land Reclamation  
1313 Sherman Street, Room 215  
Denver, Colorado 80203

**Re: Permit No. M-1980-244; Cripple Creek & Victor Gold Mining Company ("CC&V"); Cresson Project – Notification of Water Quality Analysis Parameter Exceedances December 2, 2019**

Dear Mr. Lennberg:

In accordance with Rule 9, Section 3.1.7 of the Mineral Rules and Regulations of the Colorado Mined Land Reclamation Board for Hard Rock, Metal, and Designated Mining Operations (Rules), the Cripple Creek and Victor Gold Mining Company (CC&V) hereby provides the Division of Reclamation, Mining and Safety (Division) with a formal notification of water quality parameter exceedances.

CC&V collected fourth quarter compliance groundwater samples from monitoring well GVMW-22A on November 11, 2019. CC&V received the lab report for these analyses on November 27, 2019, and upon review, determined that GVMW-22A exceeded established numeric protection limits for fluoride. The table below lists the exceedance for the location and the associated parameter and the attached graph demonstrates the parameter trend for collected data from Q1 2017 to present.

Location	Sample Date	Parameter	Value (mg/L)	NPL (mg/L)	Table Standard (mg/L)
GVMW-22A	11/11/2019	Fluoride	2.1	2.0	2.0

Should you require further information please do not hesitate to contact Ronald Parratt at 719.689.4019 or [ronald.parratt@newmont.com](mailto:ronald.parratt@newmont.com) or myself at 719.689.4042 or [justin.raglin@newmont.com](mailto:justin.raglin@newmont.com).

Sincerely,

Justin Raglin  
Senior Environmental Manager  
Cripple Creek and Victor Gold Mine

JR/RP

cc: Patrick Lennberg, DRMS

## **Attachments**

# GVMMW-22A

