



Rocky Mountain Excavating LLC

2976 L Path Cotopaxi, Co. 81223  
719-942-4311

12-31-19

Iron Mountain Road Gravel Pit  
Mine ID # M-1994-092

Division of Reclamation  
Mining and Safety  
Department of Natural Resources

The Iron Mountain Road Gravel Pit had an inspection on July 24, 2019, in regards of the surface/ runoff drainage. This inspection revealed a drainage problem and was informed that the site is improperly impounding surface water at this time. We have removed the water by of pumping it out into the proper drainage, however the water has returned and is now frozen.

I have spoken with Tim Cazier and believe that the best course of action at this time would be to let the water unthaw and backfill the area with material from the pit and correct this problem. In order for this to happen we would like to request an extension of time to be able to conduct such action. I believe that a proficient time for this to take place would be by June of 2020.

Rocky Mountain Excavating LLC  
Shawnee Koch /Bennie Koch  
Office Manager/ owner