




- LEGEND:
- PREVIOUSLY RECLAIMED
  - PREVIOUSLY, PARTIALLY RECLAIMED
  - 2018 AREA DISTURBED
  - 2020 AREA TO BE DISTURBED

NOTE:

- TOPOGRAPHY OBTAINED USING PHOTOGRAMMETRY FROM PHOTOGRAPHS OBTAINED USING UNMANNED AERIAL SYSTEMS (UAS). PHOTOGRAPHS OBTAINED BY GEI USING PHANTOM 4 PRO UAS ON MAY 4, 2017 AND NOVEMBER 29, 2018.
- TOPOGRAPHY OF UNCHANGED AREAS IN SOUTH QUARRY OBTAINED BY AGGREGATE INDUSTRIES, OCTOBER 2017.



|                                                              |                                                                                                                 |                 |                            |
|--------------------------------------------------------------|-----------------------------------------------------------------------------------------------------------------|-----------------|----------------------------|
| Morrison Quarry 2019 Annual Report<br>DRMS Permit M-1973-021 | <br><b>GEI</b> Consultants | SOUTH QUARRY    |                            |
| Aggregate Industries                                         |                                                                                                                 | Project 1705051 | December 2019      Sheet 4 |