




**MINERALS PROGRAM INSPECTION REPORT**  
**PHONE: (303) 866-3567**

The Division of Reclamation, Mining and Safety has conducted an inspection of the mining operation noted below. This report documents observations concerning compliance with the terms of the permit and applicable rules and regulations of the Mined Land Reclamation Board.

<b>MINE NAME:</b> Triantos Gravel Pit	<b>MINE/PROSPECTING ID#:</b> M-1978-304	<b>MINERAL:</b> Sand and gravel	<b>COUNTY:</b> Delta
<b>INSPECTION TYPE:</b> Monitoring	<b>INSPECTOR(S):</b> Stephanie Mitchell	<b>INSP. DATE:</b> January 29, 2020	<b>INSP. TIME:</b> 11:00
<b>OPERATOR:</b> Delta County	<b>OPERATOR REPRESENTATIVE:</b> Larry Record	<b>TYPE OF OPERATION:</b> 112c - Construction Regular Operation	
<b>REASON FOR INSPECTION:</b> Normal I&E Program	<b>BOND CALCULATION TYPE:</b> None	<b>BOND AMOUNT:</b> \$0.00	
<b>DATE OF COMPLAINT:</b> NA	<b>POST INSP. CONTACTS:</b> None	<b>JOINT INSP. AGENCY:</b> None	
<b>WEATHER:</b> Clear	<b>INSPECTOR'S SIGNATURE:</b> 	<b>SIGNATURE DATE:</b> February 6, 2020	

**GENERAL INSPECTION TOPICS**

This list identifies the environmental and permit parameters inspected and gives a categorical evaluation of each. No problems or possible violations were noted during the inspection. The mine operation was found to be in full compliance with Mineral Rules and Regulations of the Colorado Mined Land Reclamation Board for the Extraction of Construction Materials and/or for Hard Rock, Metal and Designated Mining Operations. Any person engaged in any mining operation shall notify the office of any failure or imminent failure, as soon as reasonably practicable after such person has knowledge of such condition or of any impoundment, embankment, or slope that poses a reasonable potential for danger to any persons or property or to the environment; or any environmental protection facility designed to contain or control chemicals or waste which are acid or toxic-forming, as identified in the permit.

(AR) RECORDS----- <u>Y</u>	(FN) FINANCIAL WARRANTY----- <u>NA</u>	(RD) ROADS----- <u>Y</u>
(HB) HYDROLOGIC BALANCE----- <u>Y</u>	(BG) BACKFILL & GRADING----- <u>Y</u>	(EX) EXPLOSIVES----- <u>NA</u>
(PW) PROCESSING WASTE/TAILING---- <u>N</u>	(SF) PROCESSING FACILITIES----- <u>Y</u>	(TS) TOPSOIL----- <u>Y</u>
(MP) GENL MINE PLAN COMPLIANCE- <u>Y</u>	(FW) FISH & WILDLIFE----- <u>Y</u>	(RV) REVEGETATION---- <u>Y</u>
(SM) SIGNS AND MARKERS----- <u>Y</u>	(SP) STORM WATER MGT PLAN---- <u>N</u>	(RS) RECL PLAN/COMP-- <u>Y</u>
(ES) OVERBURDEN/DEV. WASTE----- <u>N</u>	(SC) EROSION/SEDIMENTATION--- <u>Y</u>	(ST) STIPULATIONS----- <u>N</u>
(AT) ACID OR TOXIC MATERIALS----- <u>N</u>	(OD) OFF-SITE DAMAGE----- <u>N</u>	

Y = Inspected and found in compliance / N = Not inspected / NA = Not applicable to this operation / PB = Problem cited / PV = Possible violation cited

## **OBSERVATIONS**

This inspection was conducted as part of the Division of Reclamation, Mining and Safety's (Division) normal monitoring program. Larry Record representing the Operator was present during this inspection. Photographs are included at the end of this report in order to illustrate some of the conditions observed during this inspection.

The Triantos Gravel Pit, File No. M-1978-304 is located approximately 3.75 miles west of Delta, Colorado in Delta County. The site is a 112c operation that includes a total of 34.30 permitted acres with a maximum disturbance of 18 acres. The post mining land use is Wildlife Habitat.

Adequate mine identification signage was noted at the entrance to the site. The affected area was adequately marked with boundary markers.

Mining was not taking place during this inspection. Materials stockpiles were located at various locations throughout the pit floor. Phase 1 is almost completely mined out. Overburden and top soil is being stored on the east side of the pit. The active highwall, approximately 20 feet high or less, was located at the northeast side of the pit.

There was no equipment on site.

Topsoil stockpiles are protected with adequate vegetation.

No problems or violations were noted during this inspection.

Responses to this inspection report should be directed to Stephanie Mitchell at the Division of Reclamation, Mining and Safety, Grand Junction Field Office, 101 South 3rd Street, Room 301, Grand Junction, Colorado 81501, phone number (303) 866-3567 ext 8180.

**PHOTOGRAPHS**



















**Inspection Contact Address**

Larry Record  
Delta County  
501 Palmer St Ste 227  
Delta, CO 81416