




MINERALS PROGRAM INSPECTION REPORT
PHONE: (303) 866-3567

The Division of Reclamation, Mining and Safety has conducted an inspection of the mining operation noted below. This report documents observations concerning compliance with the terms of the permit and applicable rules and regulations of the Mined Land Reclamation Board.

MINE NAME: Pig Mesa Pit	MINE/PROSPECTING ID#: M-1978-168	MINERAL: Sand and gravel	COUNTY: Delta
INSPECTION TYPE: Monitoring	INSPECTOR(S): Stephanie Mitchell	INSP. DATE: January 29, 2020	INSP. TIME: 11:30
OPERATOR: Delta County	OPERATOR REPRESENTATIVE: Larry Record	TYPE OF OPERATION: 112c - Construction Regular Operation	
REASON FOR INSPECTION: Memo Of Understanding	BOND CALCULATION TYPE: None	BOND AMOUNT: \$0.00	
DATE OF COMPLAINT: NA	POST INSP. CONTACTS: None	JOINT INSP. AGENCY: None	
WEATHER: Clear	INSPECTOR'S SIGNATURE: 	SIGNATURE DATE: February 7, 2020	

GENERAL INSPECTION TOPICS

This list identifies the environmental and permit parameters inspected and gives a categorical evaluation of each. No problems or possible violations were noted during the inspection. The mine operation was found to be in full compliance with Mineral Rules and Regulations of the Colorado Mined Land Reclamation Board for the Extraction of Construction Materials and/or for Hard Rock, Metal and Designated Mining Operations. Any person engaged in any mining operation shall notify the office of any failure or imminent failure, as soon as reasonably practicable after such person has knowledge of such condition or of any impoundment, embankment, or slope that poses a reasonable potential for danger to any persons or property or to the environment; or any environmental protection facility designed to contain or control chemicals or waste which are acid or toxic-forming, as identified in the permit.

(AR) RECORDS----- <u>Y</u>	(FN) FINANCIAL WARRANTY----- <u>NA</u>	(RD) ROADS----- <u>Y</u>
(HB) HYDROLOGIC BALANCE----- <u>Y</u>	(BG) BACKFILL & GRADING----- <u>Y</u>	(EX) EXPLOSIVES----- <u>NA</u>
(PW) PROCESSING WASTE/TAILING---- <u>N</u>	(SF) PROCESSING FACILITIES----- <u>Y</u>	(TS) TOPSOIL----- <u>Y</u>
(MP) GENL MINE PLAN COMPLIANCE- <u>Y</u>	(FW) FISH & WILDLIFE----- <u>Y</u>	(RV) REVEGETATION---- <u>Y</u>
(SM) SIGNS AND MARKERS----- <u>Y</u>	(SP) STORM WATER MGT PLAN---- <u>N</u>	(RS) RECL PLAN/COMP-- <u>Y</u>
(ES) OVERBURDEN/DEV. WASTE----- <u>N</u>	(SC) EROSION/SEDIMENTATION--- <u>Y</u>	(ST) STIPULATIONS----- <u>N</u>
(AT) ACID OR TOXIC MATERIALS----- <u>N</u>	(OD) OFF-SITE DAMAGE----- <u>N</u>	

Y = Inspected and found in compliance / N = Not inspected / NA = Not applicable to this operation / PB = Problem cited / PV = Possible violation cited

OBSERVATIONS

This was a normal monitoring inspection of the Pig Mesa Pit; DRMS file# M-1978-168. This site is located about 4.5 miles north east of Delta, Colorado in Delta County. I, Stephanie Mitchell of the Colorado Division of Reclamation Mining and Safety conducted the inspection. Mr. Larry Record of Delta County accompanied me on the inspection.

This site is permitted for 331.60 acres with about 29.7 acres currently disturbed. The Division does not hold a financial warranty for the site, for it is a government entity.

Adequate mine identification signage was noted at the entrance off of Fairview Road and is in accordance with Rule 3.1.12(1).

The permit area is delineated by boundary marker posts. Material stockpiles and topsoil/overburden stockpiles appear to be stable. Mining is currently taking place in the Northeast corner of the permit area. The highwall is 25-30 feet high. A loader was the only equipment on site. No fuel is being stored at the mine site.

There were little or no weeds on site.

Overall, no problems were noted on this site. The operation appears to be in compliance with the approved mining plan.

Responses to this inspection report should be directed to Stephanie Mitchell at the Division of Reclamation, Mining and Safety, Grand Junction Field Office, 101 S. 3rd Street, Suite 301, Grand Junction, Colorado, 81501, phone # 303.866.3567 ext 8180

PHOTOGRAPHS









Inspection Contact Address

Larry Record
Delta County
501 Palmer St Ste 227
Delta, CO 81416