



DELTA COUNTY, COLORADO

Office of the County Engineer

Delta County Courthouse
501 Palmer Street, Suite 124
Delta, Colorado 81416-1796

Phone: 970-874-5914 or 874-2035 FAX 970-874-2455

February 14, 2020

Division of Reclamation, Mining and Safety
1313 Sherman St., Room 215
Denver, CO 80203

Re: Annual Report Lemoine Gravel Pit
Permit No.: M-1979-140

Included are:

1. Annual Fee and Report Request;
2. Map – site location
3. Annual fee of \$791.

Included is the site location map of the County's Lemoine Gravel Pit location.

Reclamation activity is in progress.

All gravel has been mined from this pit.

All processed gravel has been removed.


Due to snow and other weather permitting issues, no map is available for this location.

If you have any questions, please contact me.

Regards,

Bob Basher
970.874.5914
OFFICE OF THE COUNTY ENGINEER
DELTA COUNTY

Site Location



112c Annual Report

(DRMS Office Use Only)	Permit Number:	M-1979-140
	Permittee Name:	Delta County
	Operation Name:	Lemoine Gravel Pit
	County:	Delta
	Anniversary Date:	February 16, 2020
	Current Bond Amount:	\$0.00
	Annual Fee Due:	\$791.00
	Permit Acreage:	33.30
	DRMS Specialist:	SJM

According to C.R.S. 34-32.5-116 or 34-32-116, each year, on the anniversary date of the permit, an operator shall submit the Annual Fee, an Annual Report and map showing the extent of current disturbances to affected land, required monitoring information, reclamation accomplished to date and during the preceding year, any new disturbance that is anticipated to occur during the upcoming year, any reclamation that will be performed during the upcoming year, the dates for the beginning of active operations, and the date active operations ceased for the year.

Information contained in this report will be reviewed by the Division upon receipt and prior to the next compliance inspection of the site. If, while completing this report, you learn that your site is not in compliance with the rules and the act, it is advisable that the issues be rectified promptly to avoid possible enforcement action.

1. Is the site identification sign posted in accordance with Rule 3.1.12(1)? YES NO
2. Is the affected area boundary clearly marked in accordance with Rule 3.1.12(2)? YES NO
3. Is the mine site in final reclamation (all material extraction and stockpile removal is complete)? YES NO

If "YES," please note time limits related to completion of reclamation, Rule 3.1.3.

4. What was the date of last excavation, processing or hauling activity at the mine? 9/10/19
5. Does the mine operate more than 180 days per year? YES NO

If "NO," please review Rule 1.13 to assure that your mine is in compliance.

6. Has the mine been granted:
 - a. Approval of TEMPORARY CESSATION Status? YES NO
 - b. Approval for INTERMITTENT OPERATION? YES NO

7. Number of acres currently affected (mining + incomplete and or unreleased reclamation): 35.30
8. Number of acres that were newly affected during the current report year: 0
9. Number of acres that were reclaimed during the current report year: 5.5
10. Estimated new acreage to be affected in the next report year: 0
11. Estimated acres to be reclaimed in the next report year: 0
12. **Total acres** in various stages of reclamation, since permitted mining activities began: 0

Total acres backfilled: 0

Total acres seeded with approved mix: 0

Total acres with topsoil replaced: 5.5

Total acres mulched with approved mulch: 0

Total acres graded: 0

13. Total acres fertilized with approved fertilizer:

0

Topsoil replacement depth (inches):

24"

Mulch application rate (tons):

0

Seed application method:

N/A

Fertilizer application method:

N/A

Mulch application method:

N/A

14. Is weed control being conducted in accordance with an approved Weed Control Plan? YES NO N/A

If "YES," indicate the weed species, control area, control type, application rate and treatment date on the report map.

15. Is adequate topsoil reserved for reclamation, based on your approved permit? YES NO

If "NO," please explain:

16. Is the reserved topsoil vegetated/stabilized in accordance with Rule 3.1.9(1)? YES NO N/A

If "NO," please explain:

17. If mining has exposed groundwater, is the site in compliance with the approved mining plan and Office of the State Engineer (Well Permit, S.W.S.P., and/or Permanent Augmentation Plan)? YES NO N/A

18. Is all hazardous material stored within approved spill containment structures? YES NO N/A

19. Is your financial warranty value sufficient to cover the cost to complete reclamation? YES NO N/A

20. Is your basis for legal right to enter still valid? YES NO

21. Does your permit require you to submit monitoring information annually?

If "YES," please attach the required monitoring results to this Annual Report. YES NO N/A

22. As required by Colorado Mined Land Reclamation Act and/or Colorado Land Reclamation Act for the Extraction of Construction Materials (C.R.S. 34-32-116 or 34-32.5-116), attach a map to this report that accurately depicts the permit boundary, current affected area boundary and location of the acreages specified in items 7 – 12 and 14.

UPDATED MAP ATTACHED:

no