

## Minerals 3600 Mine and Reclamation Inspection U.S. Department of the Interior Bureau of Land Management Royal Gorge Field Office



The BLM has conducted an inspection of your operations, which concludes whether the documented operations on file with BLM are compliant or noncompliant. Any non-compliance issues are reported in the Additional Actions Necessary section of this inspection.

**Operation Type:** Surface – continual Surface – intermittent Underground

Date: Jan 23, 2020	<b>Operation Name:</b> Martin Marietta Materials			
<b>Time:</b> 09:39	Case Number: COC-077898			
Weather: Sunny	CDRMS #: M-1985-043			
Attendees	General			
BLM:S. Carter	<b>Operation(s) are in compliance with documentation on file</b>			
	$\checkmark$ Yes $\Box$ No $\Box$ N/A			
	<b>Operation</b> (s) and disturbance on-site coincide with the			
<b>Operator</b> (s): D. Bieber, W. Stroughton	operations and access on file			
	$\checkmark$ Yes $\Box$ No $\Box$ N/A			
Other(s): State Land Board: Ben Teschner, Lindsay Brandt and				
Stephen Freese				

**Inspection Purpose**:

□ Pre-Operations

✓ General □ Final

□ Trespass □ Complaint

Inspection Items	Compliant	Non- Compliant	N/A		
1. Method of Operations Hardrock Quarry, Pit, Other					
a. Hardrock Quarry					
- •					
Operations Equipment		Ш			
Processing Equipment					
• Blasting 🗆 Internal 🗹 External					
Interim Benches					
Final Benches					
Working Floor					
b. Pit					
			$\checkmark$		
Operations Equipment					
Processing Equipment					
• Slopes					
c. Other			$\checkmark$		
Operations Equipment					
Processing Equipment					
2. Site Conditions					
a. Material/Waste Rock Management					
b. Erosion & Stormwater Control					
c. Man-made Structures			$\checkmark$		
d. Weed Management			$\checkmark$		
e. Safety Hazards					
f. Interim Reclamation			$\mathbf{\mathbf{\mathbf{\mathbf{\mathbf{\mathbf{\mathbf{\mathbf{\mathbf{\mathbf{\mathbf{\mathbf{\mathbf{\mathbf{\mathbf{\mathbf{\mathbf{\mathbf{$		

Inspection Items	Compliant	Non- Compliant	N/A		
3. Housekeeping					
a. Container Management			$\checkmark$		
b. Spills/Leaks Observed			$\checkmark$		
c. Hazardous Substances/POL Management			$\checkmark$		
d. General Housekeeping			$\checkmark$		
4. Access					
a. Road Management			$\checkmark$		
b. Berms			$\checkmark$		
c. Security			$\checkmark$		
d. Signage			$\checkmark$		
e. Surface Water Controls			$\checkmark$		
5. Quality Assurance/Quality Control					
a. Routine Site Conditions Monitoring			$\checkmark$		
b. Air, Water, Noise, Other Monitoring			$\checkmark$		
c. Monitoring Reporting			$\checkmark$		
d. Regulatory Submittals			$\checkmark$		
e. Other Agency/Entity Permits			$\checkmark$		
7. Final Reclamation			$\checkmark$		
a. Exploration/Sampling Location					
b. Access Roads/Trails					
c. Grading					
d. Revegetation					
e. Removal of Structures					
f. Free of Trash					

## Additional Actions Necessary/Information (Non-Compliance Issues to be addressed by Operator in bold)

Focus of inspection: Meet with SLB and look at new design of area with stormwater pond and fines pile.

Section 2b only.

- Spillway ENE of scale house. New pond will be larger than last one, 150' south of original location.
- Pushed up to northern boundary of allowed disturbance. So redoing access roads and floor design just north of the scale house.

Sections 3-7 not addressed during inspection.

**Final Notes** 

**General Comments:** State Land Board 2/12 - Cheyenne Mtn Resort will be the board meeting. Info item on Red Cayon lands and permit boundary. Russ Means and Michael Cunningham will be at the meeting as well. New dev'p needs to be initiated within three years, so the quarry ops don't stagnate. Whether that is SLB to the north or the proposed new area.

Date inspection shared with CDRMS: 3/6/2020

Date inspection shared with Operator: 3/6/2020





