

2020 Annual Report Map

M2011-014 Schmidt Site


Gibbons - NBQ Inc.
f.k.a.
Trust Engineering Company, Inc.

Frank Gibbons, Registered Professional Engineer
Gary Nelson, Registered Professional Engineer

P.O. Box 3178
Durango, CO 81302
Phone (970) 246-1101
Fax (970) 246-1000

Disturbed Ground Illustration of
A portion of Lot 6, Block 5
Aspen Springs Subdivision No. 3
Sections 1 and 12 of T34N, R3W, NMPM
Archuleta County Colorado

Dashed line is
25-ft setback
from property
lines



LEGEND

Retaining Walls in magenta

SURVEYORS STATEMENT:

This survey is subject to any facts that may be disclosed by a title search and abstract.

I hereby state this plat is based on a field survey made by me or under my direct supervision and that to the best of my professional knowledge, information, and belief, it correctly represents the facts found at the time of survey.

NOTICE: According to Colorado law you must commence any legal action based upon any defect in this survey within three years after you first discovered such defect. In no event, may any action be based upon any defect in this survey beyond the period of ten years from the date of the certification herein.

Frank Gibbons 7-10-18
Frank Gibbons, Colo. Reg. J.S. #23498

This boundary was developed to show the relationship of the subject improvements and survey work in relation to the property lines and such other neighboring improvements as may be shown on the plat. The location of the subject improvements and features other than those shown on the plat.

This version prepared by Nathan A. Barton, PE #CD-27342, 11AUG18

M2011-014 Schmidt Site

Found #6 rebar

Found #5 rebar w/aluminum tag
PLS #4679
(original subdividing surveyor)

Found #6 rebar

N90°00'00"W 231.58'

S60°00'00"W 23.56'