



March 23, 2020

Mr. Pat Palmer
Palmer Pipe & Construction, LLC
381 Ute Junction Circle
Durango, CO 81303

Weather Letter

Re: Forkhorn Mesa Subdivision, Permit No. M-2008-044, Request for Financial Release, SL-01, Weather Delay.

Dear Mr. Palmer;

On February 13, 2020, the Division of Reclamation, Mining, and Safety (Division) received your request for a full release of the financial warranty and termination of the above referenced site. The request met the requirements of Construction Materials Rule 4.17 and proper notices were sent pursuant to Construction Materials Rule 4.17.2 (1).

Per Rule 4.17.2(2) the Division shall within thirty days of receiving said report, or as soon thereafter as weather conditions permit, inspect the lands and reclamation to determine if the operator has complied with all applicable requirements. This letter is to inform Palmer Pipe and Construction that current ground conditions and other factors prevent the inspection of the site. Therefore an inspection will be scheduled as soon as weather and ground conditions allow. As soon as an inspection is completed, a decision will be rendered.

If you need additional information, please contact me at the Division of Reclamation, Mining, and Safety, Grand Junction Field Office, by phone at (303) 866-3567 Ext. 8187 or by email at lucas.west@state.co.us.

Sincerely,

Lucas West
Environmental Protection Specialist
Division of Reclamation, Mining and Safety

Cc: Travis Marshall, Senior Environmental Protection Specialist

Ec: Pat Palmer, Palmer Pipe & Construction

