




MINERALS PROGRAM INSPECTION REPORT
PHONE: (303) 866-3567

The Division of Reclamation, Mining and Safety has conducted an inspection of the mining operation noted below. This report documents observations concerning compliance with the terms of the permit and applicable rules and regulations of the Mined Land Reclamation Board.

MINE NAME: North River Gravel Pit Extension	MINE/PROSPECTING ID#: M-1999-007	MINERAL: Gravel	COUNTY: Rio Blanco
INSPECTION TYPE: Aerial Inspection	INSPECTOR(S): Dustin Czaplá	INSP. DATE: March 16, 2020	INSP. TIME: 12:00
OPERATOR: George T. Weldon Construction, LLC	OPERATOR REPRESENTATIVE:	TYPE OF OPERATION: 112c - Construction Regular Operation	
REASON FOR INSPECTION: Preoperation Inspection	BOND CALCULATION TYPE:	BOND AMOUNT: \$25,900.00	
DATE OF COMPLAINT: NA	POST INSP. CONTACTS: None	JOINT INSP. AGENCY: None	
WEATHER: Clear	INSPECTOR'S SIGNATURE: 	SIGNATURE DATE: March 24, 2020	

GENERAL INSPECTION TOPICS

This list identifies the environmental and permit parameters inspected and gives a categorical evaluation of each. No problems or possible violations were noted during the inspection. The mine operation was found to be in full compliance with Mineral Rules and Regulations of the Colorado Mined Land Reclamation Board for the Extraction of Construction Materials and/or for Hard Rock, Metal and Designated Mining Operations. Any person engaged in any mining operation shall notify the office of any failure or imminent failure, as soon as reasonably practicable after such person has knowledge of such condition or of any impoundment, embankment, or slope that poses a reasonable potential for danger to any persons or property or to the environment; or any environmental protection facility designed to contain or control chemicals or waste which are acid or toxic-forming, as identified in the permit.

(AR) RECORDS----- <u>N</u>	(FN) FINANCIAL WARRANTY----- <u>N</u>	(RD) ROADS----- <u>N</u>
(HB) HYDROLOGIC BALANCE----- <u>N</u>	(BG) BACKFILL & GRADING----- <u>N</u>	(EX) EXPLOSIVES----- <u>N</u>
(PW) PROCESSING WASTE/TAILING---- <u>N</u>	(SF) PROCESSING FACILITIES----- <u>N</u>	(TS) TOPSOIL----- <u>N</u>
(MP) GENL MINE PLAN COMPLIANCE- <u>Y</u>	(FW) FISH & WILDLIFE----- <u>N</u>	(RV) REVEGETATION---- <u>N</u>
(SM) SIGNS AND MARKERS----- <u>N</u>	(SP) STORM WATER MGT PLAN---- <u>N</u>	(RS) RECL PLAN/COMP-- <u>N</u>
(ES) OVERBURDEN/DEV. WASTE----- <u>N</u>	(SC) EROSION/SEDIMENTATION--- <u>N</u>	(ST) STIPULATIONS----- <u>N</u>
(AT) ACID OR TOXIC MATERIALS----- <u>N</u>	(OD) OFF-SITE DAMAGE----- <u>N</u>	

Y = Inspected and found in compliance / N = Not inspected / NA = Not applicable to this operation / PB = Problem cited / PV = Possible violation cited

OBSERVATIONS

This aerial inspection was conducted as part of the review process for the 112c conversion application (CN-1) that was submitted to the Division of Reclamation, Mining and Safety's (Division) on October 4, 2019. Pursuant to Rule 3.2 (7), 110c operations applying for 112c conversion shall be inspected after the application is filed and prior to Board consideration.

The North River Gravel Pit is located approximately two miles northeast of Rangely, on the north side of the White River. The site is a 110c operation that includes a total of 9.99 permitted acres. CN-1 proposes increasing the affected area to 18.75 acres, in order to incorporate all of the currently disturbed land into the permit area. As stated, much of the proposed permit area has been previously disturbed by mining operations. The affected area consists of various construction material stockpiles and excavation areas. Conditions observed during the inspection are consistent with those represented in the CN-1 application. No problems or violations were noted during this inspection.

Responses to this inspection report should be directed to Dustin Czapla at the Division of Reclamation, Mining and Safety, 1313 Sherman Street Room 215, Denver, Colorado, 80203, phone number (303) 866-3567, ext. 8188.

PHOTOGRAPHS



Inspection Contact Address

Mike Weldon
George T. Weldon Construction, LLC
P.O. Box 1170
Vernal, UT 84078