



Red + is production site

Black + This area has been all sloped
to 3 to 1 or less and most has been
topsoiled

Black # - is area sloped - topsoiled and seeded

April 17, 2020

Mine Site was inspected in January of 2020 by Daniel Cunningham, Environmental Protection Specialist and the pit was found to be compliance.

Frank Leone Jr