


Note: 1) Contours shown at 5' intervals | Google 2016 Satellite Imagery



- TOTAL ACRES CURRENTLY AFFECTED: 8.15±
- MINING ACRES NEWLY AFFECTED: 0.30±
- NUMBER OF ACRES RECLAIMED: 0.00±
- APPROXIMATED NEW ACRES TO BE AFFECTED IN THE NEXT YEAR REPORT: 0.20±
- APPROXIMATED NEW ACRES TO BE RECLAIMED IN THE NEXT YEAR REPORT: 0.00±

DRAWING LEGEND

- Permit Boundary
- Section Line
- Edge of gravel roadway
- Fence line
- Edge of field
- Pin set by PLS 148-H0
- Pin as described



SUMMIT ENGINEERING CO.
ENGINEERS & LAND SURVEYORS
P: 719-589-6147 F: 719-589-6633
Loc: 1317 State Ave, Alamosa, CO 81101
Mail: P.O. Box 1397 Alamosa, CO 81101
www.summitengineering.co
summitengco@gmail.com

PROJECT

Robins Rock Pit (M-2007-079) 2019 Annual Map
A portion of the NW1/4 Section 15, T.33N., R.8E., N.M.P.M., Conejos County
Owner: Robins Construction, L.L.P.

SHEET NAME
Annual Map

C-101
SHEET NO. 1 OF 1

Job: 4861 Print Draft: A Date: 03-21-2019
Designed By: N/A Drawn By: KFA Checked By: SEJ