

5 May 2020

Mr. Graham Roberts  
Environmental Engineer  
Trapper Mining Inc.  
P.O. Box 187  
Craig, CO 81626

**Re: Trapper Permit N. C1981 010**  
**DRMS Review of Technical Revision 125, 2019 Annual Reclamation Report**

Dear: Mr. Roberts

The Division has verified the topography proposed in the 2019 Annual Reclamation Report (2019 ARR). The methodology employed utilized the currently approved Post Mining Topography Map, Map M12 sheet 3 of 3 to compare the topography of the proposed 2019 ARR Map, M1 sheet 3 of 3. ArcGIS v.10.4 software was utilized to georeference and overlay the two maps, allowing for the detection of variations in topography proposed and approved.

The Division detected no significant topographic differences between the two maps. The on the ground conditions will be verified at a later date by The Division. There are no adequacy concerns and The Division is prepared to propose a decision on this permitting action.

I'm available to discuss should you have any questions.

Sincerely

**Robin Reilley, M.S. GISP**  
**Environmental Protection Specialist II**

P [303.866.3567](tel:303.866.3567) ext 8105 Cell [303.906.3886](tel:303.906.3886)  
F [303.832.8106](tel:303.832.8106)  
1313 Sherman Street St., Suite 215, Denver, CO 80203  
[robin.reilley@state.co.us](mailto:robin.reilley@state.co.us) <http://mining.state.co.us>

