



COLORADO
Division of Reclamation,
Mining and Safety
Department of Natural Resources

June 4, 2020

Bennie & Shawnee Koch
Rocky Mountain Excavating, LLC
2976 L Path
Cotopaxi, CO 81223

**RE: Iron Mountain Road Gravel Pit, Permit No. M-1994-092;
July 2019 Inspection Corrective Action Resolved**

Dear Mr. & Mrs. Koch,

On June 2, 2020, the Division received via email photographic documentation of completed backfill in your pit, mitigating the exposed groundwater, thereby addressing the cited problem in the inspection report dated October 29, 2019.

The Division considers the corrective action resolved.

If you have any questions or need further information, please contact me at (303)866-3567 x8169.

Sincerely,

Timothy A. Cazier, P.E.
Environmental Protection Specialist

ec: DRMS file
Shawnee Koch, Rocky Mountain Excavating

