



March 19<sup>th</sup> 2020

Rob Zuber  
Division of Reclamation, Mining & Safety  
Department of Natural Resources  
1313 Sherman Street, Room 215  
Denver, Colorado 80203

Re: Quarterly Pond Inspection  
Keenesburg Mine, Permit C-1981-028

Dear Rob Zuber:

Attached is a copy of the Quarterly Pond Inspection report for the first Quarter of 2020. Coors Energy Company has prepared and is submitting this copy in compliance with revised Division Regulation 4.05.9(17). The original of this report has been placed in the inspection reference volume at the site.

Should there be questions about the report, or a need for additional information, please contact me at (303 944-8166).

Sincerely,  
*Danny Kipp*

Danny Kipp  
Chief Reclamation Specialist

Enclosure

# ANNUAL & QUARTERLY POND INSPECTION

## COORS ENERGY COMPANY

### KEENESBURG MINE SITE

Date of Inspection	3-19-2020		
Pond Identification:	Sediment Pond #2	Dugout	
Type of Pond	Sediment	Permanent	
Capacities	15.6 acre ft. 5097,925 gals.	19.7 acre ft. 6,437,760 gals.	
Approx. water level - (% of capacity)	Trace	Trace	
Sediment level - (% of capacity)	0	0	
Out flow			
Erosional Features	yes - no	yes - no	
Rills / Gullies	NO	NO	
Inadequate Vegetation	NO	NO	
Outlet Channel Erosion	NO	NO	
Burrows	NO	NO	
Other			
Structural Issues			
Settlement	NO	NO	
Cracks/Slides	NO	NO	
Seepage			
Spillways (cond.)	Good	Good	
Other			

Signature (P.E. or Authorized Inspector):

Danny New