

Cripple Creek & Victor Gold Mining Company
Squaw Gulch Valley Leach Facility
Phase 2A Part 3 Record of Construction
Geomembrane Extrusion Welding Destructive Testing Summary



Sample Number	Seam Number	Date Seamed	Welding Data		Date Tested	Test Results										QA Monitor	Remarks
			Operator	Machine Number		Peel Strength ¹ (Minimum = 100 ppi)					Shear Strength ¹ (Minimum = 120 ppi)					Pass/Fail	
DX-191	P-2680/P-3193	05/29/20	WL	44	06/01/20	135	132	136	119	105	165	160	167	161	160	Pass	JS
						-	-	-	-	-							
DX-192	P-1846/P-3198	06/02/20	WL	44	06/08/20	140	114	147	140	144	168	165	163	165	175	Pass	SA
						-	-	-	-	-							
DX-193	P-1859/P-3213	06/08/20	WL	44	06/10/20	162	154	176	161	144	186	209	191	162	151	Pass	RM
						-	-	-	-	-							
DX-194	P-3199/P-3205	06/08/20	AA	21	06/10/20	159	108	122	142	161	173	191	177	197	185	Pass	RM
						-	-	-	-	-							
DX-195	P-3199/P-3205	06/10/20	AA	21	06/10/20	135	122	125	132	115	139	139	151	153	142	Pass	RM
						-	-	-	-	-							
DX-196	P-3199/P-3205	06/10/20	WL	44	06/10/20	130	135	118	121	117	147	160	145	155	143	Pass	RM
						-	-	-	-	-							
DX-197	P-2031/P-3218	06/10/20	AA	21	06/11/20	167	112	167	172	150	161	182	166	193	166	Pass	RM
						-	-	-	-	-							
DX-198	P-2037/P-3228	06/10/20	WL	44	06/11/20	118	136	152	121	162	158	168	155	161	169	Pass	RM
						-	-	-	-	-							
DX-199	P-2034/P-3225	06/11/20	AA	44	06/12/20	164	173	118	162	160	169	170	165	169	168	Pass	RH
						-	-	-	-	-							
DX-200	P-2036/P-3227	06/12/20	AA	47	06/12/20	146	137	144	137	142	139	147	138	146	139	Pass	RH
						-	-	-	-	-							
DX-201	P-2056/P-3252	06/12/20	WL	44	06/13/20	146	138	139	128	113	155	136	149	133	150	Pass	TT
						-	-	-	-	-							
DX-202	P-3257/D-8819	06/12/20	NP	44	06/13/20	141	138	125	131	136	146	151	142	146	134	Pass	TT
						-	-	-	-	-							
DX-203	P-3249/D-8813	06/12/20	AA	21	06/13/20	141	133	135	138	141	145	150	151	144	150	Pass	TT
						-	-	-	-	-							
DX-204	P-3241/P-2047	06/12/20	WL	44	06/13/20	147	113	123	123	116	150	146	155	151	156	Pass	TT
						-	-	-	-	-							