

PLATTE S&H
Annual Report Supplemental
Year 2020

16. The new topsoil pile created in 2020 will be stabilized once area inside north slurry wall is fully stripped.
17. North slurry wall installation is complete. Working with SEO on required leak test.